UNCLASSIFIED

	AD NUMBER
	AD390750
(CLASSIFICATION CHANGES
TO:	unclassified
FROM:	confidential
	LIMITATION CHANGES
TO: Approved unlimite	for public release, distribution
FROM:	
ł	AUTHORITY 80 per group-4 document markings; General's Office, D/A ltr 29 Apr



DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310



IN REPLY REFER TO

AGAM-P (M) (23 May 68) FOR OT RD 681156

3 June 1968

SUBJECT: Operational Report - Lessons Learned, Headquarters, 52d Combat Aviation Battalion, Period Ending 31 January 1968 (U)

*This document contains information affecting the National Defense of the United States within the meaning of the SEE DISTRIBUTION Espiology Laws, Title, Th. U. S. C., Section 795 and 794. Its transmission or the revolution of its contents in any manner to an unauthorized person is prohibited by law."

- 1. Subject report is forwarded for review and evaluation in accordance with paragraph 5b, AR 525-15. Evaluations and corrective actions should be reported to ACSFOR OT RD, Operational Reports Branch, within 90 days of receipt of covering letter.
- 2. Information contained in this report is provided to insure appropriate benefits in the future from lessons learned during current operations and may be adapted for use in developing training material.

BY ORDER OF THE SECRETARY OF THE ARMY:

l Incl

KENNETH G. WICKHAM Major General, USA The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Adjutant General School

US Army Air Defense School

US Army Armor School

US Army Artillery and Missile School

US Army Aviation School

US Army Chemical School

US Army Civil Affairs School

US Army Engineer School

US Army Infantry School

US Army Intelligence School

Regraded unclassified when separated

from classified inclosure.

CONFIDENTIAL

FILE COPY

JUN 27 1968

DISTRIBUTION (Cont'd)

US Army Medical Field Service School

US Army Military Police School

US Army Missile and Munitions School

US Army Ordnance School

US Army Quartermaster School

US Army Security Agency School

US Army Signal School

US Army Southeastern Signal School

US Army Special Warfare School

US Army Transportation School

Copies furnished:

Office, Chief of Staff, US Army

Deputy Chiefs of Staff

Chief of Engineers

Chief of Research and Development

Assistant Chiefs of Staff

The Surgeon General

The Provost Marshal General

Research Analysis Corporation (Library)

OSD(SA), Assistant For Southeast Asia Forces

Defense Documentation Center

Planning Research Corporation

Director, Weapons Systems Evaluation Group

USAF Air Ground Operations School

Commanding Generals

US Army Materiel Command

US Army Weapons Command

US Army Flight Training Center

Commanding Officers

US Army Limited War Laboratory

US Army Aviation Test Activity

3d Battalion, 197th Artillery

2d Battalion, 138th Artillery

1st Squadron, 18th Air Cavalry (Sep)

52d Combat Aviation Battalion

ACCESSI	ON for		
GFSTI	¥	VILITE SECT	ורי אפו
ouc		BUFF SECT	
UKA ROU	NCCO		
JUSTIFICA	TION		<u> </u>
			- 1
Y Distribu Dist.		ILABILITY and/or SP	
_		and of 25	EGIAL
\mathcal{A}			-
\mathcal{I})	- 1	

2

CONFIDENTIAL DEPARTMENT OF THE ARMY , HEADQUARTERS, 52D COMBAT AVIATION BATTALION APO San Francisco 96318 FLYING DRACONS AVGD-CC 6 Fobra Operational Report. For Marterly Period Ending 31 January ACSFOR TO: See Distribution 7-RD-681156 SECTION I - Significant Organizational Activities (C) General: This report covers the period 1 November 1967 through 31 January 1968, and is submitted in compliance with Headquarters I Field Force Vietnam Regulation 1-3, dated 23 March 1967, and Headquarters 17th Combat Aviation Group Regulation 1-3, dated 12 July 1967. a. Mission: The mission of the 52d Combat Aviation Battalion (Flying Dragons) is to provide aviation support to US Forces, Republic of Vietnam Forces and Free Wopld Assistance Forces in the II Corps area, with priority to the Ath Infaptry Division. b. Station Plan: 9The 52d Combat Aviation Battalion is stationed at Camp Holloway, Pleiku, RVN. and is commanded by LTC Edward P. Lukert Jr. Subordinate elements consist of the following units: (Detailed list of detachments is shown in inclosure \(\) (1) Headquarters and Headquarters Detachment - Pleiku, RVW (2) 57th Assualt Helicopter Company - Fontum, RVV. Equipped with WH-1H and WH-1C(A) helicopters. (3) 119th Assault Helicopter Company - Pleiku, RVV. Equipped with WH-1H and WH-1C(A) helicopters. (4) 155th Assault Helicopter Company - Ben Me Thuot, RVN. Equipped with WH-1W and WH-1C(A) heliconters. (5) 170th Assault Helicopter Company - Pleiku, RVM. Equipped with VH-1H and VH-1C(A) heliconters. (6) 189th Assault Helicopter Company - Pleiku, RVN. Equipped with WH-1H and WH-1C(A) helicopters. (7) 179th Assault Support Helicopter Company - Pleiku, RVN. Equipped with CH-47A helicopters. (8) 355th Assault Support Helicopter Company (Feavy) -Pleiku, RVN. Equipped with CH-54 helicopters. Type aircraft authorized and on hand as of 31 January 1968: DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. FOROTRD

681156

DOD DIR 5200.10

CONFIDENTIAL

		ATTOPLIZED	ON HAND
(1)	ΠH-1C(Λ) -	40	32
(2)	17H-1C -	2	0
(3)	₩ <u>-1</u> H -	115	92
(4)	СН-471 -	16	13
(5)	CH-54 -	9	3
(6)	17-6A -	7	1
	TOTAL.	183	141

(For a more detailed account, see inclosure 2.)

- 2. (C) Intelligence: The battalion S-2 Section published a Daily INTSUM in November and December. Starting 1 January the INTSUM was deleted and a numbered Intelligence Bulletin was published with distribution to Battalion units and selected Holloway Tenant Units. (See section II para 2)
- a. Whemy Activity: The enemy activity in the Central Highlands was extremely heavy during the reporting period. Activity during the early part of the period was heaviest in the Dak To area but shifted south to the Pleiku area towards the latter part of the period. The Pattalion suffered losses both to personnel and equipment as a result of attacks on its installations at Ban No Thuot, Kontum, and Camp Wolloway. Intelligence estimates of the attack on Kontum on 10 January 1968, and Camp Volloway on 26 January 1968 are included in the after action reports attached as Inclosures 7 and 8. The first two attacks on Pan Ne Thuot were both conducted by the 301st Local Force Battalion. The first attack, on 7 November 1967, was initiated at 2340 hours and lasted for 10 minutes. From forty to fifty rounds of 82mm impacted within the 155 Maintenance area, resulting in 2 ships destroyed and ? damaged. There were no casualties. The second attack on 4 January 1968, was initiated at 0320 and consisted of 20 to 25 rounds of 60mm and 82mm, satchel charges and B-40 rockets. armin was the 155 Maintenance area and there were 2 ships destroyed and 11 damaged, 1 fire truck destroyed, 1 fire truck damaged, Maintenance area destroyed and 2 jeeps damaged. There were no casualties. The last two days of the period saw the beginning of an all out offort by the enemy to either keep us tied down in place or to take and hold one of the Province Capital cities. Of particular interest to this battalion were the hits taken by Kontum, Ban No Thuot, and Ploiku. All three installations were under attack on these two days. Heavy activity continued into the next period and comphrehensive anlysis is not yet possible.
- (1) In addition to the hits on 52d Aviation Rattalion Installations, other significant items were; the Battle of Dak To (See incl 6) the rocket attacks of II Corps Hqs, Arty Mill, 71st Evac and 433 Sig on 20 Jan 68 and again on 27 Jan 68, the Sappor attack on 937th Eng Bn Compound on 21 Jan 68 and the ground attack against the city of Pleiku on 30, 31 Jan 68.

(2) Situation:

(a) Kontum: The 24th MVA Regiment is located, with

CONFIDENTIAL

elements of the 174th NVA Regiment in the Toumorong Base area, north east of Dak To. The 66th NVA Regiment and possible elements of the 174th NVA Regiment are occupying positions west and north west of Dak To. The 40th NVA Arty Regiment is currently unlocated in the tri-border area. The 304th Local Forces Battalion is located approximately 15 Km northeast of Kontum city. Unlocated, but last reported headed for a target in the Kontum area is the 408th Sapper Battalion. As of the close of the period, the 24th NVA Regiment is reported massing north of Kontum City.

- (b) Pleiku: The 4th Battalion, 95B Regiment and elements of the 5th Battalion are located approximately 25 FM NE of Pleiku City. Elements of the 5th Battalion are also located in an area approximately 15 Km East and South East of Pleiku City. The K101 Battalion, 95B Regiment is unlocated, last believed in an area approximately 25 Km West of Pleiku City. The K-6 and possible the K-4 Battalions (of the 32 NVA Regt) last contacted at Dak To, have moved south through the Plei-Trap Valley and are believed located in an area approximately 15-20 Kms WTM of Pleiku City. The 200th Arty Bn. an element of the 40th Arty Regiment, was believed located in the same general area. The H-15 Local Force Battalion, last seen in the in Khe area, is believed heading to the Pleiku area. The 407th Sapper En is currently unlocated in Pleiku Province. The X-17 and X-18 Sapper companies are currently unlocated.
- (c) Darlac: Elements of the 33d NV\ Regiment are currently operating both south and north (40 KM) of Ban Me Thuot. The 301st Local Force Battalion is unlocated.

(3) Capabilities:

- (a) Kontum: To attack in the Dak To area with up to 6 NVA Infantry Battalions supported by heavy mortar and rockets from the 40th Arty Regiment. To attack Kontum City with up to 3 regular Battalions of the 24th NVA Regiment and 1 Sappor Battalion, the 408th. Continued interdiction of highway14U utilizing possible elements of the 24th NVA Regiment and the 304th Local Force Battalion.
- (b) Pleiku: To attack Pleiku City with up to 5 NVA Battalions, 4th and 5th of the 95B and possibly, K4 and K6 of the 32d Rogt, supported by artillery elements of the 40th Arty Regiment, 1 Sappor Bn plus local units and guerrillas from VC districts 3, 4, and 9. Is an alternate course, using elements of both MVA Regiments, conduct multi-Bn attack against Duc Co, Plei Vorong, or Plei Dierang. Continuous interdiction of highways 19E and 14N using elements of the VC 3d district and the 40th Sapper and M-15 Local Force Battalions.
- (c) Darlac: Conduct a multi-En attack on Ban Me Thuot using elements of the 33d NVA Regiment, with local harassment and interdiction of highways by the 301st Local Force Battalion.
 - b. Ground to air fire was reported on 88 occasions resulting in

62 aircraft hit, 3 crew members killed and 25 crew members wounded in action. Of the aircraft hit 29 were UH-1H's and 32 were UH-1C's and 1 was a CH-47. Altitudes of aircraft receiving hits varied from 25 feet to 4,000 feet. Specifically 26 received hits below 500 feet, 17 received hits between 500 and 1000 feet, 14 between 1000 and 2000 feet, and 5 above 2000 feet.

- c. The Intelligence Section of the 155th Asit Wel Co continues to have the responsibility of gathering intelligence information on the Ban Me Thuot area and receiving reports from local civilian agencies and military organizations in the Ban Me Thuot area.
- d. The Intelligence Section of the 57th Aslt Wel Co in Montum has effected direct liaison with the S-2 advisory elements of Kontum Sector Headquarters.
- e. Intelligence briefings and indoctrinations were given to the newest member of the Battalion, the 355th Heavy Helicopter Company, stationed at Comp Holloway. A basic load of maps was provided the Company.
 - 3. (C) Operations and Training Activities
 - a. Operations:
- (1) Support: The 52d Combat Aviation Battalion(Flying Dragons) supported numerous operations including Mac Arthur (92 days), Tran Son I (7 days), Michael (10 days), Co "E", 20th Inf (62 days), FCR-II (92 days), IRVN (92 days), CRID (4 days), Press Camp (66 days). In addition eviation support was provided II Corps Fqs (92 days), Co "R", 5th SFG (91 days), 52d Arty Gp (91 days) and 17th Aviation Troup (78 days). In general during the reported period, the "Flying Dragons" supported II Corps with one Assault Felicopter Company and one Assault Felicopter Company minus. The 4th Infantry Division was supported with two Assault Felicopter Company. The percentage of the battalions lift capability allocated, by month, was as follows:

	NON	DEC	IVM
4th Inf Div -	66% 12%	65% 13%	63¢ 13 %
Other -	22%	22%	24%

(For detailed sequence of significant events and statistics, see inclosure 4; for a map of the operational area, see inclosure 5.)

(2) Operational Statistics (1 Nov - 31 Jan 68)

CBT	OTHER	UH-1H	UH_1C	CH-47A
SORTIES	SORTIES	HOURS*	HOURS*	HOURS*
85,319	43,228	29,391	7,527	3,597
TOTAL	PAX	CARGO	A/C	A/C**
HOURS*		TONS	HIT	DAM/DEST
40,515	175,270	21,380	62	129/22
CREY MEM	ENEMY	STRUCT	MED	SORTIES DELAY
	KBA	DEST	EVACS	OR CXL FOR WX
37/6	217	167	1,506	62

- * Adjusted DA Form 1352 time.
- ** Includes results of hostile fire and accidents.
- (3) UH-1H and UH-1C(A) Support: During Movember, the increased demand for UH-1 aircraft, brought on by the Battle of Dak To, had a lasting effect of this battalions availability for the remainder of the reporting period. Demands made it necessary to reinforce this battalion with elements of severalunits within the 17th Combat Aviation Group. This support extended anywhere from a day to in excess of one week. (For a more detailed analysis of this problem area; see Section II, Part I)
- (4) 355th Assault Helicopter Company (Heavy) arrival: The main body of the 355th Assault Helicopter Company (Heavy) deployed to Vietnam beginning 10 January 1968, and completed the move on 12 January. The company (-) was assigned to the 52d Combet Aviation Battalion at Camp Holloway, Pleiku, RVN. The TOME equipment began arriving on 24 January 1968. A small delegation from the company was sent to the Nhon to organize the shipment of aircraft and equipment to Pleiku, RVN. The remainder of the company worked to complete facilities prior to the arrival of their equipment.
- (5) CH-47A Support: During this reporting period the demand for CH-47A support in the Central Highlands continued at a phenomenal rate. Again, it was necessary to reinforce the 179th ASEC with aircraft from other units within the 17th Combat Aviation Group, for short periods.
- (6) 335th Aslt Fel Co: In mid-November the 335th returned to the Central Highlands and Ploiku area in support of the 173d Abn Bdo. Although OPCON to the 173d, the 335th was attached for administration and logistics to the 52d Cbt Avn Bn. The statistics reflected in this report do not include these of the 335th Aslt Hol Co.

- (8) Weather: During the month of November, the weather was charactorized by high coilings, moderate winds and good visibility. Winds were prodominately out of the NAME during this period. In late December, the winds began shifting to the ENE bringing cooler temperatures and excellent flying conditions for the remainder of the reporting period. (For more detailed meteorological data, see inclosure 4)
- (9) Enomy Attacks: In the past quarter all units of this battalion have been attacked. Both NVA and VC units conducted attacks on Kontum, Ban Mo Thuot, and Holloway sirficlds. The enemy used 82mm mortars, 122 & 140mm rockets, sappers and Infantry assaults during his compaigns. (For detailed information on each attack see inclosure 7, 8, and 9.)

Training:

(1) During the reported period, the following subjects were stressed:

(a) Aviation Training:

- Pre-flight Inspections
- Rules of Engagement
- Instrument Training
- Formation Flying
- Escape and Evasion
- Monsoon Weather Procedures
- Cam Ranh, Wha Trang and Saigon control zone Procedures
- Amergency Procedures

(b) Ground Training:

- Code of Conduct

- Immediate Action Drills
- 1. Code of Conduct
 2. Rules of Engagement
 3. Ceneva Convention
 4. Gas Chamber Exercises
 5. Viet Cong Tactics
 6. Immediate Action Drill
 7. Fines and Booby Traps
 8. Security and Sentry Dr
 9. Meapons Safety
 10. Familiarization and sentry Security and Sentry Duty
- Familiarization and zero firing of individual weapons

- (2) Portions of the ground training program have been eliminated during this reporting period. This was primarily due to higher Headquarters assuming responsibility for the initial in-country training.
- (3) Instructor Pilots from the 355th ASHC(H) were sent to the 478th ASVC(H), located at An Khe, for training with that unit. This training included ground, flight, and operational procedures peculiar to these units.
- c. Research and Development: During the reporting period, the 52d Combat Aviation Battalion took part in a minimum number of evaluations and no significant advances were made.

4. (C) Logistics

- a. Class I: No significant problems.
- b. Class II: Command emphasis placed on control and turn in of excess equipment and conex containers throughout the period.
 - c. Class III & IIIA:
- (1) Over 4,000,000 gallons of JP4 used by the battalion during the period.
- (2) Holloway miniport relocated on the new heliport to vacate previous location for the 355th Assault Support Helicopter Company (Heavy). The 350 GPM POL pump provides adequate pumping pressure over a lateral distance of 800 feet.
- (3) Approval was received from 1st Log Command to retain the 3-3000 borrel POL storage tanks at Molloway should the Class III storage facility be moved.
- d. Class IV: No significant problems. Command emphasis placed on class five accountability and storage facilities during the period.

5. (W) Civil Affairs

a. The Battalion Civic Action Officer, the Battalion Chaplain and volunteers from subordinate units are now engaged in civic action activities in five Montagnard villages in the battalion area of operations. The battalion continues to receive many boxes of soap, vitamins and clothing from friends in the US. As new personnel arrive, so do new sources of donations. These items are being distributed through village chiefs, the Pleiku Province Pospital, the Evangelical Mospital, and the Christian and Missionary Alliance. The battalion conducts medical assistance clinics with emphasis on hygiene; eg, washing and treating skin disorders. The Battalion Civic Action Fund continues to receive donations from organizations interested in the program. (For a pictorial account of Civic Action similar to that of the 52d, see inclosure 3.)

- b. Emphasis in the Civic Action Program is being placed on establishing channels of communications between GVN and the Montagnard Chiefs. The Montagnards definitely prefer to work directly with the Americans, although resistance to the idea is present on both sides.
 - c. Specifically, the Chaplain contributed:
- (1) Over 20 boxes of sheets, clothing, soap and drug items were received from churches and individuals in the States. These were distributed for use by the CMA missioneries and the VNCS Clinic Hospital.
- (2) Two sewing machines found in the Special Services storage building were given to the Pleiku Mentagnard Farm and School.
- (3) Approximately 300 cases of surplus food from units at Camp Holloway and the PX warehouse were distributed to the Montagnard tribes through the CMA missioneries.
- (4) The Protestant congregation received special offerings for the following causes:
- (a) \$668.95 to Jerai Church for construction of library and reading room.
 - (b) \$50.75 to the Bible Societies of Vietnam.
- (c) \$80.00 to the CMA missionaries at Ban Me Thuot for the Montagnard Church under construction.
- (5) The Catholic congregation received \$128.53 in offerings for Catholic missionary activities in the area.
 - 6. (C) Personnel
 - a. PIO activities during the period November 1967 January 1968.
 - (1) Feature stories submitted: 8
 - (2) Pictorial releases (homotown and in-country): 30
 - (3) Tapod interviews: 23
 - (4) Formal press interviews: 4
 - (5) Newsmen and representatives sur wited: 48
- (6) The "Dragon Fire" was revived a d increased in size and scope during this period. It provides local new, of interest and selected news service items.

g

CONFIDENTIAL

- (7) The nightly report of daily aviation activities has greatly improved during the period. Unit PIO's are beginning to submit better reports, thereby enabling the Battalion PIO to submit more effective reports.
- b. Special Services activities for the period November 1967 January 1968.
- (1) During the period, a total of 506 out of country R&R quotas were received; of these, 396 were filled.
- (2) A total of 6 in-country R&R quotas were received, 3 for EM and 3 for officer. This is a notable decrease from the last reporting period.
- (3) The arts & crafts shop as well as the library have expanded to a seven day a week operation.
 - c. Awards and Decorations:
- (1) Total number of awards and decorations submitted during this period are as follows:

MARD	NUTBER SUB	APPROVED
Silver Star	22 47	, n 19
'Soldiers Medal	6	3
Bronzo Star Air Modals	36 .1487	28 2035
AOM	37	34
Furple Heart TOTAL	14 1649	2127 2127

- d. Personnel problems during the period November 1967 January 1968.
- (1) The problems of receiving replacements in our critical MOS areas still exists. Most critical during the period were helicopter Tech Inspectors (MOS 674), Aircraft Armament Repairmen (MOS 45J), Petroleum Storage Specialists (MOS 764) and Cooks (MOS 94B). The shortage of personnel in MOS iiB continues to be a matter of grave concern.
 - o. Command Changes:

The following new commanders assumed command on dates indicated:

COMMANDER	קידורוז	DATE
Maj Billy R. Goodall Maj Eugene P. Malkoff Maj Joseph R. Campbell III Maj George E. Burnison Maj Neil I. Leva *Maj Glenn E. Vorgan *Maj William H. Winds	155th MPO 165th TO Dot 119th APO 57th APO 189th APO 355th ASHO 622nd TO Dot	6 Nov 67 6 Nov 67 20 Mov 67 1 Duc 67 2 Jan 68

NOTE: Does not indicate date individuals assumed command of respective units, only when they reported in-country as elements of this command.

f. Gain and Losses

(1) The following gains and lesses occured during the period November 1967 - January 1968:

(a)	<u>GAINS</u>	नुष्य <u>्</u>	<u> Pa</u> 4
	November	118	212
	December	36	140
	January	42 .	114
(ð)	Losses	OFF	EM
	Movember	83	282
	Pecomber	26	150
	Taluary	28	164

- (2) At present the battalien is $\underline{298}$ FM and $\underline{49}$ officers and warrant officer, below TOSE strongth.
- g. Morale: The morale of officer and enlisted personnel throughout the battalien continues to be exceptionally high. This was due primerily to the following:
- (1) Maximum recognition for job accomplishment through promotions, awards and decorations and letters of appreciation.
 - (2) Liberal leave and R&R policies.
 - (3) Continually improving standards of living.
 - (4) Avialability of post facilities.
- (5) Continual indoctrination in job performance and mission orientation.

h. Religious Activities:

- (1) During the quarter the Battalion Chaplain was responsible for all religious activities at Camp Holloway and at the operational sites. Protestant services were conducted by the Battalion Chaplain.
- (2) Religious services were provided for the 155th ivn Co in Ban Me Thuot on a weekly basis by the Protestant missionaries and the Catholic Chaplain from MACV.
- (3) Religious services for the 57th Avn Co in Kontum were provided by the Protestant Chaplain and the ARVN Catholic Chaplain.
- (4) Catholic services for Camp Holloway were conducted each Sunday by the PSAC Chaplain.
- (5) Transportation was provided from Camp Holloway to the 71st Evac Hospital Chapel each Friday for Jewish personnel.
- (6) The Protestant congregation continues to attend the hymn sings at the CMA compound each Sunday. One cook out was held jointly with the CMA missionaries in January.
- (7) In November, a bus tour was taken of all the missionary institutions of the Pleiku area.
- (8) At Christmas time, several packages were received from individuals and churches for distribution to men of the units.
- (9) In January, a regular pianist/organist was secured for the Chapel, and a choir was started.
- (10) During the quarter new light fixtures were installed inside the Chapel, catalog speakers were erected to play religious music on Sunday and at other special times.

7. (II) PSYOPS

The battalion continues supporting the Chiu Hei and Hei Chanh programs. The battalion works jointly with the 4th Infantry Division, distributing leaflets and in aerial sound broadcasts. These activities are programed in known or suspected enemy areas of operation and are the responsibility of the PSYOPS Officer.

8, (C) Safety and Standardization

a. Standardization: The Battalion Standardization Pilot flew 24 check rides in November, 21 in December and 14 in January. These check rides are broken down as follows:

- (1) 5 SIP (Standardization Pilot)
- (2) 9 IP (Instructor Pilot)
 (3) 7 AC (Aircraft Commander)
- (4) 42 Quarterly check rides and in-country standardization

and orientation.

5) 3 Post Accident Check Rides

Primary emphasis during all rides has been upon aircraft and emergency procedures. Young aviators soon develop a high degree of proficiency but may arrive at AC status without over having a review of emergency procededures. This is an underlying cause of "complacency" and leads to unnecessary low level flight, take-off over unnecessary barriers, disregard for routes offering good forced landing areas, failure to make precautionary landings and to execute successful autorotations. Daily committment of all flyable assets precludes adequate scheduled unit flight training.

b. Safety:

- (1) The accident rate (per 100,000 flight hours) for this period was 24.6 for 40,515 flight hours. All were major accidents.
 - (a) November Three accidents, rate; 21.6
 - (b) December Four accidents, rate; 27.3
 - (c) January Three accidents, rate; 23.8
 - (2) The following causes (all were major accidents) are sited.
 - (a) #391 22 Nov 67
 - " U FOD
 - k. Maintenance error
 - 3. Lick of forced landing sites in AO
 - b. #390 25 Nov 67
 - 1. Material failure (sun goar shaft)
 - 2. Failure to execute successful autorotation
 - (c) #759 28 Nov 67
 - 1. Crow orrer, hit tree
 - (d) #577 6 Doc 67
 - 1. Crow orror
 - 2. Patimo
 - 3. Possible engine deficiency
 - (e) #219 16 Doc 67
 - 1. Over loaded

12

- 2. Possible engine deficiency
 2. Poor selection of flight route

(I) #154 20 Due 67

- 1. Crew error, hit tree
- 2. Fatigue

(g: #697 21 Dec 67

- 1... Crew error
- 2. Poor judgement
- Poor operating conditions (dust, crowded, no
- (h) #075 6 Jam 68
 - 1. Over loaded
 - 2 Crew error
- (i) #168 IO Jam 68
 - I. Short shaft failure
 - 2. Lack of forced landing site in AO
- (j) /181 21 Jam 68
 - Overweight
 - 22 Went IFR in dust
- (3) During the period an air traffic flow plan has been devised for the Pleiku metropolitan area. Tho plan, accepted by the Air Force and 4th Infantry Division, is still being staffed prior to implementation.
- (A) The airfield at Holloway has new improved runway markings, runway lighting and a lighted miniport. Several major dust areas have been pene- primed, and several hauardous wires have been marked.
- (5) A new Aviation Accident Provention SOP has been written and a new Ground Safety SOP is close to completion. Both functions have boon comsolidated into one office. This action will not only reduce the commanders span of control for safety matters, but will provide the best qualified personnel to direct the Ground Safety Program. The two programs normally overlap and integration should not create any major problems.
 - 9. (C) Post Hondquarters (Comp Holloway)
- a. During this reporting period, Post Headquarters continued normal operation and continued offert was expended on various projects

with the goal of improving Post Hondquarters and Defense Structures:

- (1) With an increase in availability of material the perimeter light project made considerable progress during the period. Approximately 50% of the system is operational and approximately 30% is currently in use. The major problem encountered during the period was the inability to get a crane into a swamp to erect light poles. This problem was solved by sling loading the poles with a UN-1N helicopter.
- (2) The 815th Engineer Battalion continued to progress on the 70 pad Christmas Tree Heliport. Progress was delayed due to increased Combat Engineer support and emergency road work during this period. Estimated completion date is now 1 March 1968.
- b. The Airfield Operations Detachment was reorganized under a new TO&E. There were changes in personnel and equipment with the major change being the upgrading of the Commander from Captain to Lioutenant Colonel.

' 10. (C) Signali

- n. Dial telephone service was installed at Comp Helloway during the month of December. Although this system is not complete, all major staff sections and companies have dial telephone service. This new dial system has greatly increased the quality of telephone service and reduced the time needed to place calls.
- b. Two types of telephone service have been installed. Class A and C service. Class A service gives the subscribers access to the long distance telephone system. All major staff section and companies have Class A dial service. This is especially important in an aviation battalion where units are separated and operate over a large geographical area. Class C service within the Plaiku area has provided faster service for subscribers at Camp Holloway who still do not have dial telephones.
- c. The dial telephone system will eventually replace the Camp Holloway AN/TTC-7 switchboard. Existing dial telephones at Camp Polloway have greatly reduced the amount of traffic handled by the Holloway switchboard. This in term has provided faster switchboard service for subscribers at Camp Holloway who still do nothave dial telephones.
- d. VHF radio relay-carrier communications are presently being used to link Camp Holloway with the 155th AHC at Ban Ma Thuot and the 57th AHC at Kantum. Direct OKTS to these companies has greatly improved command and administration between 52d CAB and these two companies. As soon as the new AN/VSC-2 or AN/ARC-119 radios are issued to these companies a more reliable voice communications net will be established.
- e. The new AN/VSC-2 HF/RTT radio has proven to be a reliable and useful piece of equipment. This SSB radio has provided the battalion

with a reliable means of radio communications with the 17th Aviation Group Headquarters. Previous radios utilized were not as reliable and voice communications was often weak and distorted.

f. The AN/NSC-2 or AN/MRC-119 radio set will be issued one each per aviation company as soon as they arrive within the command. These radios will not with each other and provide an HF not between hattalion and company operations.

11. (W) Aircraft Maintenance

a. Maintenance Statistics:

	<u> 11H-1 H</u>	<u> </u>	<u>CH-47A</u>
Aircraft Authorized -	115	40	16
A/C Assigned (AVG) -	18	6	13
Availability Rate -	80,8	75.7	58.1
EDM Rate -	14.7	15.7	28.8
EDP Rate -	3.6	5.6	13.0

(For detailed statistical data, see inclosure 10)

b. Due to the increase in enemy attacks on units of this battalion availability was dropped to some extent. However, after attack remains and round the clock maintenance has kept the availability at a phenomenal rate. More specifics are presented in Section II.

12. (U) Flight Surgeon

- a. During the past three months the Comp Holloway Despensary has been averaging 1900 outpatients visits per month while supporting about 4000 personnel.
- b. There have been no significant outbrenks of unusual or epidemic diseases during the past reporting period. Upper respiratory infections, veneral diseases and dermatological conditions are the most prevailant diseases. The rate for these diseases have remained about the same month to month with the exception of an upsurge in URI during November.
- c. The significant aviation medicine problem is aviator fatigue. This problem cannot be solved until sufficient aviators and equipment are available for use in Vietnam. Aviators are automatically grounded at 140 hours by their company and allowed to fly if the mission dictates only if cleared by the flight surgeon.

SECTION II - Commanders Observations and Recommendations Part I, Observations (Lessons Learned)

1. (c) Intelligence FICENTIAL

a. Item: Daily INTSIM

Biscussion: The Daily INTSUM published by the Battalion S-2 Section consisted of, for the most part, a listing of contacts, agent reports, atc, extracted from INTSUMS published by various C2 sections in the Fleiku, and Kontum area. A time study revealed that preparation and publication of the INTSUM cost upwards from three (3) hours daily. Coordination with adjacent and higher headquarters subscribers revealed that they were merely receiving from this Battalion, several days later, items that they had already published. Coordination with subordinate subscribers revealed that a daily listing of Corps wide contacts, incidents, agent reports, etc., was of no benefit to company size aviation units.

Observation: A numbered Intelligence Bulletin containing High Hazard areas, 24 hour weather forecast, aircraft Shot Ats, and a discussion of current enemy capability and probable course of action, would perform a much more beneficial service. Bulletin was initiated 1 Jan 68 and time saved by not preparing and publishing the Corps wide listing, was used to prepare the more comprehensive "Discussion Section".

2. (C) Operations

o. Thom: Bomb Crater Landing Zones

Discussion: The use of the bomb crater landing zones increased significantly during the past quarter. During the past several months this battalion has experimented with the use of these landing zones on many minor operations. However, during the Battle of Dak To, it became an operational necessity to use them in almost every airmobile operation. The terrain within the Spaatz AO (Dak To) is characterized by double and triple canopy jungle, thick undergrowth, and 200 - 300 trees; landing zones are almost non-existant. Seeking the utmost in airmobile floxibilthy, the U.S. Air Force was frequently called upon to develop helicopter landing areas. To perform this task they employed the use of several 750 and 1,000 pound bombs concentrated into a small area. Unfortunately present delivery techniques precluded any two bombs from falling into the same area. Many of the bombs fell onto steep slopes in the torrain, leaving large gaping holes that were unusable for heliborno operations. It was found that at best, only one chip landing zones could be expected. Mowever, even these had the one single troo or stump in the wrong place, requiring the ship to hower at 15 - 20 feet to discharge its passengers. The undesirability of this is obvious; personnel injuries, rotor blade strikes and aircraft accidents rates went sparing.

Observation: The basic concept of this technique is excollent. It broadens the employment of helicopter forces immeasurably. Powever, extensive improvements must be made in both delivery techniques and the type ordinance used. The use of A-1E aircraft equipped with 2,000 pound daisy cutters, has been the most effective in this area. This is primar-

ily due to the increase in accuracy by slower delivery speeds and the increased effectiveness of the 2,000 pound daisy cutter. Unfortunately the bonb shackles on this aircraft were found to be unsafe to carry this load, and the use of this type of ordenance was discontinued.

b. Item: Dust Hazards

Discussion: During this reporting period several incidents have occurred as a result of dust hazards. These incidents have ranged from the closa-call category to the major accident. Operational requirements compel continued usage of the numerous simi-improved airfields located in the Central Highlands. This fact alone does not always create the hazardous conditions. These conditions normally arise with the selection of these sites for major operations. With this selection comes a vast armada of men and equipment to an airfield never designed to accomodate the increased traffic. The area is quickly leveled by bulldozers and vehicular traffic over the dirt roads is doubled. In addition, the increase of air traffic aggravates the already hazardous dust conditions.

Observation: Obviously it would not be tactically sound to make major improvements to an airfield prior to a major operation. Fowever, if immediate engineer assistance could be made available, many of the dust problems would never occur. Immediate construction of necessary road nets would preclude the taxi-ways from becoming major highways for resupply. Helipads and heavy traveled roads should be peneprimed as soon as possible to further improve the area. In most cases if the above improvements could be made early in the operation, the dust problem could almost be eliminated.

c. Item: Late Releases by Support Units

<u>Discussion</u>: This unit is still encountering a recurring problem of supported ground units failing to release their C&C and resupply aircraft at the appointed time. Aircraft have been released as late as 2100 hours which in several instances has contributed to crew fatigue, delayed intermediate inspections, and late arrivals for other missions assigned the aircraft.

Observation: Aircraft scheduled to be released at a specific time should be released at that time. The supported unit should be made aware of the problems incurred by their failure to observe the release time.

d. Item: Low Level Approaches in Support of Clandestine Reconnaissance Operations.

<u>Discussion</u>: On numerous occasions this battalion has been required to perform the covert infiltration of reconnaissance teams into areas known or suspected anomy activity, as well as effecting the exfiltration of these units, often under fire. The clandestine nature of these operations created a requirement for reconnaissance at altitude

several days prior to the infiltration, and insertion during those hours of limited visibility, utilizing techniques which would minimize the possibility of enemy detection. A covert exfiltration was also required to limit the exposure of the exfiltration aircraft to enemy fire.

Observation: It was determined that the best technique to perform this mission was a low level approach; controlled throughout its conduct by an aircraft at altitude. The command aircraft is positioned so that visual contact with the primary landing zone can be effected. With both the landing zone and the infiltration aircraft in sight, the command aircraft directs the infiltration aircraft to touchdown with the LZ. It was found that the infiltration pilot need not have seen the landing zone prior to the flight. The same procedure is used for exfiltration and emergency extraction, with the exception that the reconnaissance teams select the pickup site, and identify their location to the command ship by the use of pannels, signal mirrors, or smoke.

e. Item: Daily CM-47 Operational Commitments

Discussion: During this period, as with the last, the battalion has had to fly many loads to areas where airfields are available. The number of sorties involving roves of the supported units continue to increase. There have been many instances where the loads were not "CH-47" loads in that the weight was far below the desired 7,000 pounds. Also the Chinook is still being used for loads that are capable of being carried by smaller, less expensive aircraft. Many hours of CH-47 flying time are still being used to transport units to an area accessable by roads. In most cases these areas are but a few miles from the resupply point.

Observation: The Chinook should seldom be used in flying loads into areas where airfields are available. With improved planning and coordination, fixed wing aircraft are available for these missions. Continued emphasis must be placed on the requirement for reducing sorties in unit moves. Units should monitor all Chinook sorties and make certain that the loads are as close to 7,000 pounds as possible or that they are at least an item that a smaller aircraft cannot carry. Every effort should be made to utilize the existing road network for unit movement and resupply of units that are accessable by roads.

f. Item: Flying Hour Program

Discussion: During the reporting period a series of inevitable circumstances led to some interesting developments. Due to the maximum support effort of this organization during the Dak To campaign, post Dak To aircraft availability was vastly decreased. However, even with the loss of aircraft, using units appeared to be functioning normally. Some investigation of this matter revealed, that when aircraft were only available for a few hours, using commanders became keenly aware of his aircraft utilization. Missions well well planned and organized to achieve the maximum, with the allotted time.

Observation: Considering the above; a possible solution to the present shortage of mission ready sincraft is apparent. A closely monitored, five hour flying day for other than tactical requirements, could be established. This should be sufficient support in almost every case. Exceptions to this rule could be taken on a mission basis only. This would keep blade time at a minimum, and allow for sorely needed day-light maintenance. If additional administrative time is needed on one day, an equal amount of ground time should be allowed the following day.

g. Item: Sapper Attacks

<u>Discussion:</u> During the reporting period assaults on this battalions installations have increased considerably. In almost every instance the enemy has successfully employed the use of sappers. Analysis of after action reports clearly indicate, that damage suffered at the hands of the sapper far exceeds that of the damage caused by mortars.

Observation: In an attempt to reduce the effectiveness of the sappers, new precautions have been taken. New and strategically placed positions have been constructed in the aircraft parking areas. These positions are automatically manned when the units are placed on fifty per cent alert. Personnel in these positions are to ston the sapper before they have the time to place their charges.

3. (C) Signal

a. Item: Shortage of Maintenance Float FM, UHF, VHF RT Units

<u>Discussion</u>: Maintenance Cloat FM, UHF, VHF RT units never seem to reach the 52d CAB Avionics Shop. Equipment has been released by the 58th Transportation Bn and never arrived here.

Observation: The close liaison with the supporting facility is often necessary in order to determine whether parts have been shipped and to which location.

b. Item: Shortage of APH-5 Parts

<u>Discussion</u>: The Avionics Shop has experienced great difficulty in receiving parts for the APF-5 protective helmet. According to the Avionics News Letter published by the 34th General Support Group, those repair parts are in country. Repair parts for the APF-5 often take more than sixty days to receive on an O2 priority.

Observation: That immediate action is received if requisitions are carried to 34th General Support Group.

4. (W) Maintenance

a. Item: Revetments

Discussion: The value of revetments in helicopter maintenance areas can not be minimized. The last four attacks against units of this battalion have been concentrated against maintenance areas. The enemy has used mortars, rockets, and hand carried sappor charges or a combination of all three. In general, the maintenance areas offer the larger structures, the greater concentration of equipment and aircraft and are lighted at night. In addition a successful attack limits a units maintenance repari capabilities. When aircraft are reveted a mortar round landing outside a revetment will cause damage to a single ship and usually only to the area extending above the revetment. Extensive damage to main rotor, tail rotor, and pylon assembly (WH-1) is often incurred, however, this is usually repairable. When a helicopter is not revoted, which is frequently true in crowded maintenance areas, a round falling some distance away will cause extensive damage. Aircraft in this situation suffer considerable sheetmetal, wiring and window damage which requires much time and effort to repair. Even in case of fire a revetment will confine the damage to one sircreft which is not the case when unreveted ships are parked some distance apart. The tendency of raintenance personnel to park the aircraft as close to the work area as possible is a common error.

Observation: Revetment should be as high as practical and long enough to protect the full leng of the aircraft. Extra revetments should be constructed in maintenance area in anticipation of peak input of aircraft. Consideration should also be given to parking 2½ tons trucks on the open side of the revetments this also gives dispersion to vehicles, which are also prime targets of the enemy.

b. Item: Radio Retrofit Program (Project ZYR)

<u>Discussion</u>: IW-1 aircraft continue to be received without the KY-28 retrofit being completed. This program places an additional burden on maintenance, administration and operations. This unit has had two aircraft at a time in Project ZYR for six month. This is two aircraft that can not perform a mission.

Observation: The retrofit on new aircraft should be accomplished in CONUS before they are sent to RVN.

c. Item: Repair of Helicopters After Attack

<u>Discussion:</u> Following a concentrated ground attack on a helicopter unit there will be a considerable amount of sheetmetal remain to be performed, usually beyond the capabilities of the unit. The unit will often times be reluctant to turn work over to support maintenance to repair knowing that given enough time they can make the repairs themsolves.

20

Observation: Upon notification of an attack the support maintenance unit should be prepared to provide a sheetmetal repair team. In the case of extensive aircraft destruction a contact team should be provided to assit in classification, inventorying and expeditious processing of aircraft to supporting maintenance. Unit maintenance personnel should be encouraged to turn is as much work as possible to their support and not to get tied up in major repair projects.

d. Item: Armament Copabilities

<u>Discussion:</u> Due to the lack of armament personnel (9 on had of 39 authorized) assigned to the units at Camp Holloway (3 AHC and 1 ASHC) consideration is being given to establishing a consolidated armament shop. This will provide a pooling of personnel and physical resources.

Observation: When an adequate physical facility is located and a qualified shop commander is found this consolidation will take place.

e. Item: Dispersal of Vehicles and Equipment

<u>Discussion</u>: During January this battalion lost numerous vehicles and equipment. This combat damage was incurred by satchel charges, and could as well have been by mortar fire.

Observation: By dispersal of equipment the number incurring damage would have been reduced. Compound areas do not lend themselves for wide dispersal, also security of equipment cannot be maintained with wide dispersement. The equipment can be spread throughout the compound and eliminate congestion. When possible, revetted areas should be provided for prime equipment io., Wreckers, Fuel Tanker and Aircraft Service vehicles. Maintenance shop areas should never be allowed to become congested at night. During good weather most maintenance can be performed by operators within assigned parking areas.

5. (T) Aviation Safety

a. Item: Foreign Object Damage

<u>Discussion</u>: Foreign object damage (FOD) was identified as a major cause of engine usage. A request for assistance is the design of a "last chance" filter for the T-53-L13 engine installation was requested of USABAR. In addition the units have been instructed to perform a last chance inspection of the sand and dust separator and plenum chamber area.

Observation: Failure of the sand and dust separator to stop FOD and increased night rmintenance are believed to be the primary causes (See incl 11)

b. Item: Accident Cause Factors

<u>Discussion</u>: In our continuing search for accident cause factors an analysis of the Crash Facts Message File was made. (See incl 12 from 1 Jun 67 to 22 Doc 67 time of analysis). The 41 events lead to the following conclusions. First, that there were no accidents, incidents, forced or precautionary landing from 0700 - 0920 hours. Second, that 67% of the major accidents occured after 1500 hours or during the last 25% of the normal flying day.

Observation: It appears that aviator fatigue may be more closely related to the number of hours flown in one day than it is related to flying time per month. Consideration for a 5 hour non-tactical mission flying day and a 1700 hour aircraft release time has been requested. This will not only provide for aviator fatigue prevention, but will provide some daylight hours for maintenance.

c. Item: Maintenance Personnel

<u>Discussion</u>: The fatigue factor of maintenance personnel is also serious. Continuous daily committment of flying assests beyond the flying hour program and the shortage of skilled personnel, especially supervisors, cannot help but effect the quality of maintenance.

Observation: The aircraft are flying more and more hours than programmed. Trained maintenance personnel become fewer and are forced to work longer and harder under poor lighting (or none at all). The inevitable result can only lead to mistakes and accidents. We must either reduce the flying hours and force the user to improve his use of the aircraft and increase the number of maintenance personnel or accept lower standards and high accident rates.

PART II: . Rocommondations:

- 1. (C) Operations: Reference Section II, Part I, para a, b, c, e, f.
- a. Recommend increased use of the 2,000 pound daisy cuttor for this type operation. In addition, that the necessary modifications be made on the A-1E aircraft be made to carry the larger leads.
- b. Recommend closer direct liaison between the major aviation unit and engineer support unit concerned, prior to the commencement of a major operation in the vicinity of an airfield.
- c. Recommend command emphasis be placed on the absolute necessity of scheduled release times being honored.
- d. Recommend a study be made to determine the reason behind the phenomenal increase in sorties for battalien moves. In addition, that requests for CH-47 support be closely monitored.

- Recorr rd a study be conducted to determine a realistic flying hour program, would meet operational requirements and increase needed ground time for aviation units.
- 2. (C) Signal: Reference Section II, Part I, para 3b. Recommend present system of requisitioning be inspected. Several sections still report difficulty in receiving requested items through supply channels. This would indicate requests are not being proporly processes.
 - 3. (W) Maintenance: Reference Section II, Part I, para 4b.

Recommend future acquisitions of aircraft be retrofited during production.

- 4. (W) Safety: Reference Section II, Part I, para 5a.
- a. Recommend immediate implementation of a "last chance" filter for the T-53-I/13 engine. That the sand and dust separator inspection be emphasized to other aviation units with similar difficulties in this aroa.
- b. Recommend a study be conducted by a USABAAR team concerning the fatigue problem. This should encompass both aviators and maintenance personnel. In addition, that aircreft utilization be monitored for a possible increase in daylight maintenance time.

12 Incl as

Commanding

1. List, 52d CAB Dotachmonts withdrawn, Ags. DA

2. Recapitulation of flying hours and availability

3. Civic - Action photographs Williams, Has, un Chronological Sequence of Significant Events

5. Map of operational area

After Action Report (Dak To)

After Action Report (KTM Attack)

8. After Action Report (Hol Attack)
9. After Action Report (RMT Attack)

10. Recapitulation of availability, mission ready, EDP, and EDM percontages by month

11. Crash Facts Extract

12. F.O.D. Problom aroas

AVGD-SC (16Feb 68) 1st Ind SURJECT: Operational Report for Quarterly Period Ending 31 January 1968.

HEADQUARTERS, 17TH COMBAT AVIATION GROUP, APO 96240

TO: Commanding General, 1st Field Forces Vietnam, APO 96350

- 1. (U) The 52d Combat Aviation Battalion Operational Report for quarterly period ending 31 January 1968 is forwarded for information and action as necessary.
- 2. (U) This headquarters has reviewed this report and concurs with the report as modified herein.
- 3. (C) Reference section I para 106 concerning classes of Telephone Service. Last sentence should read; "class c service within the Pleiku area has provided faster service for subscribers at Camp Hollaway who have received dial telephones."
- 4. (C) Reference section I para 10d concerning voice communications. Concur the intent of this item is to emphasize that the AN/USC-2 and AN/MRC-119 will provide an organic means of communications that may be used as a back up when circuits provided through the Army Area communications systems fail.
- 5. (C) Reference section II Part I para 4a. Concur. Command emhasis is being placed on revetment criteria and design to afford maximum protection of aircraft.
- 6. (C) Reference Inclosure 8 para 5b (3). Item concerning perimeter lights at Hollaway has been completed. Short circuits in some of the wiring exist but is being isolated and corrected.

FOR THE COMMANDER:

ROBERT R. LOVELY

CPT, AGC

Asst Adjutant

CONFIDENTIAL

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

20

AVFA-GC-OT (6 Feb 68)

2d Ind

EUBJECT: Operational Report-Lessons Learned for Quarterly Period Ending 31 January 1968 RCS CSPOR-65 UTC MCMIGK 52d CAB (U)

HEADQUARTERS, I FIRID FORCE VITTMAN, AFO 96350

9 MAR 1968

TO: Commanding General, 1st Aviation Brigade, AFO 96375

Concur.

FOR THE COMMANDER:

ROBERT C. GABBARD ILT; AGC ASST ADJUTANT GENERAL

Copy furnished: 17th Cbt Avn Gp 29

AVBA-C (6 Feb 68) 3d Ind SUBJECT: Operational Report - Lessons Learned for Quarterly Period Ending 3l January 1968 RCS CSFOR-65 (UIC MCYMTO)(U)

HEADQUARTERS, 1ST AVIATION BRIGADE, APO 96384 MAR 31 1968

THRU: Ucommanding General, US Army Vietnam, ATTW: AVHGG-DST, AFO 96375 Commander in Chief, US Army Pacific, ATTW: GPCP-OT, APO 96558

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310

- 1. (U) This headquarters has reviewed this report and concurs with the report as modified herein.
- 2. (C) Sec 1, para 101, page 15: The AN/VSC-2 radio sets are being issued as they arrive in NVN. The AN/ARC 119 are being shipped direct to the using unit from the manufacturer. The logistical elements in AVN do not exercise any control over distribution of these radio sets.
- 3. (C) Sec II, para 3b, page 19: This headquarters is issuing instructions concerning requisitioning of APH-5 and ballistic helment parts. These helment parts are a lst Logistical Command responsibility, not a responsibility of the 34th General Support Group. All helment parts on hand at the 34th General Support Group are being turned over to this headquarters for redistribution to 1st Aviation Brigade units.
- 4. (C) Sec II, para la, page 22: This headquarters recommends that USARV establish coordination with 7th USAF to deal with this problem. The availability of 2000 pound daisy cutter bombs does not meet the demands. Additionally, the techniques used should be analyzed jointly in search for improved employment.
- 5. (C) Sec II, para 1b, page 22: This is a matter which must be accomplished at 52d Combat Aviation Dattalion, supported division and engineer support unit level.
- 6. (C) Sec II, para 1c, page 22: Headquarters I Field Force Vietnam published a letter subject, Aircraft Accidents, dated 10 Jan 63 that encourages units to plan the use of their supporting aviation to insure minimum flying during the hours of darlness which will improve safety and aircraft maintenance. Additionally, Headquarters 4th Infantry Division published a letter subject, Aviation Utilization, dated 20 Feb 68 encouraging all subordinate units of that division to adhere to the 1700 release time as much as possible.
- 7. (C) Sec II, para ld, page 22: This is a matter which should be determined by the 52d Combat Aviation Battalion and its supported units.

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

CONFIDENTIAL

मिन्स है है 1980 AVBA-C (6 Feb 68) 3d Ind SUBJECT: Operational Report - lessens becamed for Quarterly Period Ending 31 January 1968 RCS COPCR-65 (UTC MONTRO)(U)

8. (C) Sec II, para 4a, page 23: This headquarters published a letter subject, Prevention of FOD to T-53 Engines, dated 1 Mar 68 which requires a daily inspection of the particle separator. The crew chief is required to have the cowling opened, air filters removed and the top half of the particle separator removed. The pilot or co-pilot from the first crew of the day to fly the helicopter inspects for foreign objects and makes a directed entry in the DA Form 2408-13.

FOR THE COMMANDER:

JAMES M. GOLDMANN 1LT/AGC

Assistant Adjutant General

CONFIDENTIAL

AVHGC-DST (6 Feb 68) 4th Ind (C) CPT Arnold/twl/LBN 4485 SUBJECT: Operational Report For Quarterly Period Ending 31 January 1968 RCS-CSFOR

HEADQUARTERS, US ARMY VIETNAM, APO San Francisco 96375 12 APR 1969

TO: Commander in Chief, United States Army, Pacific, ATTN: GPOP-DT, APO 96558

- 1. (U) This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 31 January 1968 from Headquarters, 52d Combat Aviation Battalion as indorsed.
- 2. (C) Pertinent comments follow:
- a. Reference item concerning bomb crater landing zones, page 16, paragraph 2a; and page 22, paragraph 1a; and 3d Indorsement, paragraph 4. A letter has been forwarded to COMUSMACV, ATTN: MACJ3 regarding this matter.
- b. Reference item concerning radio retrofit program, page 20, paragraph 4b; and page 23, paragraph 3.
- (1) The MD-736 discrete discriminators and shielded cabling have not been available for installation in aircraft at the time the aircraft were processed through ZYR retrofit sites. Originally, when the ZYR retrofit kits were assembled, the requirement for the MD-736's was not known. This requirement became known after the KY-28 failed the tempest testing. At that time, procurement action was initiated for the MD-736's. Shielded cabling is now arriving in sufficient quantities to incorporate this modification in the normal ZYR program.
- (2) Replacement aircraft and new production aircraft are scheduled to have this modification accomplished in CONUS in addition to all other modifications now in the ZYR program.
- c. Reference item concerning accident cause factors, page 22, paragraph 5b; and page 23, paragraph 4b. A study by this headquarters indicates a pattern of accidents entirely different. It is found that aircraft accidents occur on a rather even basis throughout the day from 0800 to 1800 with the largest number actually occurring between 0800 and 1000 hours. It has been established that measuring aviator fatigue based on the number of flying hours per

23

CONFIDENTIAL

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10 AVHGC-DST (6 Feb 68) 4th Ind

SUBJECT: Operational Report For Quarterly Period Ending 31 January 1968 RCS-CSFOR

month leaves much to be desired. USABAAR is currently conducting a study on this matter.

- d. Reference item concerning maintenance personnel, page 22, paragraph 5c; and page 23, paragraph 4b:
- (1) Night maintenance and resultant problems are recognized. Two actions are pending to relieve this situation:
- (a) Expedited procurement of portable lights to provide adequate lighting for the performance of night maintenance.
- (b) Expedited approval of USARPAC manpower survey requested through channels.
- (2) The matter of monitorship of aircraft utilization for a possible increase in daylight maintenance time should be acted on at Headquarters, I Field Force Vietnam since operational control of aviation assets rests with that headquarters (reference page 23, paragraph 1c).
- 3. (U) A copy of this indorsement will be furnished to the reporting unit through channels.

FOR THE COMMANDER:

C. S. NAKATSUKASA

Captain, AGC

Assistant Adjutant General

Copies furnished: HQ 52d Cbt Avn Bn HQ 1st Avn Bde HQ I FFORCEV GPOP-DT (6 Feb 68) (U) 5th Ind SUBJECT: Operational Report of HQ, 52d Cbt Avn En for Period Ending 31 January 1968, RCS CSFOR-65 (R1)

HQ, US Army, Pacific, APO San Francisco 96558 3 MAY 1368

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. 20310

- 1. This headquarters has evaluated subject report and forwarding indorsements and concurs in the report as indorsed.
- 2. Reference 4th Indorsement, paragraph 2d(1)b. The Manpower Survey-USARV Security Forces, conducted during December 1967, approved by: 1st Indorsement, GPOP-FD (23 Jan 68), subject: Manpower Survey-USARV Security Forces (TDA P-5-WIZJAA-00) recognized additional security personnel which would release crew chiefs, gunners, and maintenance personnel to perform their primary duties. The 52d Combat Aviation Battalion was specifically identified with the aforementioned survey.

FOR THE COMMANDER IN CHIEF:

C.L. SHORTT CPT, AGC Asst AG

DEPARTMENT OF THE ARMY
HEADQUERTERS, 52D CG.BAT AVIATION BATTALION
APO San Francisco 96318
"FLYIIC DRAGONS"

AVGD-CZ

5 February 1968

SUBJECT:		Recapitulation of	• •	Flying Hours	ours					Combin	්ර	
UNIT	Konth	•	Fours Flown	Avg. Hours	Avail ability	Lvg Hr. Slicks	Hours Flown	hvg. Hours	Avail- ability		Total Combined Hours Avg	
		Hand	1//	Guns		on Rand	· į	יייייייייייייייייייייייייייייייייייייי	70	- 1	rioui s	•
57th	Nov	00 t C	466	75.5	0,50 0,89 0,89	21,0		117.0	9 27		105,6	
	Jan	6,9	359	52,0	50.0	18.5		104.2	63		0°06	
35 T		7.2	76.77	67.5	0.0%	20,5		106.2	83.4		36.5	
		-10	438	59.2	.∵. .∵.	20.1		76.9	8,03 8,03		72.1	
	Jan	5.4.5	404	63.1	82.6	19,0		85,6	84.6		6*62	
N Company		Į~.	414	58,3	6.17	20.4	1948	95.5	91.8	2362	85.9	
		9	730	71.7	9,08	20.0		91 04	67.4		86.8	
	Jan	\ 0	761	16.7	92.3	17.5		90.3	7.68		67.3	
177th	Nov	7.5	519	69.2	77.0	18.7		123.4	₽. 13	2826	107,8.	
		භ	. 753	79.3	56.7	20,00		133.2	8, 2		117.2	
	Jen	50%	240	69,2	<u>6</u>	18,6		106.0	78,6		95.2	
, , , , , ,			57.6	77.3	6.33	20,2		5,68	83.2		4.68	
			276	3,17	C 33	20.2		108,0	80,3		98.1	
	Jen	့	633	79.9	85.0	18,0		104.7	78,1		97.0	
	实水水水水	全年 医水水水水素	字字: "表表示"	类点类求学	"宋·孝·孝·孝·孝·孝·孝·孝·孝·孝	を表現なる大学で で のので	3.	学生を主なな	**************************************		00 - OO	
523	Nov	37,2	27.2	53.5	1.87.	100.8		\$ \$ \$ \$	C/4°0		07.44 07.00	
	Dec	37.50	2653	101	٥° دي.	100,2		105.1	- 0 i	,	, ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	
	, jan	35.5	24:03	67.7	68,2	,22 1,32 1,33 1,33 1,33 1,33 1,33 1,33 1		58°4	2, 0.	• • • •	89.1	

CONFIDENTIAL

Inc/2

1.vail - ability 55.0% 65.0% 54.5%	(1) ment hin
Percent of Dh. Program 142% 168% 169%	following provisions: ction, and (2) Replace Unission ready" or wit
Avg. Hours per CH-47 70.8 83.7 83.9	EMIPES: Liverage number of aircraft is based on those estuality on hand with the following provisions: (1) Liverage number of aircraft is based on those estuality the day following destruction, and (2) Replacement Destroyed aircraft are dropped from the first day that they become "mission ready" or within aircraft or picked up on accountability on the first day that they become "mission ready" or within 72 hours following receipt, whichever occurrant of the first of the following receipt, whichever occurrant occurrants following receipts.
Hours Flown 1118 1305 1174	is based on those firention than the firent on the firence occurs firence.
ivg. CH-47 On Hand 15.8 15.6 14.0	aircreft is best drowed from acc on accountabilitieipt, whichever
Nonth Nov Dec Jan	EMIPES: Lverage number of aircraft Destroyed direcraft are dropped direcraft are dropped direcraft are dropped direct for picked up on account hours following receipt, which
Unit 179th	EMIPES: Lven Destroyed aircm ft 72 hours

DEPARTMENT OF THE ARMY
HEADQUARTERS, 52D COMBAT AVIATION BATTALION
APO San Francisco 96318
"FLYING DRAGONS"

AVGD-CC

31 January 1968

SUBJECT: Detailed Chronological Sequence of Significant Events 1 November thru 31 January 1968

- (I) General: This detailed summary of significant events is extracted from the Daily Journal (J), Daily Intelligence Summary (I), Daily OPIEP-5 (W), Daily Allocation Report File (A), JSAFIDR (Shot At Reports) (H), After Action Report File (R), and covers the period 1 November 31 January 1968.
- 3. (C) Supported Unit Activities: Units and activities supported by the 52d Combat Aviation Battalion utilized aircraft in support of the type operation indicated. (See inclosure for diagram of operational area):
 - a. 4th Infantry Division (4th Inf Div)
- (1) Operation Mac Arthur (2nd Bdc, 4th Inf Div) Middleton AO Search and Destroy.
- (2) Operation Mac Arthur (1st Bde, 4th Inf Div) Spaatz AO Search and Destroy.
- (3) Operation Mac Arthur (2nd Bde, 4th Inf Div) Middleton AO Search and Destroy.
- (4) Operation Mac Arthur (TASK FORCE 22, Ath Inf Div) Wain-wright and Corrigidor AO Search and Destroy.
- (5) Operation Msc Arthur (173d Abn Bde, OPCOW Ath Inf Div) Bataan Leyte Luzion AO Search and Destroy.
- b. ARVN includes all II Corps ARVN units; primarily in Kontum, Darlac, and Fleiku Provinces.
 - (1) Road clearing operations
 - (2) Search and Destroy
 - (3) Cordon and Search

33

Ind 4

CONFIDENTIAL

COMFIDENTIAL

c. DSA II Corps

- (1) Support of HO, II Corps, Pleiku
- (2) Support of Sonier Advisors, primarily at Kontum and Ban Me Thuot.
 - (3) VIP Flights
- d. Company "E", 20th Infantry a First Field Force Vietnam (IFFV) long range reconnaissance organization. Details of operation are classified.
 - (1) Infiltration and exfiltration of reconnaissance teams.
 - (2) Reconnaissance
 - (3) Search and Destroy
- e. Operation Prairie Fire An operation conducting clandestine ground reconnaissance. Details of operation are classified.
- f. Operation Daniel Boone An operation conducting clandestine ground reconnaisance. Details of operation are classified.
- g. 52d Artillery Group Command and Control for Group Headquarters and emergency resupply of fire bases.
- h. Aviation Command and Control Aircraft utilized by 17th CAG for Command and Control of aviation operations.
- i. 5th Special Forces Group Support of Company "B", 5th SFG, Pleiku; Special Forces camps and Special Forces operations not included in other allocations.
- j. Press Camp Support of authorized representatives of civilian news agencies.
 - 3. (C) Sequence of Events:

Poriod 1 Nov 67 - 2 Nov 67

a. Weather (I):

Sky conditions averaged 3.500 scattered to 8,000 broken, high their overcast with rain showers during the early part of the afternoon lasting approximately one hour. Visibility varied on both days from one mile during the rain to thirteen miles after the weather cleared. Morning temperatures averaged 64°, afternoon temperatures ranged from 75° to 83°. Wind was from the NE at an average speed of 10 knots during daylight hours. Minimum density was during the hours of 0400 - 0600 at 3,500°. Maximum DA was during 1300 - 1500 hours at 4,600°.

 \mathbb{R}^{2}

b. Mircraft Allocation (Average per day) (A):

	<u>11H-1H</u>	<u>1151—1 C</u>	CH-471
4th Inf Div -	24	8	8
ARVN -	11	4	0
17th CAG -	4	1	. 0
52d Arty Gp -	1	0	0
DSA II Corps -	8	0	0
Press Camp -	*	0	0
Avn C&C -	4	0	0
5th SFG -	2	0	0
Prairie Fire -	3	4	0

- * Supported for less than majority of period and average is less than on aircraft.
 - c. Significant Events (I) (D) (J) (H) (R):
- (1) 02 Nov 179th conducted a Fire Base Move for 3/8 Inf, 4th Inf Div, in Mac Arthur AO. They moved 179 pax and 116 cargo tons in 74 sorties. The mission was conducted with no incidents and negative contact.
- (2) O2 Nov 170th WM-1H model aircraft received heavy enomy small arms and automatic weapons fire, vicinity YB8812. Aircraft took seven (7) rounds, 1 WIA and returned to Dak To Airfield.
 - d. Operational Statistics (W) (J) (H):

CBT SORTIES	OTHER SORTIES	HOURS	THE-1C HOURS	CH-47A HOTER
1394	719	375	156	68
TOTAL HOURS	<u>PAX</u>	CARGO TONS	N/C	A/C** DAM/DEST
599	2,950	328	1/0	1/0
CREW MEM	KBV EMENX	STRUCT DEST	MED EVACS	SORTIFS DELAY OR CXL FOR MX
1/0	0	0	6	0

^{**} Includes results of hostile fire and accidents.

35

Period 3 Nov 67 - 9 Nov 67

a. Weather:

Generally sky conditions digressed as total sky cover averaged 9/10. Light to moderate rain showers of one how duration occured the 4th and 7th of November during the early morning hours (0500 - 0700). Geilings in the area of operation averaged 1000' scattered, 5,000' broken and 7,000' overcast from 0900 - 1500 daily. Best sky conditions occured during early morning or late afternoon hours. Heavy ground fog was incountered and reduced visibility to 1/2 mile. Winds were calm during fog and rain conditions but increased to average speeds of 5 - 9 knots ENE during clear conditions. Daily temperatures varied from 60 - 83 degrees. Generally temperatures averaged 75° during the best flying conditions and in the low 60's during the poorer flying conditions. Density altitudes up to 4,660' were encountered 1300 - 1500 daily.

b. Aircraft Allocation:

	<u> </u>	<u> 1114-10</u>	<u>CH-471</u>
4th Inf Div -	25	8	7
ARVN - 17th CAG -	11 1	. 4	0
52d Arty Gp - DSA II Corps -	1 8	0	0
Ava C&C -	2	0	0
Pross Camp - 5th SFG -	1 2	0 .	0
Prairie Fire -	4	5	0

e. Significant Events:

- (1) 03 Nov 155th conducted a CA for 22nd ARVN Div, vicinity Kontum. 338 pax in 184 sorties. Mission was conducted with no incidents and negative contact.
- (2) 03 Nov 170th conjected a CA for the 3/8 Inf and 3/12 Inf, . h Inf Div, in Mac Arthur AO. Two assaults of 513 pax in 216 sorties. The mission was conducted with no incidents and negative contact.
- (3) 03 Nov 119th conducted a CA for the 1/12, 4th Inf Div, in Mcc Arthur AO. 211 pax in 103 sortios. The mission was conducted with no incidents and negative contact.
- (4) 06 Nov 155th conducted a CA and Final Extraction for 22nd ARVN Div, vicinity of Ban Me Thuot. 252 pax in 118 sorties. Mission was conducted with no incidents and negative contact.
 - (5) 06 Nov 170th conducted a CA for the 2/504 Abn, 173d

Abn Bde, vicinity of Dak To. 120 pax in 65 sorties. Heavy enemy fire was encountered in the landing zone. One (1) WH-1H received 5 hits, wounding one (1) crew member.

- (6) 07 Nov 155th and Ban Me Thuot City Airfield came under enemy attack at 2345 hours. The enemy attacked with 81mm mortars and the rounds fell for approximately ten minutes. Two (2) WH-7C gunships destroyed and others received heavy damage, but were repairable. Five (5) WH-1H model aircraft were damaged, but were repairable. One (1) transient UH-1H model from 4th Avn Bn was also damaged. Negative friendly or enemy KIA-WIA were reported.
- (7) 08 Nov 179th sent 2 CH-47 aircraft to Dak To, in respone to a Tactical Emergency for 1st Avn Bde, 4th Inf Div. Aircraft departedHolloway Army Airfield at 0220 hours, hauling Class V and med evacs throughout the night.
- (8) 08 Nov 189th WH-10 model aircraft shot down in classified area. The ship was on initial (hot) run and encountered intense enemy automatic weapons fire. Aircraft suffered loss of power and settled intotrees. Heavy enemy activity hampered rescue efforts. One (1) KIA and three (3) WIA. Aircraft was total loss and was destroyed on site by Air Force tac-air. The 189th had a total of two (2) WH-10 aircraft shotup on this mission.
- (9) 09 Nov 170th conducted a CA in support of the 3/8 Inf, 4th Inf Div, in Mac Arthur AO. They lifted 283 pax in 127 serties. Aircraft received light small arms fire approaching LZ. As aircraft departed LZ, heavy mortar fire was encountered. IV-1F was shot down and destroyed, resulting in one (1) crew member WIA.
- (10) 09 Nov 119th conducted a CA for B/24th CIDG, in vicinity of Dak To. They lifted 130 pax in 51 sorties. Mission was conducted with no incidents and negative contact.
- (11). 09 Nov 179th conducted a Fire Base Move in support of 173d Abn Bde, vicinity of Dak To. They moved 56 pax and 180 cargo tons in 54 sorties. The mission was conducted with no incidents and negative contact.
- (12) 09 Nov 179th CH-47A received two (2) hits from enemy heavy automatic weapons, in vicinity of YB850175. Negative injuries and the aircraft continued to fly.

d. Operational Statistics:

CBT	OTIER	UH-1H	HOIRS	CH-47A
SORTIES	SORTIES	HOURS		HOURS
4,926	1,783	1,589	373	258

TOT/L HOURS	PAX	CARGO TONS	A/C	DVW\Digat V\C##
2,220	9,575	1,250	6	7/4
CREW MEM	KBV — ENEWA	STRUCT DEST	MED EVACS	SORTIES DELAY OR CXL FOR WX
5/0	2	10	179	26

Puriod 10 Nov 67 - 16 Nov 67

a. Weather:

Generally flying conditions improved over the previous reporting period. 10 Nov 67 is the only exception with light rain showers throughout the area of operation from 0600 - 1600. Total cloud cover averaged 3/10 at 3,500' scattered, 8,000' broken and improved throughout each day to clear skies. Morning temperatures averaged 67° increasing to daily highs of 78°. Winds were predominately out of the NE (050° - 070°) at 5 - 8 knots increasing in late afternoons 10 - 17 knots. In mountainous terrain winds were steady at 20 - 35 knots with light to moderate turbulence. Density altitude reached highs of 4,500' and dissipated later in the day to 1,000' - 1600'. Visibility remained constant throughout each day at 12 - 15 miles.

b. Aircraft Allocation:

	<u> 111-14</u>	17H-1C	<u>CH-471</u>
4th Inf Div -	22	. 6	7
ARVN -	11	4	0
52d Arty Op -	1	Ö	0
DSA II Corps -	8	0	0
Avn C&C -	3	0	0
Press Camp -	1	0 .	0 1
5th STG -	2	0	0
Prairio Fire -	7	8	0
17th CAG -	*	0	0

c. Significant Events:

(1) 10 Nov - 119th conducted a CA in support of 1st Inf Bde, 4th Inf Div, in Spartz AO. They lifted 60 pax in 23 sorties. One (1) UH-1C was hit with heavy enemy anti-aircraft fire while on firing run. The aircraft fuel cell was hit and exploded at approximately 3001 altitude. Three (3) members were WIA and one (1) KIA: Aircraft was a total loss.

(2) 10 Nov - 119th WH-1H model aircraft was hit by enemy air

ZO

CONFIDENTIAL

burst, vicinity of YB893146. Air-burst was believed to be 37mm anti-air-craft fire, but was not confirmed. Aircraft sustained one (1) schapnel hole and continued to fly. Negative injuries to crew members.

- (3) 11 Nov 119th conducted a CA in support of the 3/12 Inf, 4th Inf Div, in Spaatz AO. They lifted 120 pax in 57 sorties. The mission was conducted with no incidents and negative contact.
- (4) 12 Nov 119th conducted a CA in support of the 1/8 Inf, 4th Inf Div, in Spaatz AO. They lifted 180 pax in 78 sorties. Enemy small arms fire was received in the vicinity of the landing zone. One (1) Whith model, assisting in the lift, sustained two (2) hits. Negative injuries and aircraft continued to fly.
- (5) 12 Nov 179th conducted a Fire Base Move in support of the 1/12 Inf, 4th Inf Div, in Spantz AO. They lifted 175 pax and 93 cargo tens in 69 serties. The mission was conducted with no incidents and negative contact.
- (6) 12 Nov 179th conducted a Battery Move for 1/8 Inf, 4th Inf Div, in Spantz AO. They lifted 293 pax and 199 cargo tons in 145 serties. Mission was conducted with no incidents and negative contact.
- (7) 13 Nov 52d CAB conducted a battalion size CA and Fire Base Move in support of 1/8 Inf, 4th Inf Div, in Spaatz AO. 24 UH-1H 4 UH-1C, and 9 CH-47A's were used to move over 550 pax and 143 cargo tons in 437 sorties. Fog and enemy automatic weapons fire delayed lift for over an hour. One (1) UH-1H model aircraft was hit with a enemy rocket (B-40) and was destroyed. The crew members were all WIA.
- (8) 13 Nov 155th conducted a CA in support of the 11th ARVN RANGER Bn, vicinity of Bao Loc. They lifted 729 pax in 226 sorties. The mission was conducted with no incidents and negative contact.
- (9) 13 Nov 179th conducted a Fire Base Move for 173d Abn Bde, in Spaatz AO. They lifted 36 pax and 179 cargo tons in 106 sorties. Mission was conducted with no incidents and negative contact.
- (10) 14 Nov 119th conducted multiple CA's in support of 3/8 Inf, 4th Inf Div, in Spantz AO. They lifted 450 pax in 212 serties. Enemy sniper fire was received in all quadrants around the LZ. No hits were sustained and negative injuries.
- (11) 14 Nov 155th conducted a CA in support of 23d ARVN Div, vicinity of Phu Heip. They lifted 555 pax in 193 sorties. Two (2) UH-1C model aircraft were shot down by heavy automatic weapons fire. Both aircraft received over 20 hits and were major combat losses. Two (2) crew members were WIA.

39

(12) 15 Nov. - 170th conducted multiple GA's in support of ARVN Abn, in Spoatz AO. They lifted 690 pax in 164 serties. Intense enemy small arms fire was received in the vicinity of the LZ. Cno (1) UH-1H model sustained one (1) hit, wounding a crew member.

d. Operational Statistics:

CBT	OTHER	TH-114	TH-10	CH-47A
SORTIES	SORTIES	HOURS	HOURS	HOURS
6,556	2,259	2,198	523	348
TOTAL	PAX	CARGO	1./C	A/C**
MOURS		TOMS	HIT	D^M/DEST
3,069	16,016	1,693	3	3/2
IAT\Kra	ENEMY	DEST	MED	SOUTIES DELAY
CEEM FIEM	KBA	DEST	EVACS	OR CXL FOR WX
. 8/1	10	10 .	380	10

Period 17 Nov 67 - 23 Nov 67

a. Wonther:

There was a noticeable improvement in sky conditions. Ceilings usually were 4,500° scattered, high thin broken throughout each day. Total cloud cover averaged 2/10. Temperatures increased to average 79° each day and dissipated later in the afternoon (0900 - 1630). Wind direction shifted more easterly and average speed remained 8 - 11 knots during the reporting period, visibility was 12 - 15 miles. Daily high density altitude averaged 4,300°.

b. Aircraft Allocation:

	तास-1 म	<u> 1117-10</u>	<u>011-474</u>
4th Inf Div -	20	10	3
ARVN -	11	4	0
52d Arty Gp =	. 1	0	0
DSA II Corps -	8	. 0	0
Avn 0&0	4	0	0
Pross Camp -	1	O	0
5th Swg -	S	0	0
17th CAG -	₩	O	0
Preirie Fire -	9	8	0
Co "E", 20th Inf -	1	0	O

45

CONFIDENTIA'

c. Significant Events:

- (1) 19 Nov 119th UH-1H model aircraft received heavy enemy automatic weapons fire in the vicinity of YB876078. One (1) UH-1C model gunship also received fire from the same area later in the day. Both aircraft sustained one (1) hit, and continued to fly with negative injuries.
- (2) 21 Nov Intelligence reports indicated a high probability of an attack on the Kontum military complex: All Army aircraft not of an immediate operational need or not in revetments were evacuated to Holloway Army Airfield. The possibility of an attack was verified by the discovery of rocket launching sites within 10 KMS of the Kontum Airfield.
- (3) 21 Nov 155th conducted a CA in support of the 144th Int (ANNN), in the vicinity of Bao Loc. They lifted 361 pax in 47 sorties. Mission was conducted with no incidents and negative contact.
- (4) 21 Nov 155th conducted a Final Extraction in support of the 24th Mike Force Company, vicinity of Di Linh. The extracted 126 pax in 24 sorties. Mission was conducted with no incidents and negative contact.
- (5) 22 Nov 119th conducted a CA in support of the 173d Abn Bde, in Spectz AO. They lifted 120 pax in 19 sorties. Two (2) UH-1H model aircraft received hits from enemy small arms fire in the vicinity of the LZ. Three (3) passengers were WIA, but only minor damage to the aircraft.
- (6) 22 Nov 179th responded to TAC "E" with a night resupply of Class V to Dak To. They lifted 18,000 lbs of Class V in 3 sorties. The mission was conducted with no incidents and negative contact.
- (7) 22 Nev 189th WH-10 gunship received four (4) hits from heavy enemy automatic fire in classified area. One (1) crew member WIA and aircraft continued to fly.
- (8) 22 Nov 170th WH-1H crashed in the vicinity of Dak To. Complete engine failure, and the autorotation was made into the trees. One (1) crew member sustained minor lacorations and a broken nose.
- (9) 23 Nov 119th conducted multiple CA's and Final Extraction in support of the 3/8 Inf, 4th Inf Div, in Spaatz AO. They lifted 360 pax in 117 sorties. Enemy small arms fire was received from the vicinity of the LZ (5 reported hits). Negative injuries and aircraft centinued to fly.
- (10) 23 Nov 119th WH-1H model aircraft received heavy enemy automatic weapons fire vicinity of Dak To. Aircraft sustained 8 13 hits and continued to fly. One (1) crew member WIA.

d. Operational Statistics:

CRT	OTHER. SOUTHIES	IIH-1H	TH-1C	CH-47A
SORTIES		Holms	HOIMS	HOURS
5,416	3,937	2,321	603	1 91
TOTAL	PAX	CARGO	A/C	A/C**
Hours		TONS	HIT	DAM/DEST
3,115	11,677	923	11	10/1
CROW MEM	KBV	STRUCT	MED	SORTIES DELAY
	EAEMÄ	DEST	EVACS	OR CXL FOR MX
7/1	11	0	353	11

Period 24 Nov 67 - 30 Nov 67

a. Weather:

Lower temperatures made a noticeable change in density altitude during this reporting period. Average highs were 74° of short duration (1100 - 1300). Morning and evening averaged 60 to 65 degrees. Density altitudes were lower throughout the day (4,250°). Ceiling conditions were lower, averaging 3,500° scattered, 8,000° broken. Total cloud cover average 5/10 covered throughout each day. There was no change in visibility (12 - 15 miles). Wind direction shifted slightly ENE (070° - 090°) at 5 - 10 knots.

b. Aircraft Allocation:

	<u>11H-1H</u>	11171C	<u>CF-471</u>
4th Inf Div -	22	10 .	5
ARVN - 52d Arty Gp -	1 1	5	0
Avn C&C -	5	Ô	Ö
Press Camp -	1	0	0
5th SFG -	2	0	0
Prairie Fire -	11	8	0
Co "E", 20th Inf -	2	0	0
DSA II Corps -	ક	0	0

c. Significant Events:

(1) 24 Nov - 119th conducted a CA in support of the 1/12 Inf, 4th Inf Div, along with the 170th, in the vicinity of HILL 875. 120 pax were assaulted onto the LZ in 23 sorties. Intense enemy anti-aircraft fire was received from all quadrants of the LZ. Two (2) aircraft were hit;

one by 8 rounds, the other by 10 rounds. One (1) crew member WIA.

- (2) 24 Nov 119th conducted a Final Extraction in support of 2/503d Abn Bn, 173d Abn Bde, from HILL 875. The extraction of 150 pax was made in 31 sorties. A heavy volume of enemy small arms, and automatic weapons fire was received from the area surrounding the P2.
- (3) 25 Nov 119th conducted multiple CA's and Extractions in support of 1/8 Inf, 3/8 Inf, and 3/12 Inf, 4th Inf Div. The operation took place in the vicinity of Dak To, moving over 610 pax in 226 sorties. Sporatic enemy resistance was encountered during the lift. Negative aircraft hits or injuries were reported.
- (4) 25 Nov 170th conducted a CA in support of the 3/12 Inf, 4th Inf Div, vicinity of Dak To. They lifted over 300 pax in 100 softens. Mission was conducted with no incidents and negative contact.
- (5) 25 Nov 155th UH-1H model aircraft crashed in the vicinity of ZA220890. Aircraft experienced a short shaft failure and entered autorotation. The ship landed in a field, hit a stump and rolled over. The crew and passengers experienced minor lacerations. Aircraft was recovered by the 179th ASHC.
- (6) 26 Nov 189th conducted three (3) night emergency medical evacuations in support of FOB-II. The evacuation took place in a classified area under intense enemy automatic weapons fire. One (1) UH-1H received several hits, wounding both the aircraft commander and pilot. The pilot maintained control of the aircraft and returned to Dak To.
- (7) 28 Nov 170th and 189th conducted multiple CA's and Final Extractions in support of 1/8 Inf, 1/12 Inf, 4th Inf Div, vicinity of Dak To. They lifted 846 pax in 429 sorties. One (1) UH-1H crashed in the bomb crater used for the LZ. There were negative injuries sustained by the crew and passengers. Enemy fire was received from all quadrants. Negative hits were reported.
- (8) 28 Nov 155th NH-1C received one (1) hit from enemy small arms fire, vicinity CRO55352. Negative injuries and aircraft continued to fly.
- (9) 28 Nov 179th conducted a Fire Base Move in support of the 3/12 Inf, 4th Inf Div, vicinity of Dak To. They lifted 439 pax and 151 cargo tons in 100 sorties. Mission was conducted with no incidents and negative contact.
- (10) 29 Nov 189th conducted a Final Extraction in support of 1st Bde, 4th Inf Div, vicinity of Dak To. They extracted 252 pax in 87 sorties. Mission was conducted with no incidents and negative contact.
 - (11) 29 Nov 155th conducted a CA in support of 22d ARVN

Div, vicinity of Cheo Reo. They assaulted 130 pax in 28 sorties. The mission was conducted with no incidents and negative contact.

(12) 30 Nov - 189th conducted a CA in support of 3/12 Inf, 4th Inf Div, vicinity of Dak To. They lifted 585 pax in 182 sorties. The Battalion Commander of the 3/12 Inf received a minor facial wound when his C&C aircraft came under enemy anti-aircraft fire: Negative injuries to crew and the aircraft continued to fly.

d. Operational Statistics:

OBT SORTIES	OTHER SORTIES	UH-1H HOURS	TIH-1C HOURS	CF-47A HOURS
6,994	3,784	2,797	701	254
TOTAL HOURS	PAX	C'RGO TONS	A/C HIT	D/C**
3 , 752	13,501	1,547	4	5/0
CREW MEM	KBA KBA	STRUCT DEST .	MED EV+CS	SORTIES DELAY OR CXL FOR WX
2/0	20	10	85	2

Period 1 Nov 67 - 30 Nov 67 TOTALS

CBT	OTHER	UP-1H	TH-1C	CH-47A
SORTIES	SOUTSOE	HOURS*	HOTIRG#	HOURS*
25,286	12,482	9,862	2,471	1,118
TOT'L	<u>PAT</u>	CARGO	A/C	A/C**
HOURS*		TONS	HIT ·	<u>DAM/DEST</u>
13,451	53,719	5,741	25	26/7
CREW MEM	<u>KBV</u>	STRUCT	MED	SORTIES DELAY
	ENUMA	DEST	EVACS	OR CXL FOR MX
23/2	4.3	30	1,003	49

^{*} Adjusted DA Yorm 1352 time.

^{**} Results of hostile fire and accidents.

Period 1 Dec 67 - 7 Dec 67

a. Weather:

On the 1st and 2nd very light showers were reported throughout the area of operations (1300 - 1500). Ground fog was reported in low valleys on the morning (0500) 5 Dec 67 that reduced visibility to 1/2 mile but dissipated by 0700. Total cloud cover was 6/10 with ceilings at 3,500 scattered, 6,000 - 8000' broken. Winds remained ENE 060° - 090° degrees at 5 - 10 knots. High density altitude averaged 4,400' each day from 1400 - 1500 hours.

b. Aircraft Allocation:

	<u> 11H-1H</u>	<u>UH-1C</u>	<u>CH-47A</u>
4th Inf Div - ARVN - 52d Arty Gp - DSA II Corps - Avn C&C - Press Camp - 5th SFG -	22 11 7 8 5 1 2	10 5 0 0 0	5000000
Prairie Fire - Co "E", 20th Inf - Avn Tng -	11 2 2	8 0 0	· 0 0

c. Significant Events:

- (1) 01 Dec 119th UH-1C received one (1) hit from enemy small arms fire in classified area. Negative injuries and aircraft continued to fly.
- (2) 02 Dec 179th conducted a night resupply mission in support of 1st Bde, 4th Inf Div, in Spaatz MO. They responded to the TAC-E with 17 sorties of Class V. Mission was conducted with no incidents and negative contact.
- (3) 02 Dec 170th conducted a CA in support of the 1/12 Inf, 4th Inf Div, in Spaatz AO. The assaulted 270 pax in 125 sorties. The flight received enemy small arms fire from the SE quadrant, but sustained no hits.
- (4) 03 Dec 155th conducted a CA in support of the 23d ARVN Div, vicinity of Bao Loc. They assaulted 80 pax in 45 sorties. The mission was conducted with no incidents and negative contact.
- (5) 04 Dec 155th conducted a CA in support of the 23d ARVN Div, vicinity of Phan Rang. They assaulted 58 pax in 35 sorties. The mission was conducted with no incidents and negative contact.

- (6) 04 Dec 170th conducted a CA in support of the 3/8 Inf, 4th Inf Div, in Spactz AO. They lifted 160 pax in 30 sorties. Mission was conducted with no incidents and negative contact.
- (7) 05 Dec 119th UH-1C received one (1) hit from enemy small arms fire in classified area. Wegative Injuries and the aircraft continued to fly.
- (8) 06 Dec 189th conducted a CA in support of the 1/8 Inf, 4th Inf Div, in Sphatz AO. They lifted over 255 pax in 45 sorties. The mission was conducted with no incidents and negative contact.
- (9) 06 Dec 170th WH-1H model aircraft crashed in vicinity of XP13P315. Aircraft lost RPM on termination of an approach, turned 360°, and southed onto slope. Main rotor blade hit a tree and separated from the narroralt, the nirraft then rolled inverted. One (1) ARVN KIA and two (2) other WIA. Negative injuries to crev

d. Operational Statistics:

CBT SORTIES	other sorttes	HOURS	TH-1C HOURS	CH-47A HOURS
6,249	3,818	2,201	775	253
TOTAL HOURS	<u>PAX</u>	CARGO TOVS	A/C HTT	A/C** DAM/DEST
3,229	14,929	1,630	12	2/0
CREW MEM	KBV	STRUCT DEST	EVACS	SORTIES DELAY OR CXL FOR WX
0/0	14	5	73	7

Period 8 Dec 67 - 14 Dec 67

a. Weather:

Weather summary for this reporting period indicated a slight increase in total sky cover, 8/10 covered at 2,500' scattered to broken with a high partial obscuration on 9, 11, 12, and 14 December. Visibility averaged 10 miles with HK as the only obstruction to vision. Light rain was encountered on the mornings of 8, 11, and 12 December with 30 minutes duration throughout the area of operations. Wind remained out of the ENE (070° - 090°) but increased in velocity to 10 - 15 knots gusting to 25 knots. Temperatures remained cool during nights and early mornings (58° - 65°) increasing throughout each day to average 73° - 75°. Density altitude decreased to average a daily high of 3,800°.

91

CUNFIDENTIAL

b. Aircraft Allocation:

	<u> 11H-1H</u>	<u> 11H-10</u>	<u>CH-471.</u>
4th Inf Div -	26	à	7 .
ARVN -	10	4	0
52d Arty Gp -	1	Ú	0
DSA II Corps -	10	0	0
Avn C&C -	5	0	Ö
Pross Comp -	*	Ö	0.
5th SFG -	3	0	0
Prairie Fire -	11	8	Q
Co "E", 20th Inf -	4	2 .	O.

Significant Events:

- (1) 98 Dec 119th WF-10 model aircraft received one (1) hit from enemy small arms fire, in a classified area. Negative injuries and the aircraft continued to fly.
- (2) 09 Dec 170th conducted a CA in support of the 1/12 Inf, 4th Inf Div, in Spaatz AO. They lifted 240 pax in 49 sorties. The mission was conducted with no incidents and negative contact.
- (3) 10 Doc 155th MP-1H model aircraft had a forced landing in the vicinity of AQ839115. The ensine failed and the aircraft autoretation was made into an open field: Negative injuries and only minor demage to aircraft
- (4) 10 Doc 170th conducted a C1 in support of the 1/8 Inf, 4th Inf Div, in Spantz 10. They lifted 121 pex in 35 sorties. The mission was conducted with no incidents and negative contact.
- (5) 10 Doc 155th UP-1H model nircraft received two (2) hits from enemy automatic wepons fire, vicinity VB170270. Wegative injruies and the aircraft continued to fly.
- (6) 12 Dec 119th conducted a CA in support of FOB-II into a classified area. Intense enemy anti-aircraft fire was encountered with the following results:
 - 3 TF-1H models damaged
 - 1 TH-10 model damaged
 - 1 WH-1W model dostroyed
 - . 1 WH-10 model destroyed

Heavy enemy contact hampered rescue efforts. One (1) crow member was WIA.

(7) 13 Dec - 170th conducted a C1 in support of the 5th SEG, CIDG Force, vicinity of YA669551. They lifted 121 pax in 77 sorties. The

mission was conducted with no incidents and negative contact.

- (8) 13 Dec 119th WH-1W model aircraft received two (2) hits from heavy enemy automatic weapons fire, in a classified area. Negative injuries and the aircraft continued to fly. In addition, one (1) WH-1C model took one (1) 50 cal. round. Negative injuries and the aircraft continued to fly.
- (9) 14 Dec 119th and 170th had three (3) WH-10 model aircraft shot-up by heavy enemy automatic weapons fire, in a classified area. One (1) crew member was WIA and all aircraft continued to fly.
- (10) 14 Dec 189th WH-1H model aircraft was hit by enemy automatic weapons fire. Negative injuries and the aircraft continued to fly.

c, Operational Statistics:

CBT	OTHER	TH-1H HOURS	UH-1C	CH-47A
SOUTTES	SORTIES		HOURS	HOURS
7,1779	4,374	2 , 352 .	637	362
TOTAL.	<u>PAX</u>	CARGO	A/C	A/C**
HOURS		TONS	HIT	DAM/DEST
3;351	15,312	2,068	14	12/2
CREW MEM	ENEMY	STRUCT	MED	SORTIES DELAY
	KBA	DEST	EVACS	OR CXL FOR WX
2/0	11	21	39	4

Period 15 Dec 67 - 21 Dec 67

a. Weather:

Sky conditions improved during this period, especially night conditions. Total cloud cover averaged 4/10 covered at 3,500' scattered high broken. At night clear sky prevailed. Visibility increased 12 - 15 miles. 20 Dec proved to be the only exception with 1/2 mile visibility from 0200 - 0600 throughout the area of operations because of ground fog. Definite wind change was observed with a marked decrease in speed, 010° - 030° at 3 - '7 knots. There were no changes in daily temperatures and duration (averages, early mornings 53° - 60°, mid-afternoon 73° - 78°). Density altitude increased to highs of 4,100°.

48

CONFIDENTIAL

b. Aircraft Allocation:

	<u>1111-1 H</u>	TH-1C	<u>CH-47A</u>
4th Inf Div -	25	6	7
ARVN -	9	7	0
52d Arty Gp -	1	0	0
DSA II Corps -	10	Ċ	0
Avn C&C -	3	0	0
Press Camp -	1	0	O
5th SFG -	2	0	0
Frairie Fire -	11	8	0
Co "E", 20th Inf -	4	2	0

c. Significant Events:

- (1) 16 Dec 170th UP-1H model aircraft crashed in vicinity of NE935186. Aircraft took off to the North and failed to clear barriers. The ship crashed into an area with 2001 trees; killing three (3) and wounding three (3) crew members. Aircraft was a total loss.
- (2) 16 Dec 119th two (2) TH-1H model aircraft received five (5) hits from enemy automatic weapons fire, in a classified area. Negative injuries to crew and the aircraft continued to fly.
- (3) 17 Dec 170th conducted a CA in support of the 1/503d Abn, 173d Abn Bdo, vicinity of Dak To. They lifted 120 pax in 96 sorties. The mission was conducted with no incidents and negative contact.
- (4) 20 Doc 189th WH-1H model aircraft crashed and burned, vicinity of Dak To. Two (2) crew members were KIA and the other two (2) were WIA. Aircraft burned and was a total loss.
- (5) 21 Dec 119th had three (3) UF-1H model aircraft shot-up in a classified area. Each ship took one (1) round. One (1) crew member was WIA.
- (6) 21 Dec 189th TH-10 model aircraft crashed at Polie Kling AAF. Negative injuries and the aircraft was a total loss. One (1) U.S. was KIA by flying schapnel from the crash.

d. Operational Statistics:

CBT	OTHER	HOURS	TIH-10	CH-47A
SORT TES	SORTIES		HOTERS	HOURS
7,383	3,638	2,280	535	2.89

49

TOTAL HOURS	PAX	CARGO TOVS,	A/C HIT	DAM/DEST -
3,104	14,260	2,153	5	5/3
CREW MEM	ENEMY KBA	DEST DEST	MED MED	OR CXL FOR WX
7/3	10	9	34	5

Period 22 Dec 67 - 28 Dec 67

a. Weather:

Cloud cover averaged 2/10, 4,000' scattered. Visibility remained at 12 - 15 miles. Winds increased in velocity 10 - 14 knots out of the ENE 080° - 110°. Higher temperatures caused a smaller temperature - dew point separation (79° temp - 65° dew point), and resulted in a high daily average density sltitude of 4,300'.

b. Aircraft Allocation:

<u> 1111–114</u>	<u> 11H-1C</u>	CH-47A
22	9	7
	4	0
	0	0
3	Ô	Ō
1	0	0
	. <u>0</u>	0
2	8 0	0
	22 10 2 10 3 1 2	22 9 10 4 2 0 10 0 3 0 1 0 2 0 11 8

c. Significant Events:

- (1) 24 Dec Notified of arrival of 73 cargo tons for the 355th ASHC (CH-54A). The equipment arrived by the USNS Kenyon Victory at Qui Nhon, RVN.
- (2) 25 Dec 170th UP-1F model aircraft received several hits from an enemy B-40 rocket, vicinity YB799110. Megative injuries and aircraft continued to fly.
- (3) 26 Dec 170th conducted a CA in support of 1/22 Inf, 4th Inf Div, in Spartz AO. They lifted 118 par in 30 sorties. The mission was conducted with no incidents and negative contact.
- (4) 27 Dec 189th conducted a C.1 in support of the 2/503d Abn, 173d Abn Ede, vicinity of Fontum. They lifted 252 pax in 42 sorties.

20

The mission was conducted with no incidents and negative contact.

- (5) 28 Dec 189th conducted a CA in support of the 1/503d Abn, 173d Abn Bde, vicinity of Kontum. They lifted 120 pax in 20 sorties. The mission was conducted with no incidents and negative contact.
- (6) 28 Dec 170th conducted a CA in support of the 3/8 Inf, 4th Inf Div, in Spaatz AO. They lifted 209 pax in 198 sorties. The mission was conducted with no incidents and negative contact.

d. Operational Statistics:

OBT	OTHER	HOURS	TH-1C	CH-47A
SOMTIES	SORTIES		HOURS	FOURS
7,013	4,053	2,181	584	283
TOTAL	PAX	CARGO	A/C	A/C**
Parks		TONS	HIT	D*M/DEST
3,048	15,159	1,857	1	1/0
CREW 1 IM	ENEMY	STRUCT	MED	SORTIES DELAY
	I'B'	DEST	EVACS	OR CYL FOR MX
0/0	18	20 ·	45	0

Period 29 Dec 67 - 31 Dec 67

a. Weather:

Gloud cover average 5/10 cover during this reporting period; 3,500 scattered, high thin broken. Night flying weather continued clear. Visibility averaged 12 - 15 miles daily with the following exception; 0400 - 0800 hours ground fog throughout the area of operations. Winds continued out of the NE (040° - 090°) at 5-10 knots. Temperatures increased to an average high of 77°. Density altitude averaged a high of 3,850°.

b. Aircraft Allocation:

	<u>1114-1 H</u>	TTH+1C	<u>CH-4.71</u>
4th Inf Div -	21	10	6
ARVN -	10	5	O
52d Arty %p -	3	0	0
DSA II Corps -	1 0	Ò	0
Avn 08:0 -	3	0	n
Press Camp -	1	0	0
5th SFG -	2	0	0
Prairie Fire -	11	8	0
Co "E", 20th Inf -	2	. 0	0

CONFICENTILL

c. Significant Evonts:

- (1) 29 Doc 189th conducted a CA in support of the 3/12 Inf, 4th Inf Div, in Sphatz AO. They lifted 120 pax in 24 sorties. Enemy small arms fire was received from the SM quadrant of LZ. One (1) 114-10 gunship sustained one (1) hit, with negative injuries to crow.
- (2) 29 Dec 189th conducted a CA in support of the 6th ARVN Abn Bn, vicinity of Dak To. They lifted 352 pax in 44 sorties. The mission was conducted with no incidents and negative contact.
- (3) 30 Doc 170th conducted a CA in support of the 6th ARVY Abn Bn, wholmaty of Dak To. They lifted 126 pax in 48 sortios. The mission was conducted with no incidents and negative contact.
- (4) 30 Dec 170th conducted a CA in support of the 3/12 Inf, 4th Inf Div. in Speatz AO. They lifted 310 pex in 175 sortios. The mission was conducted with no incidents and negrtive contact.
- (5) 31 Dec 189th conducted a C' in support of 3/12 Inf, 4th Inf Div, in Spantz AO. They lifted 150 pax in 50 sorties. The mission was conducted with no incidents and negative contact.
- (6) 31 Dec 119th had two (2) UH-10 models and one (1) UH-1H model receive three (3) hits from enemy small arms fire in a classified area. Two (2) crew members were WIA.

d. Operational Statistics:

CET SORTIES	OTHER SORTIES	TIH-1H HOTES	77-10 170175	CH-47A HOTES
3,127	1,386	917	206	98
TOT L Hours	<u>P\X</u>	CARGO TOMS	i./C ·	^/o## <u>ኮሴተ/ኮክኖዊ</u>
1,221	6,532	601	4	4/0
CREW MEM	ENERTY KBA	STRUCT DEST	TED TWAGS	SORTIES DELAY OR CXL FOR WX
2/0	0	0	. 24	0

52

Period 1 Dec 67 - 31 Dec 67 TOTALS

CBT	OTHER	UH-1H	TIH-1C	CH-47A
SORTIES	SORTIES	HOURS*	HOURS*	HOURS*
31,551	17,269	10,528	2,653	1,305
TOTAL	PAX	CARGO	/c	\/C**
HOURS*		TOMS	hit	DAM/DEST
14,486	66,192	8,309	26	25/5
CREW MEM	KBV	STRUCT	MED	SORTIES DELAY
	ENEMA	DEST	EVACS	OR CXL FOR WX
11/3	53	55	215	9

Period 1 Jan 68 - 4 Jan 68

a. Weather:

Cloud cover averaged 4/10 cover during this reporting period; 3,500' scattered, high thin broken. Night flying weather continued clear. Excellent visibility (12 - 15 miles) throughout the period. Winds were NNE at 5 - 10 knots, occasional gusts to 20 knots. Temperatures increased to an average high of 77°. Density altitude averaged 3,850°.

b. Aircraft Allocation:

	11H-1H	<u>1774-10</u>	СН-47Л
4th Inf Div -	20	9	7
VLAN -	8	5	0
52d Arty Gp -	1	0	0
DSA II Corps -	10	1	O
Avn C&C -	2	C	0
Press Camp -	1	0	0
5th SFG 🗝	2.	0	0
Prairie Fire -	11	8	0
Co "E", 20th Inf -	2	0	0

c. Significant Events:

(1) 03 Jan - 170th conducted multiple CA's in support of the 1/8 & 3/8 Inf, 4th Inf Div, in Spaatz AO. They lifted over 408 pax in 115 sorties. The mission was conducted with no incidents and negative contact.

53

(2) 04 Jan - At approximately 0230 hours the Ban Me Thuot Airfield Complex came under an attack by a company size VC unit. The attack lasted approximately 30 minutes. The energy utilized 82mm mortars, B-40 rockets, sapper element and a unknown number of small arms. Approximately 25 - 30 rounds of mortar fire was received with negative US casualties. Ten (10) UF-1H models were damaged and two (2) were completely destroyed. One (1) fire truck was damaged and another destroyed.

d. Operational Statistics:

CBT	OTFER	HOUBS	HOURS	CF-47A
SORTIES	SORTIES	TH-1H		HOURS
3,075	2,173	1,046	202	172
TOTAL	<u>P^X</u>	CARGO	A/C	A/C**
101 MB		TOVS	FIT	DAM/DEST
1,420	8,007	1,117	Ō	10/2
CREW MEM	KBV	STRUCT	MED	SORTIES DELAY
	EMEMA	DEST	EVACS	OR CXL FOR WX
0/0	4	2.	10	0

Period 5 Jan 68 - 11 Jan 68

a. Meather:

Slightly lower cloud laver provailed throughout this reporting period at 5/10 covered, 3000° scattered variable broken. Visibility averaged 12-15 miles, except during fog conditions on 6 & 8 Jan at 1/2 mile during the hours 0500-0800. There was no significant wind change which remained $040^{\circ}-090^{\circ}$ at 8-10 knots. Tomogratures remained at an average of $78^{\circ}-82^{\circ}$ and dissipated later each day. Figh Density altitude was lower and of short duration (3,750).

b. Aircraft Allocation:

	117-111	<u> </u>	CH-47A
4th Inf Div -	20	. 9	7
ARVN -	8	. 5	0
52d Arty Gp -	1	0	0
DSA II Corps	10	1	O
Avn C&C -	2	0	Ō
Press Camp -	*	0	0
5th SFG -	2	0	0
Prairie Fire -	11	. 8	0
Co "E", 20th Inf -	2	n	0

c. Significant Events:

- (1) 05 Jan 170th conducted a Final Extraction in support of the 5th SFG. They extracted 31 pax in 12 sorties. The mission was conducted with no incidents and negative contact.
- (2) 05 Jan 57th WH-10 model aircraft received one (1) hit from heavy enemy automatic weapons fire. Negative injuries to crew and aircraft continued to fly. Aircraft was on a classified mission.
- (3) 06 Jan 119th VH-10 model aircraft received one (1) hit from heavy automatic weapons fire. The ship was on a armed escert mission in a classified area when hit. Megative injuries to crew and the aircraft pentiamed to fly.
- (4) 06 Jan 170th CH-47A model aircraft crashed in the vicinity of M158468. The aircraft was on final approach to a fire base, lost power and settled to the ground. Major damage to the aircraft with negative injuries to the crow or passengers.
- (5) 08 Jan 189th UP-18 model aircraft while running in a fire base (ZB206522) received extensive main retor damage. An Infantry detail working at the fire base cut a tree down and it fell into the turning blades. The aircraft was recovered and no injuries to the crew.
- (6) 09 Jan 170th conducted a CA in support of the Capital Republic of Korea Division in the vicinity of BR804367. They assaulted with 224 pax in 40 sorties. The mission was conducted with no incidents and negative contact.
- (7) 10 Jan 57th AFC and Kontum 'irfield came under heavy enemy attack at approximately 0200 hours. The NVA used mortars, B-40 rockets, stachel charges and heavy small arms fire. The contact lasted approximately 7 8 minutes, resulting in; six (6) US KIA, 20 VII, 2 VF-1H destroyed, 2 UH-1C destroyed, 2 UF-1H major damage, 7 UH-1H and 2 UH-1C moderate damage. Member of the 57th AHC close with, and killed a Morth Vietnamese. An additional five (5) NVA were killed by B Troop, 2/1 CAV.
- (8) 10 Jan 189th conducted a CA and Final Extraction in support of the 1/12 Inf, 4th Inf Div, vicinity of ZA885788. They lifted 254 pax in 42 sorties. The mission was conducted with no incidents and negative contact.
- (9) 10 Jan 189th WH-1F model aircraft crashed in the vicinity of AR884796. Major damage to the aircraft with negative injuries to crow.
- (10) 10 Jan 189th conducted a CA and Final Extraction in support of 2/503 Abn, 173d Abn Bde, in the vicinity of Ventum. They lifted 252 pax in 40 sorties. The mission was conducted with no incidents and negative contact.

(11) 11 Jan - 57th top (1) The Lord - I direct word fired upon in the vicinity of ZA185013. The (1) ship week one (1) hit and continued to fly. Megative injuries to crew.

d. Operational Statistics:

CRT	OTHER	TH-1H	HOURS	07-474
SORTIES	SORTIES	HOURS		HOURS
6,230	3,731	2,325	860	265
TOTAL	<u> XX4</u>	CARGO	v <u>íl</u>	1/C**
HOURS		TONS	V\C	DAM/DEST
3.450	12,948	1,886	3	17/4
CREW MEM	ENELY	STRUCT	EATOS	SORTIES DELAY
	KBA	DEST	Mad	OR CXI, FOR WX
0/0	11	23	65	<i>L</i> ₁ .

Poriod 12 Jan 68 - 18 Jan 68

a. Weather:

cloud cover remained 3/10 covered at 3,500 scattered, variable thin broken. 10 - 15 miles vicibility prevailed daily except 13 Jan, with dense ground fog through the area of operation; especially in the valleys of the mountainous terrain. Minds remained calm during early morning hours with low temperatures dissipating later each morning. Winds increased in late afternoon to remain steady at 10 - 15 knots with frequent gust to 20 - 25 knots. Daily high temperature occured later each day to average 73° - 77°. Density altitude remained 3,750°.

b. Aircraft Allocation:

	<u>1111-111</u>	1111-1C	<u>CH-471</u>
4th Inf Div -	18	7	5
ARVN -	16	.5	0
52d Arty Gp -	1	. 0	()
DSA II Corps -	10	Ü	0
Avn C&C -	3	0	0
Pross Camp -	0	n	.0
5th SEG + ·	1	\cap	Ō.
Prairio Fire -	11	8	<u>`</u> √ ∩
Co "E", 20th Inf -	1	0	0
CRID -	1	0	0

c. Significant Events:

- (1) 12 Jan 189th conducted a series of Combat Asserts and Extractions in support of the 3/8 and 1/8 Inf, 4th Inf Div, in Spaatz AO. They lifted 777 pax in 139 serties. The Flight received moderate enemy-automatic weapons-fire in the vicinity-of-FB910120. 179th UH-1H model aircraft, assisting in the lift, sustained one (1) hit with negative injuries to crew. The aircraft continued to fly.
- \ (2) 13 Jan 170th conducted multiple CA's and Final Extractions in support of 3/12 Inf, 4th Inf Div, in Spartz AO. They lifted over 420 rex in 228 serties. The mission was conducted with no incidents and negative contact.
- (3) 14 Jan 189th conducted multiple CA's and Extractions in support of the 1/8 and 3/12 Inf, 4th Inf Div, in Spantz AO. They lifted 256 pax in 43 sorties. The mission was conducted with no incidents and negative contact.
- (4) 14 Jan 170th conducted multiple CA's and Extractions in support of the 1/503 Abn, 173d Abn Bdo, in the vicinity of Kontum. They lifted over 380 pax in 216 sorties. The mission was conducted with no incidents and negative contact.
- (5) 15 Jan 170th conducted a CA and Final Extraction in support of the 3/8 Inf, 4th Inf Div, in Spaatz AC. They lifted over 240 pax in 40 serties. Three (3) WH-10 model aircreft escerting the the mission sustained several hits from intense enomy automatic weapons fire. Negative injuries to crew and the aircraft continued to fly.
- (6) 15 Jan 170th WI-1H model aircraft crashed and burned in the vicinity of ZB185110. The aircraft landed with toes of skids on an upslope, when the tail reter disintegrated. Heavy enemy contact was reported in the vicinity of the LZ. Aircraft rolled ento armunitions stores and emploded. One (1) crew member KTA, no other injuries were reported.
- (7) 16 Jan 179th conducted multiple Fire Base Moves in support of 1st Bde, 4th Inf Div, in Spantz AO. They lifted 144 pax and 85 cargo tens in 60 sertics. The Dission was conducted with negative incidents and no contact.
- (8) 17 Jan 170th conducted a CA and Final Extraction in support of 1/8 Inf, 4th Inf Div, in Spaatz AO. They lifted 330 pax in 165 sertios. The mission was conducted with no incidents and negative contact.
- (°) 17 Jan 179th conducted a Fire Base Move in support of 1/12 Inf, 4th Inf Div, in the vicinity of ZAO36625. They lifted 14 pax and 43 cargo tons in 29 sorties. The mission was conducted with no incidents and negative contact.

CONFIDENTIAL

lo

(10) 17 Jan - 155th and Dan Mc Threat Limitally over under attack at approximately 0125 hours. The energy used 82mm Lorters. U.S. losses: Five (5) UH-1H damaged, and no U.S. WIA or KIL. Energ Esses: Unknown.

(11) 18 Jan - 189th conducted a UA and Final Extraction in support of the 1/503 Abn, 173d Abn Bdo, in the vicinity of Kontum. They lifted 478 pax in 158 serties. The mission was conducted with no incidents and negative contact.

(12) 18 Jan - 170th conducted a Final Extraction in support of the 1/8 Inf, 4th Inf Div, in Spaatz 10. They extracted 330 pax in 168 socies. They conducted the mission with no incidents and negative contact.

d. Operational Statistics:

CBT SORITES	OTHER SORTIES	UH-TH HOURS	TTH-10 HOTTRS	CP-47A HOURS
7,345	2 , 660	1,958	548	287
TOTAL HOURS	<u>PAX</u>	CARGO TOMS	V/C	A/C** DAM/DEST
2,793	14,403	1,696	4	9/1
CREW MEM	EMEMY KBA	STRUCT DEST	MED Evics	SORTIES DELAY OF CXL FOR VX
0/1	9	0	11	0

Period 19 Jan 68 - 25 Jan 68

a. Woather:

Total sky cover averaged 5/10 cover. 3000' - 3500' scattered variable thin broken. Clear nights with calm wind conditions, caused fog to provail 0400 - 0800 on 19, 20, 21, and 24 Jan. Light rain showers were encountered throughout the area of operation on 1700 - 1900, 18 Jan. Visibility remained constant each day 10 - 15 miles, except during fog conditions (1/4 - 2 miles). Winds shifted NNE 020° - 080° and increased in volocity 10 - 15 later each afternoon. Temperatures - dew point conducive to fog existed later each day (0400 - 0800). Daily high temperatures averaged 70° - 73°. Density altitude increased to 4,175'.

b. Mireraft Allocation:

	<u>1111-111</u>	<u> 11H-1C</u>	<u>C11-471</u>
4th Inf Piv -	20	3	4
ARVN -	ક	3	0
52d Arby Gp -	1	0	0
DSA II Corps -	10 .	0	0
Avn C&C -	2.	0	ŋ
Press Camp -	1	0	0
5th SFG -	5	0	C
Prairie Fire -	11	8	0 .
Uo "E", 26th Inf -	1	0	0
CRID -	1	0	0

3. Significant Events:

- (1) 19 Jan 170th conducted a CA in support of the 2/503 Abn, 173d Abn Ede. in the vicinity of ZAO29625. They lifted 272 pax in 92 sorties, the (1) UH-1H model aircraft received one (1) hit from enemy small arms fire. Negative injuries and the aircraft continued to fly.
- (2) 20 Jan 179th conducted a Fire Rase Move in support of the 173d Abn Bde, in the vicinity of ZAO768. They moved 384 pax and 68 cargo tens in 65 sorties. The mission was conducted with no incidents and negative contact.
- (3) 20 Jan 189th conducted a CA and Extraction in support of the 2/503d Abn, 173d Abn Bdo, vicinity of ZA108680. They lifted 369 pax in 62 sorties. The mission was conducted with no incidents and negative contact.
- (4) 21 Jan 170th conducted multiple CA's in support of 1/12 Inf, 4th Inf Div, vicinity of YA964474. They lifted 244 pax in 132 sorties. The mission was conducted with no incidents and negative contact.
- (5) 21 Jan 179th conducted a Fire Base Move in support of 1/12 Inf, 4th Inf Div, vicinity of YA860540. They moved 171 pax and 40 cargo tens in 41 sorties. The mission was conducted with no incidents and negotive contact.
- (6) 21 Jan 155th WW-1M model aircraft crashed in the vicinity of Gia Nghia airfield. The aircraft went IFR from dust off the end of the dirt strip; main reter contacted ground on right side. The aircraft sustained rajor damage and negative injuries.
- (7) 23 Jan 189th conducted multiple CA's in support of the 173d Abn Bde, vicinity of ZA132570. They assaulted with 380 pax in 68 sorties. The mission was conducted with no incidents and negative contact.

- (8) 23 Jan 179th conducted a Pirc Base leve in sumport of the 173d Abn Bde. They moved 36 pax and 37 carse tens in 24 sorties. The mission was conducted with no incidents and negative contact.
- (9) 24 Jan 170th conducted a CA in support of the 1/22 Inf, 4th Inf Div, vicinity of 7A222678. They lifted 366 par in 90 sorties. The mission was conducted with no incidents and negative contact.
- (10) 24 Jan 189th conducted a CA and Final Extraction in support of the 1/503 Abn, 173d Abn Bdo, vicinity of ZA143483. They lifted 117 pax in 20 sorties. The mission was conducted with no incidents and negative contact.
- (11) 25 Jan 170th conducted multiple CA's in support of the 3/8 and 3/12 Thf, 4th Inf Div, in Sphatz AO. They lifted 360 pax in 66 serties. The mission was conducted with no incidents and negative contact.

d. operational Statistics:

	GET SOFITES	OTHER SORTIES	THE THE FOURS	HOURS	CH-47A HOURS
	6,589	2,890	1,920	487	210
•	TOT/L HOURS	<u>P/X</u>	GARGO TONS	A/C FIT	^/C** <u>DAM/DFST</u>
	2,617	11,551	1,216	1	2/0
	CREW MEM INJ/K**	ENEMY KBA	STRUCT DEST	MED EVACS	SORTIES DELAY OR CXL FOR MX
	0/0	Ō	0	72	0

Period 26 Jan 68 - 31 Jan 68

a. Weather:

Total sky cover averaged 6/10. 3,500' - 4000' scattered variable thin broken. Forning ground fog prevailed, causing some delay in early take-offs. Late afternoon rain showers occurred over the entire area of operation. Winds were generally out of the ENE at 5 - 10 knots, gusting occasionally to 20 knots. Temperatures ranged from 72° - 76° and the density altitude increased to 4,350'.

60

b. Mireraft Mlocation:

	<u> 114-14</u>	1TH-10	CH-47'
4th Inf Div -	19	4	5
138AM =	٥	4	0
52d Arty Gp	1	0	n
DSA II Corps -	9	0	0
Lvn C&C	2	n	0
Pross Camp -	7	0	0
5th SFG -	1	O	0
Prairic Fire -	10	7	0
Co "E", 20th Inf -	0	0	0

c. Significant Events:

- (1) 26 Jan At approximately 0230 hours, Camp Holloway came under attack. The initial attack came when sappers penetrated the 28th 565 Bn perimeter, slipped by W.S. personnel on Guard, and planted satchel charges in and around the ISP area. Initial knowledge of enemy in the area came as the enemy were leaving the perimeter, when either a flare was fired by a VC, initiating the mortar attack (one M-26 chicom flare pistol was found approximately 10 feet behind one VC VIA within the perimeter) or a flare tripped by a VC retreating through the perimeter. The sappers left charges in the 28th SAS Bn Class I, II, and IV vards and one amunition pad. The mortar attack was initiated at 0245 hours against the 52d Cbt Avn Bn and the 215th Avn Co. An estamated 110 120 82mm mortar rounds fell in the vicinity of the aircraft parking ramps. The attack was broken at approximately 0320 hours local. Results friendly: 40 W.S. WIA, 24 aircraft damaged, 3 major, 21 minor. VC losses: 1 KIA, 1 WIA captured by 52d Security Detachment.
- (2) 26 Jan 170th conducted a C1 in support of the 64th ARVN RNG Bn, vicinity of YB881312. They lifted 500 pax in 188 sorties. The mission was conducted with no incidents and negative contact.
- (3) 26 Jan 179th conducted a Fire Base Move in support of 1/12 Inf, 4th Inf Div, in Sphatz 10. They moved 40 pax and 34 cargo tons in 23 sorties. Mission was conducted with no incidents and negative contact.
- (4) 26 Jan 189th and 57th W-10 model muships (3) received 12 hits from intense enemy automatic weapons fire, in a classified area. Negative injuries to crew and aircraft continued to fly.
- (5) 28 Jan 189th conducted multiple CA's and Extraction in support of the 3/8 and 1/8 Inf, 4th Inf Div, in Spaatz AO. They lifted 610 pax in 200 sorties. Some enemy small arms and automatic weapons fire was received, but no hits were sustained.
 - (6) 29 Jan 170th conducted a CA in support of the ARVN,

C V5869006 That 31 that 323 is a in 120 good to a little manual.

vicinity of YAV69006. They differ 323 to min 139 conties. The mission was conducted with no incidents and regulate conducted.

- (7) 30 Jan At approximately 0305 hours all write and associated airlields of this battalion came under a heavy coordinated energy attack. The attack on Followay Lasted 30 35 minutes. The attack on Ban Fo Thuot and Fonton, RVN, continued through the night.
- (8) 31 Jan Attacks on Foutum and Ban Ne Thuot continue. The energy continues with heavy mortar and rocket attacks, followed by human wave assaults. Both the perimeters have held. Friendly and energy losses undetermined at this time.
- (A detailed report on these attacks will be inclosed to this report).

d. Operational Statistics:

CBT SORTIES	OTHER COUTTES	PH-1H ROURS	THE-10 HOURS	CF-47A HCTES
5,243	2,,023	1,355	432	203
TOTAL HOURS	PAX	CARGO TONS	A/C FIT	A/C** Dam/dest
1,990	8,450	1,415	3	40/3
CRIEW MEM	ETEMY	STRICT DEST	MED EWACS	SORTIES DELLY OR CXL FOR MX
3/0	97	55	130	O

Period 1 Jan 68 - 31 Jan 68 TOTALS

CBT SORTIES	OTHER SORTIES	HOURS*	TU-10 HOTINS*	CH-47A HOURS*
28,482	13,477	9,001	2,403	1,174.
TOT^I. HOURS*	<u>P^X</u>	CARGO FOMS	A/C HIT	D:M\DESL V\C**
12,578	55,359	7,330	11	78/10
CREW MEM INJ/K**	KBV	DHST STRUCT	MID BVACS	SORTIES DELAY OR CXL FOR WX
3/1	121	82	288	4

62

59

CONFIDENTIAL DEPARTMENT OF THE ARMY

HEADQUARTERS, 52D COMBAT AVIATION BATTALION APO San Francisco 96318 "FLYING DRAGONS"

AVGD-CC

10 December 1967

SUBJECT: After Action Report, Operation MAC ARTHUR (AO SPAATZ), 25 Oc-

tober - 30 November 1967

TO:

See Distribution

1. (C) GEMERAL: This report covers Operation MAC ARTHUR (AO SPAATZ) in the vicinity of DAK TO, Kontum Province, Republic of Vietnam, for the period 25 October - 30 November 1967.

a. Command Headquarters. The command headquarters, from the standpoint of aviation operations, was the 17th Combat Aviation Group.

b. Mission. The mission of the 52d topoat Aviation Battalion (FLYING DRAGONS) was to provide aviation support to the 1st Brigade, 4th Infantry Division and it's attached and supporting elements within the confines of AO SPAITZ (see incloseure 1).

c. Participating Units.

(1) Units organic to the 52d Combat Aviation Battalion, commanded by LTC Edward P Lukert Jr, which participated in Operation MAC ARTHUR, are as follows:

Hoadquarters, 52d Combat Aviation Battalion 57th Assault Helicopter Company 119th Assault Helicopter Company (-) 170th Assault Helicopter Company 189th Assault Helicopter Company (-) 179th Assault Support Helicopter Company

(2) Supporting detachments organic to units in paragraph lc(1), which supported the operation, were:

545th Transportation Detachment 70th Signal Detachment 94th Medical Detachment 405th Transportation Detachment 448th Signal Detachment 755th Medical Detachment 402nd Transportation Detachment 604th Transportation Detachment

(MANA THE TARREST

CONFIDENTIAL

SUBJECT: After Action Report, Operation MAC ARTHUR (AO SPAATZ), 25 Octobor - 30 November 1967

> 6th Signal Detachment 615th Transportation Detachment 822nd Signal Detachment

(3) Additional aviation support elements, CPCON to the 52d CAB during Operation NAC ARTHUR, were:

Gun Platoon, 192nd Assault Helicopter Company 180th Assault Support Helicopter Company 196th Assault Support Helicopter Company 213th Assault Support Helicopter Company 243rd Assault Support Helicopter Company

2. (C) INTELLIGENCE:

a. INTSUES partaining to Operation FLC ANTHUR were published as early as 15 October 1967, containing reports showing the build-up of enemy forces in propuration for the Battle of DAK TO. However, taken as they occurred, the reports were not significant until on or about 29 October when they began to indicate a pattern.

- (1) During the period 15-21 October, there were several reports of small arms fire directed at aircraft in an area 20 kilometers (km) northeast of DAK TO. TAN CANH City (4 km northeast of DAK TO) received 5 rounds of mortar fire.
- (2) 22-29 Getober, contact was made with an unidentified company size unit 8 km southeast of DAK TO. Heavy trail building activity was reported 30 km northwest of DAK TO. An agent reported that a 4000 man force would use the trails indicated to move into KCMTUN Province.
- (3) From 30-31 Octo, an agent reported the 24th NVA Regiment in an area 25 km northwest of DAK TO. A Special Forces vehicle hit a mine 12 km northwest of DAK TO.
- (4) During the period 1-7 November, several mines were detenated along Highway 14, between DAK TO and KONTUL City. Ground contacts took place daily in an area Most and South of DAM TO. The National Police reported extensive propaganda and anti-government lectures throughout KONTUL and PLETKU Provinces. They also reported plans to cut Highway 14 and hit KONTUL with rockets and mortars. NVA Sgt Vu Hung, 66th MVA Regiment, rallied at DAK KRI Village, near DAM TO. He gave locations and battle plans for the 66th, 32nd, 24th and 174th Regiments. He also montioned the 40th Heavy Artillery Regiment. These units were reported by Sgt Vu Hung to be deployed in the vicinity of DAK TO, and planned to recket DAK TO and KONTUL and overrun DAK TO.
- (5) From 8-14 November, savage fighting occurred in the DAK TO area, with almost continuous heavy contact. 8-10 November, contact centered 7-15 km westsouthwest of DAK TO. After the 10th, the heaviest concentration of activity was approximately 15-20 km westsouthwest of DAK TO.

1


CONFIDENTIAL

SWEJECT: After action Report, Operation NAC ARTER (AO SPANTZ), 15 October - 30 November 1967

- (6) On 15 November, the second phase of the DLK TO battle began. From 15-21 November, heavy contact continued. Enemy troops seemed to be well entrenched. Their objective seemed to be an attempt to inflict as many US casualties as possible, rather than attempting to over-run DLK TO itself. Units rentioned in paragraph 2a(4) had by now been confirmed in contact.
- (7) During the period 22-28 November, enemy activity decreased significantly. In what appeared to be an attampt to divert US Forces from D.H. TO, the enemy be an to increase ambush and harassing activities in the KOVIM City, PLESTAU area. KOVIM City was mortared on the 27th. The 32nd, 66th and 174th Regiments were badly mayled and attempted to pull back and regroup and resupply, with the 24th remaining in contact northeast of D.K. TO.

3. (C) OPERATIONS:

- a. The 52d CAB was the principle supporting aviation element during Operation NAC ARTHUR. The battalion's normal daily operational committment to the 4th Infantry Division was 22 UH-1Hs, 10 UH-1Cs and 7 CH-4/s, the majority of which was allocated to the 1st Brigade at DAK TO.
- b. Significant Events. A day-by-day account of significant events is listed below. Due to the heat of battle and the maximum effort required of the operation, only the most important events are recorded. Single ship operations and discollaneously missions will only be reflected in the overall statistics.
- (1) 25 October 67 170th Askault Helicoptor Company (AHC) participated in a combat assault (CA), lifting the 1/8th Inf and 1/82nd Inf, for a total of 550 passengers (PAX) and 150 sorties. 119th AHC moved a portion of the 1/12th Inf, totaling 54 PAX in 20 sorties.
- (2) 26 October 67 170th AFC conducted a CA, lifting the 1/Eth Inf, totaling 225 PAX and 143 sorties. 119th AHC conducted a final extraction for the 3/12th Inf, totaling 100 PAX.
- (3) 27 October 67 170th AHC conducted a CA for the 3/12th Inf, lifting 132 PAX in 40 sorties. 119th AHC conducted a CA, lifting 108 PAX; then conducted a final extraction for 3/8th Inf, totaling 261 PAX.
- (4) 28 October 67 170th AHC participated in a CA for the 1/8th Inf.
- (5) 30 October 67 170th AHC conducted a CA for 3/12th Inf, totaling 254 PAX in 158 sortios.
- (6) 31 October 67 170th AHC conducted a CA for ist Bde lifting 72 PAX in 45 sorties.



SUBJECT: After Action Report, Operation FLC MINITER (LC SPARTZ), 25 Catoher - 30 November 1907

- (7) 3 November 67 170th 270 conducted a CA for the 3/Eth Inf, lifting 254 P/X in 111 sorties; followed by 4 assaults for the 3/12th. totaling 249 PAK in 105 sorties. The 119th then assaulted with the 1/12th, airlisting 211 PAK.
- (E) 6 November 67 170th ABC conducted a CA for the 2/504th Abn, lifting 120 PAM in 65 sorties. Heavy encor fire was encountered in the landing zone (LZ). 1 FM-1F received 5 hits and 1 crewran was wounded.
- (9) 7 November 67 170th LHC participated in a CL for the 1st Fde.
- (10) 9 November 67 17 th AHC conducted a CA with the 3/Eth Inf, lifting 121 PAX in 54 sorties. Aircraft received light small arms fire approaching the LZ. As afreraft were departing the LZ, heavy morter fire was received. 1 WH-1H was hit and destroyed, wounding 1 crewran. The 177th them assembled with alcounts of the 3/8th Inf, lifting 162 PAX in 67 sorties. That sare day, the 119th lifted B/ 24th CIDG, totaling 130 PAX.
- (11) 10 November 67 119th AMC lifted a 4th Div olement, totaling 60 PAX. I TE-10 was shot down while providing covering
- (12) 11 Jovember 67 119th AMO conducted a CL for the 3/12th Inf, totaling 120 F/X.
- (13) 12 Tovember 67 129th ARS conducted a CA for the 1/8th Inf, lifting 130 P.X. Sniper fire was received in and around the Li with no stive results. The 1/9th, on the same lift, had 1 TH-1H bit by 2 rounds of scall arms fire, sustaining minor damage.
- (14) 13 November 67 119th AUC assaulted with Bland 6 Companies, 1/8th Inf, lifting 210 PMX and 4 additional sling loads. Sniper fire was received from 6 locations in and around the LZ, with negative results. On the same assault, the 170th had 1 TF-18 hit by rechet fire (B-49). The aircraft was destroyed and 4 crewen wounded.
- (15) 14 November 67 119th AEC conducted 2 CLs for the 3/6th Inf, totaling 450 PAX. Sniper fore was again received from all quadrants.
- (16) 15 November 67 170th ARC conducted 2 CAs with the ARVN is supjort of the 1st Bde. A total of 690 PAM were lifted in 164 sorthes. I TH-IH was hit by small arms fire and I crew member was wound-
- (17) 18 November 67 170th AFC participated in a 4th Inf Div CA.

- SUBJECT: After Action apport, Operation MAC ARTHUR (AO SPAATZ), 25 October 30 November 1967
- (18) 19 November 67 170th AHC participated in 4th Inf Div CA. 1 UH-1C was hit by small arms fire, sustaining only minor damage.
- (19) 22 November 67 170th AHC participated in a CA for the 4th Inf Div. The 119th assaulted with the 173rd Abn, lifting 120 PAX. 2 aircraft were hit by small arms fire without major damage.
- (20) 23 November 67 170th AHC participated in a CA for the 4th Inf Div. The 119th conducted an assault and final extraction for the 3/8th Inf, totaling 120 PAX. Another final extraction for the 3/12th Inf resulted in the movement of 240 PAX.
- (21) 24 November 67 170th and 119th AHCs conducted assaults with the 1/12th Inf, vicinity HILL 875. 120 PAX were moved. Automatic weapons fire was received from all quadrants of the LZ. 2 aircraft were hit; 1 by 8 rounds, the other by 10 rounds. 1 crew member was wounded. The 119th then made a final extraction for 2/503rd Abn from HILL 875. 150 PAX were extracted.
- (22) 25 November 67 119th AHC conducted an assault and final extraction for the 1/8th Inf, totaling 240 PAX and 10 sling loads. A final extraction was also executed for the 3/8th and 3/12th Inf with 370 PAX. Immediately following, the 170th assaulted with the 3/12th with 300 PAX in 100 sorties.
- (23) 26 November 67 189th AHC executed 3 night medical evacuatuins under emergency conditions.
- (24) 27 November 67 189th AMC moved 73 PAX and 1600 pounds of cargo for 4th Inf Div.
- (25) 28 November 67 170th AHC conducted a CA with the 1/8th Inf, moving 121 PAX in 58 sorties. The 1/12th Inf was then lifted, totaling 353 PAX in 183 sorties. The 189th also participated in this lift, moving 372 PAX. 1 UH-1H crashed in the LZ with negative injury to the crow.
- (26) 29 November 67 189th AHC conducted a final extraction and an assault, moving 252 PAX.
- (27) 30 November 67 189th AHC conducted another move, lifting 585 PAX. I aircraft received automatic weapons fire, suffering 1 hit with negative injury to the crew. However, the battalion commander of the 3/12th Inf received minor facial wounds from flying metal particles.
- c. Operational Statistics. The following is a resume of statistics amassed by the 52d CAB during Operation MAC ARTHUR. These totals do not include performances of these units attached or OPCON to the battalion during that operation.

1	
/	4

•	COMFIL	DEMTIAL	,
CBT	ucuna Trouna	CII-47	TOTAL
SORTIES	<u>HOURS</u>	<u> FOURS</u>	HOURS
17,563	6325	1225	7550
CBT	BTRY ·	TOTIL	CARGO
<u> aslts</u>	<u>MOVES</u>	<u>P.'X</u>	TONS
64	20	32,516	9075
MED	DELD	ENELY	1./C
EVACS	<u>EV/.CS</u>	KB/L	HITS
*720	*320	MMOMM	16
1./C	<i>i</i> /C	DOMA T\C	CREW 10EH
DIMMOED	DEST	RECOV: D	. INJ/KILL
24	3	**40	15 / 3
	MI'UNITION EXPENDED		
7.62mm	2.75mm	. LOmm	
577,900	3488	6329	

* Figures include ARVM evacuations.

** Figures include aircraft evacuated for the 335th Aslt Hol Co (attached to 173rd Abn Bdo and B/229th Avn Bn (attached to elements of 1st Cav Div).

4. (C) MAINTENANCE:

c. During the period 25 October - 30 November 1967, elements of the 52d CAB flew in excess of 10,000 hours, the majority of which were flown in support of the 1st Frigade, 4th Infantry Division, on Operation MAC ARTHUR. The elements involved performed 330 PAIs and 121 PEP inspections during that same period.

b. In and around D.K. TO, 40 aircraft were evacuated by the 179th Aslt Spt Hel Co. All of these aircraft had been demaged by enemy fire or due to operating in extreme confined areas. Nost of these aircraft were repairable, but may have been otherwise lost except for the professional competence of the 179th.

c. It required approximately 25,000 maintenance manhours to perform the inspections mentioned in paragraph 4e. Additionally, it took an estimated 25,000 maintenance manhours to perform unscheduled maintenance. Because of the shortage of maintenance personnel in critical skills, crews often worked around the clock to supply aircraft to meet operational requirements. Because of their efforts, the battalion was able to maintain throughout the operation an availability rate of 78.4% on UH-10s and 84.6% on UH-1Hs.



CONFIDENTIAL CONFIDENTIAL

SUBJECT: After Action sport. Operation FAC ARTHUR (AC MATZ), 25 October - 30 November 1967

5. (U) /WARDS AND DECORATIONS: The following recommendations for awards and decorations have been forwarded or are being prepared as a result of the Battle of DAK TO.

Silver Star	25
Distinguished Flying Cross	41
Bronze Star	13
Air Modal with "V" Dovice	74
Army Commondation Hodal	16
Purple Heert	18

- 6. (U) COMMANDER'S OBSERVATIONS, DISCUSSION AND RECOMMENDATIONS:
 - a. Landing Zones.
- (1) Observation and Discussion. During this operation, an increased rate of combat and operational damage was experienced in infantry battalion and company size landing zones. On several combat asscults bomb craters were used for landing zones. This situation, although extremely hazardous, was unavoidable due to the terrain and location of the energy. However, these same hazardous landing areas were used again and again with little or no improvement. In addition to the extremely small landing areas, trash in these landing zones doubled the risks to inconing aircraft. Loose ponehos, C-ration boxes and cans, as well as empty sandbags, were to be found in quantity in and around all landing zones. During this operation clone, this battalion replaced 38 main roter blades and 35 tail roter blades, the rajority of which were caused by flying debris. The incidents cited cost the government approximately \$123,500.
- (2) Recommendation. I recommend that commenders place increased emphasis on proper landing zone selection and preparation. The police of the area should be the responsibility of the individual within the infantry unit who is responsible for unit resupply by aircraft, and the clean-up program should be closely remitered.

b. Mircraft Utilization.

(1) Observations and Discussion. During the Battle of DIK TO, a misutilization of aircraft was experienced on a number of occasions. This was due primarily to inadequate plunning or a lack of sufficient planning time. On several occasions, mireraft were assembled from all ever II Corps for a priority lift when existing assets could have served the purpose, properly utilized. Communders failed to seek aviation advice during mission planning. Consequently, aviation supporting elements suffered. Mireraft would arrive on station, on time, only to find loads not ready for pickup or the intended delivery point had not been decided upon. Due to excessive idle time, critical blade time was expended, thereby reducing the aviation effectiveness during peak operational periods. Aviation requirements were constantly changed without warning, and using units had difficulty determining what night be needed two hours hence. The more aircraft allocated a unit, the more serties added on to

SUBJECT: After Action Report, Operation MAC ARTHUR (AO SPAATZ), 25 October - 30 November 1967

the existing requirements. Frequently, aircraft were extended to conduct emergency resupply at night, though these same aircraft may have remained idle for prolonged periods throughout the day. Whenever possible, missions should be given to the aircraft commander, not just a committment for a certain number of aircraft. This way full utilization of the aircraft can best be managed with maximum flexibility.

(2) Recommendation. Commanders of supported units should place increased emphasis on the need to make known their requirements as far in advance as possible, utilizing warning orders which should be issued to aviation units as well as to ground elements. If a combat assault is to be conducted at first light, the mission requirements should be made known early enough the day before to provide time for a daylight reconnaissance of landing zones, flight routes and pickup zones. Execution of immediate combat assaults should be kept to a minimum and ordered only in the case of a combat emergency. With adequate planning time, a greater aviation effort can be made with fewer aircraft.

c. Airfield Operations.

- (1) Observations and Discussion. A common practice of ground commanders is to establish their base of operations adjacent to the air facility serving the area. Of course, this is for convenience of the headquarters, as well as facilitating air support to forward elements. However, after a time, so many restrictions are placed on the aviation elements involved that it ceases to function as an aviation base of operations; and at times, air craft are forced to divert to alternate, poorly equipped areas to continue operations. The haphazard mixing of Air Force cargo aircraft, helicopters, light fixed-wing aircraft and LOHs, plus the lack of ramp space and inadequate refueling and rearming facilities, cause confusion and resulted in a distinct safety hazard during the Battale of DAK TO.
- (2) Recommendations. Extreme care should be exercised in the development of a small airfield into an adequate facility for supporting the various aviation elements required for a major operation. Priority engineer support must be allocated to build adequate parking ramps, dispersed POL points and rearming points. Consideration must be given to separating fixed-wing traffic and parking from helicopter traffic and parking. Right and left hand traffic patterns should be initiated. Also, hover lanes should be provided gunships, so that they may move to the runway for a running takeoff after refueling and rearming. A high priority should be given to dust control. Artillery positions should be placed so they do not fire through traffic patterns or otherwise restrict the full utilization of the airfield. Airfield perimeters must be moved out far enough to meet the above requirement and to provide for adequate dispersion of aircraft to preclude excessive losses to rocket or mortar attack. Vehicle traffic must be routed away from the active runway(s), taxi strips and parking areas. The location of VIP pads, medevac pads and other critical installations should be dispersed parallel to and along the active runway.

SUBJECT: After Action Report, Operation MAC ARTHUR (AO SPAATZ), 25 October - 30 November 1967

d. Safety.

- (1) Observations and Discussion. During the Battle of DAK TO, several extremely unfortunate accidents occurred; accidents which could have easily been avoided. Passengers loading and off-loading helicopters continued to walk into turning rotor blades. Turning blades are a hazard at any time; however, when operating on other than level ground, the hazard increases ten-fold. A rotor strike will almost always result in decapitation and death to the individual involved.
- (2) Recommendation. Personnel operating in the vicinity of helicopters should be constantly reminded of the dangers involved. Classes or demonstrations should be given as to the proper method of boarding or departing a helicopter. On the just concluded operation, 3 lives were unnecessarily lost due to carelessness in this manner.

FOR THE COMMANDER

1 Incl
Map-(AO-SPAATZ) Not received
Mas DA

s/ Curtis D. Green T/ CURTIS D. GREEN MAJ INF Adjutant

Distribution
2-1st Avn Bde
4-17th Cbt Avn Gp
2-4th Inf Div
1-1st Bde, 4th Inf Div

19

CUNFICENTIAL

DUPARTHENT OF THE ARMY
57TH ASSAULT HULICOPTER COMPANY
APO 96499
"CHADIMORS"

5 February 1968

SUBJECT: After Action Report 30 January thru 4 Febrauary 1968

TO:

Cormanding Officer
526 Corbat Aviation Battalion
APO 96318

1. General

- a. The sustained attack by NVA/VC forces in the Kontum area began 30 January at 0212 hours and was reduced to minor sniper fire and occasional mortar/rocket rounds by 000 hours on 5 February 1068. This was a coordinated attack against the city of Kontum as well as all U.S. and ARVV military installations in the area. The magnitude of the attack requires consideration of the entire Kontum action rather than the 57th Assault Hallacopter Company area alone.
- b. Indications are that the overall plan called for taking adventage of the isolated locations of US and ANN compounds. The plan was time phased to eliminate specific compounds on given dates. The 57th Assault Helicopter Company was the first to come under heavy ground attack. This attack, from 300230 thru 310900 January 1968, was an estimated force of 200 and included sapper, security and indirect fire elements.
- c. The major attack on this compound was basically a remeat of the 10 January action. NVA intelligence had not been updated since that defensive posture. The enemy was either over confident in their ability to eliminate this unit or were inflexible to initiate alternate plans once the attack had failed. The action on subsequent days was oriented mainly against MACV, Special Forces, 43d Signal and 24th STZ compounds.

2. Sequence of Events

a. 30 January 1968

(1) At 300212 hours a coordinated rocket, mortar and ground attack was launched against the 57th Aslt Hel Co compound. During the battle that followed WA forces reached a point within 50 meters of our defensive wire. Gunships engaged the enemy outside the entire eastern perimeter

at a range of 20 -30 meters utilizing minimums and M-5 systems. This action, combined with ground defensive mine, broke the attack but fighting continued until 0900 hours on 30 January.

- (2) Defensive fires of this unit combined with those of 1 Troop, 2/1 Cav inflicted heavy ensualties upon the attacking forces and a scaled off oscape routes for PVA elements.
- (3) The action during the early morning hours of 30 January resulted in one aircraft receiving minor damage on the ground while six additional aircraft, including four gunships, received varying degree of damage from intense enemy fire while performing aerial flight.
- (4) From first light mutil 0900 hours muships of 52d Bettelion organod isolated units to the east and northeast of this compound. Action was later continued with TAC air. A firm body count for all 52d Combat Aviation Baltalion gaughips was not obtained but 57th cans accounted for 35 NVA bodies during this phase of the action.
- (5) A sweep of the area initiated at 0900 hours to conduct a body count along the perister. This action was terminated by intense sniper fire prior to completion. Body count had reached 59 at this time.
- (6) Sniper fire continued throughout the day along the east, west and north perimeter.
- (7) 122mm rocket and morthr attack was initiated at 1845 hours. Sporactic fire and small scale problems continued until 2400 hours.

b. 31 January 1968

- (1) Botween the hours of 0230 and 0330 a series of reports from the 24th STZ indicated a severe situation in their compound.
- (a) NVA/VC forces, estimated at 150 strongth, were over running their parimeter and final butkers were occupied.
- (b) The 105m bettery was reported to be infiltrated and possibly in enemy hands.
- (c) This unit was notified that MACV and 3-24 compounds were being overrun. Gunships dispatched and engaged the NVA forces along the wire defenses at which time enemy forces withdrew.

74

- (d) Zone notified this unit of a confirmed NVA forces of 300 500 men located 2000 meters to the east of 57th Aslt Hel Co compound.
- (e) At this time the Senior Advisor, 24th STZ declared a tactical energoney in an effort to obtain additional gunships and TLC air support. This unit was advised that some communications were out and request we relay the situation and declaration to II Corps headquarters through 52d Combat Aviation Battalian.
- (2) Enemy forces infiltrated NRVN forces defending the south side of Kentum Airfield and were within hand granade range of out southern perimeter. Genships were employed and a low pass with searchlights on indicated seven begins alon the fence.
- (3) Stoady but light contact was maintained on the east and west perimter between the hours of 1900 and 2400.

c. 1 February 1968

- (1) Gunships of 52d Combat "viation Rettalion were employed from 0230 thru 0800 against targets within the built-up area of Konton and to the north. Targets included building, churches, streets on housing and government complexes. In each case fire was requested and targets identified by ground commanders and/or advisors.
- (2) Sniper activity continued on east and west perimeter of the 57th Assult Helicopter Jorgany throughout the period.
- (3) A recket and mortar attack was launched by the energy at 1745 hours. Counter fire in close proximity to our perimeter, when mixed with enemy fire, made it extremely difficult to differentiate between friedly and enemy rounds.
- (4) Light probes against the western perimeter were encountered from 1910 hours until the end of this period.

d. 2 Mebruary 1968

- (1) At 0220 hours a mortar/recket and ground attack was launched against the MACV, Signal and Special Forces complex. Conships were dispatched in support of local defense.
- (2) Six toams of 52d Combat Aviation Battalien genships were on-station supporting local forces against heavy enemy fire in and around the city. Mothods of control included:
- (a) Targets and clearance to fire word obtained from ground commanders.

- (b) Those tergets femiliar to personnel operating Gladiator TOC, for which definite targets identification central measures could be established, were controlled by this unit. Targets that were unfamiliar to TOC personnel were passed to the requesting agency for identification and control.
- (c) Gunships not assigned to the 52d Combat Aviation Battalion were operating in area without contact and minor control problems were encountered.
- (d) All 52d Combat Aviation Battalion aircraft were given a cease fire and returned to 57th Assault Helicopter Company revetments area until positivo fire control was established.
 - (c) See lessons learned.
- (3) Cantonment area received 2 122mm rockets at 1900 hours setting fire to a 5,000 gallon tanker.
- (4) Isolated sniper fire during the remainder of the period. Total curlative KIA and KBA count was 203.
- o. 4 February 1968. Relatively inactive with the exception of 2 122mm rockets in the compound at 1600 hours. The city of Kontum was reported secure except for sniper fire. The 57th Assault Helicopter Company continued on 100% alert and provided continuous illumination during the hours of darkness.
- f. 3 February 1968. Enemy activity decreased considerably however, rocket attacks on this compound occurred at 1040 and 1200 hours.
- g. 5 February 1968. In estimated enemy battalian moved within 3 kms of MACV compound during the early hours and were encoded by artillery and gunships. Activity was on a small scale and this unit received six unidentified rounds that failed to explade and penetrated to a depth of six feet (assumed to be 105mm illumination). Flare coverage was reduced to a standby status and the unit went on 50% alort.

3. Significant Factors

- a. The NVA intelligence on local defense appeared to be the same as 10 January attack. This possibly is due to control of civilian traffic around the 57th Assault Helicopter Company compound. In addition, local hire personnel are used outside the compound only.
- b. The security force of 35 provided to this unit after the 10 January attack was instrumental in improving defensive facilities during the 20 day period between attack. Major recomplishments included:

76

- (1) Defensive wire was improved and expanded out to encompass a larger area. This work is still in progress.
 - (2) Temporary perimeter lighting had been istelled.
 - (3) Bunkers had been improved and repositioned.
 - (4) A larger force was employed on the perimeter.
- c. The NVA/VC body count reached a total of 203 by KIA and KBA. This firme is by no means all inclusive for 52d Combat Aviation Battalion action in the Kontum area. In addition, secodary explosions were obtained during gunship employment against four mortar and rocket positions.
- d. A search of the battle area in the vicinity of the 57th Assault Helicenter Company perireter revealed numerous satchel charges, bangalow tempedoes (home made and remufactured), wire cutters and 60mm mortars, thus, varifying the intent to destroy this complex in include aircraft.
- o. The sequence of events indicated the enemy respected the potential of helicopters being employed against their force and therefore intended to eliminate that threat on the first day of the attack.
- f. Continuous illumination of the bettle area ground Fentum was a major factor in the successful defense by all US and 'RVV forces during the hours of darkness.
- g. Night omployment of conships in a final protective fire role was a significant factor in proventing enemy ponetration of compounds on at least two occasions.
 - h. A listing of ensualties is at inclosure 1.
- i. The major impact of personnel lesses for both attacks is in the maintenance area. Shortages are as indicated at inclosure 2.
- j. This unit suffered no loss or denage to major items of equipment other than eigeraft. All aircraft denaged appear to be repairable.
- k. The parking area for 0-1 and 0-2 aircraft (south side of the field) was destroyed. An emergency work order is being submitted to prepare temporary parking facilities.

4. Lessons Learned

a. The armed helicopter is an accurate and effective weapon platform that can be integrated into final protective fires. Employment at night, as well as in built-up areas, requires close coordination,

target identification and positive location of friendly troops by the commander being supported. These systems are area type weapons and ground commander must accept a degree of risk that some rounds will inadvertently land within their positions when employed close-up or on point targets.

- b. The enemy force, when employing infiltration and sapper tactics, is inflexible to changes in defenses that disrupt his rehearsed plan. Continued improvement to wire locations, bunkers location and overall security serves to deny him the intelligence, detailed planning and rehearsal so often employed in successful infiltrations.
- c. The lack of combat forces in the immediate vicinity of Kontum and the covered avenue of approach from the north thru the southeast continues to be the major problem in providing adequate security for this compound. An enemy force of any size has a high probability of reaching this unit's perimeter prior to detection.
- d. The physical location of US and ARVN compounds are such that any mutual support is denied. This situation favors the enemy in that he can attack and eliminate compounds one by one with minimum interference. The major exceptions are supporting artillery and gunships.
- e. The organic fire power of an assault Helicopter company and its detachments is capable of defending against a substantial attacking force. However, manning the perimeter on 50% alert during the hours of darkness degrades immendely from the aircmaft maintenance effort and results in a slow recovery to full operational capacity.
- f. It is essential that one agency have knowledge of all gunships operating in the area. At one time, two gun teams (other than 52d CAB) were operating independently in and around Kontum City. Friendly forces were being fired upon and 57th Assault Helicopter Company TOC had no means of contacting these elements to effect a cease fire.
 - 5. Planned action and recommendations
 - a. Planned actions
- (1) Work will continue to replace defensive wire destroyed, expand the outer perimeter wire and install anti-personnel mines along the north and east side.
- (2) Civilian access to the compound is limited to permanent hire and KP personnel who have received a local clearance. Civilian traffic through the area will continue to be denied.
 - (3) Continued improvement on defensive bunkers.
 - (4) Temporary perimeter lighting will be improved. The

FE

major limiting factor is a readily available power source. This unit has operated on TO&E generators since arrival in-country. The demand for power has reached the stage where lights to the billeting area is occasionally denied to provide perimeter lights.

(5) Defensive plans will continue to be reviewed and updated as required.

b. Recommendations

- (1) A US Combat unit be stationed in the Kontum area to provide early detection and warning of any forces approaching along the major avenues of approach.
- (2) Designation of one agency to control all gunships operating within the immediate tactical area.
- (3) Immediate replacement of key personnel losses during the month of January.
- (4) Authorization be given to retain the security augmentation from other battalions until planned improvements to local defenses are completed. (Estimated 2-3 week period)
- (5) USARV approval and engineer tasking for the 57th Assault Helicopter Combat base development plan be executed so that construction of permanent defenses can be accomplished with minimum time delay.

2 Incl
 as
Incl 1; Withdrawn, Hqs, DA

t/GEORGE E. BURNISON Major, Infantry Commanding

rsof

Incl 2

MAINTEN MOE PURSOWNEL SHORTAGES

The following list shows the maintenance personnel shorters within the 615th Trans Det and Service Flatoen at this time. Shorters which are directly affecting maintenance productivity are designated by an asterisk.

A. 615th Dot:

Item	$O^{\frac{1}{2}}Y$	Job Titlo	Grade	<u> MOS</u>
(1)	**7	Aircraft Maintenauce Technician	I-IO	062B
(2)	9F 7	Detachment First Sorgent (Note 1)	मृन्द्र	6774.0
(3)	*1	Assistant Shop Foroman	TG-6	67Z40
(4.)	#2	Sonior Engino Ropairman	型5	68820
(5)	**5	Sonior Airfrano Repairman (Moto 2)	E-5	68420
(6)	*5	lirframe Repairman	H-4	ଌଌ୕ଌଌ
(7)	1	Aircraft Electrical Royairman	Buch	68T/20
(8)	*1	fireraft Supply Specialist	18,005	76H20
(9)	1	Aircraft Supply Specialist	E-3	76F20
(10)	*1	Mircraft Tech Inspector (Note. 3)	Ps-6	. 67420
(11)	*1	Aircraft Irnament Repairman	F-4	45320

B. Sorvice Platoon Maintenance Shortares

<u>Itom</u>	Oby	Inh Dagozintion	<u>Ĝrado</u>	MCS
(1)	1	Maintonanco Supervisor	T-6	67N4.0
(2)	5	Somior Holicopter Repairman	13-5	67720

Note 1. Although the Det First Sersent does not directly affect the maintenance output, his absence requires most of the time of the Shop Foreman acting as First Serseant.

Vote 2. Includes one man who is DEROS in 10 days.

Note 3. Includes one man who is on emergency leave and is not expected to return.

80

9

CONFIDENTIAL

DEPARTMENT OF THE ARMY
HEADQUARTERS, 52D COMBAT AVIATION BATTALION
APO San Francisco 96318
"FLYING DRAGONS"

AVGD-CC

31 January 1968

SUBJECT: Enemy Attack on US Installations After Action Report

TO:

Commanding Officer 17th Combat Aviation Group APO San Francisco 96240

INFO:

Commanding General 1st Aviation Brigade APO San Francisco 96384

1. General: Camp Holloway, Pleiku, RVN, was attacked by four (4) mortar tubes and elements of the 408th NVA Sapper Battalion at 0230 hours on 26 January 1968. The attack lasted approximately fifty (50) minutes, and concentrated the sapper attack against the 88th S&S Bn area, with the mortar concentrating along the aircraft revetment areas adjacent to the runway and the 604th Trans Maint Co (GS) area (See inclosure 1).

2. Sequence of Events:

a. The samper unit, an estimated 50 - 60 man force, approached the perimeter from the cast, and a 20 man team undetected, breached the perimeter in the 88th S&S Bn area. Entry was made by tying off trip flares and cutting of barrier wires. Upon entry, 30 - 50 satchel charges (3 blocks of TNT, 200 grams, with fuze wells in center blocks) were placed adjacent to numerous supply and storage facilities. At this point, the sappers departed the area. Upon departing the area, via same route, either a trip flare was ignited or a flare was fired, and members of the unit word detected. At approximately 0247 hours, fire was placed on the fleeing enemy, killing one and wounding another (See inclosure 2).

b. At about the same time the retreating sappers were detected, four mortars, located in the vicinity of ARS18477, opened fire on Camp Holloway Complex, and between 0247 and 0305 hours, 110 - 120 rounds of 82mm were fired into aircraft parking and maintenance areas. The heaviest concentrations fell into the 604th Trans Maint Co (GS) area, the miniport refueling area, and the aircraft parking areas adjacent to and paralleling both sides of the runway.

Incl 8

- c. Immediately following the initial incoming rounds, countermortar radar confirmed in the enemy mortars and return mortars, mortar radar confirmed fire was brought to bear on the confirmed position. Within rinutes incoming fire, except for sporadic sniper fire, ceased.
- d. At approximately 0310 hours, a tremendous explosion occurred in the 88th S&S Bn area. Ammo Pad #S, probably caused by a satchel charge, exploded, causing blast damage throughout the complex. At 0320, the alert ceased and Camp Holloway returned to a fifty per cent status.
- e. The attack was well planned and executed with precision. Indications are that the enemy possesses a detailed knowledge of the peneral layout of the compound, and probably selected this course of action because:
- (1) Detonation of the ASD area of the 88th 985 Pn area would place an increased logistical burden on an already strained line of resupply.
- (2) The enemy may well have been testing our security alertness in preparation for a larger attack during the TET season.
- f. Though local reaction had little effect on the sapper attack, the reaction of the mortar element of the security detachment, and gunships, probably caused the enemy mortar element to cose fire and disperse.
 - 3. Significant Intelligence Information:
- a. Sapper personnel were MVA, assigned to the 408th Sapper Bn. This is the first known contact with the element in the vicinity of Pleiku.
- b. The mortars were positioned in approximately the same location as during the previous two attacks.
- c. The enemy was equiped with satchel charges, 82mm mortars, M-26 chicom flare pistols, AK-47's, B-40 rockets, bangalore torpedoes and chicom cannister stick concussion groundes.
- (1) The satchel charges were 3 blocks of TNT, 200 grams with a fuze well in the center blocks. Approximately half of the charges failed to detonate. The only major damage caused was to Ammo Pad #8.
- (2) The 82mm morter fire was erratic with about ten por cent of the rounds failing to detonate. Eleven rounds were later found at firing site.
- (3) One M-26 chicam flore pistol was found were the body of the slain NVA.
- (4) One AK-47 was left within the perimeter along with three magazines.

- (5) One B-40 rocket lauchor and two rounds were left behind, but no rockets were known fired during the attack.
- (6) Two five inch banglore torpodess were found, but none employed.
 - (7) Eight chicom cannister stick grenades were recovered.
- d. It appears that the enemy was not particularly interested in inflicting personnel casualties, but attempted to destroy supply facilities with sapper charges and aircraft and maintenance facilities with mortars.
 - 4. Damage, Information:
 - a. Porsonnel losses by unit are listed in inclosure 3.
- b. Major items of equipment damaged or destroyed are listed in inclosure 4.
 - 5. Plannod Action and Recommondations:
 - a. Planned Actions:
- (1) The defensive wire will be repaired where breached and reinforced throughout the perimeter. Random wiring will be placed throughout the contenement area to channelize and confuse a successful penetration.
- (2) All trip flares were inspected and expended flares replaced.
- (3) Additional anti-personnel mines will be sown throughout the outer perimeter.
- (4) Additional bunkers are being constructed to provide botter visual coverage of the perimeter and to provide increased fire power where initial engagement is probable.
- (5) Defense plans are constantly being reviewed and revised as deemed necessary.
 - b. Recommendations:
- (1) Replacement of destroyed equipment as soon as possible, with priority on aircraft.
- (2) Increase manning level of security detachment. Detachment presently operating at approximately fifty (50) per cent strongth.

(3) Prosent perimeter lighting is inadequate. Since 7 January 1967, this project has supposedly had top priority, but has yet to be completed. Recommend immediate completion of project for maximum security vigilance.

5 Incl

1 - Dofensive Posture (OMITTED)

IMC Inf

2 - Comment Relative

Commanding

Capture of Prisonor

3 Personnol Lossos Withdrawn, Mgs, DA
4 - Equipment Lossos

5 -After Action Report - Period 30 January 1968

Inclosure 2: Comments Relative Capture of Prisoner

A captured PW stated two (2) companies of the 408th Battalion (Sapper) were responsible for the attack on Camp Holloway. One, a combat support company (numerical designation unknown), which handled the 82mm mortars, and the K-90 Company of the 408th, which handled the sapper activities. The PW stated his unit (K-90 Company) was located northwest of Pleiku, north of Plei Mrong. The company took two days to reach the target area. He states that 20 sappers ponetrated the 88th S&S Bn area; the remainder waiting outside to provide covering fire with small arms and automatic weapons. Whether all sappor personnel exfiltrated the area was not known. The PM stated the combat support company utilized four mortar tubes in the attack (verified by area sweep the morning after the attack). (They were fired from the vicinity of AR818477, approximately 50 meters from previously used site.) He further stated that his unit was not to launch a new attack the following night (27 January), but to return to their base camp in the vicinity of Dai Thong (coordinates unknown). Fis battalion was to conduct an attack on another location prior to TET.

The 408th units, as was the case with the 60th Company, 408th, which conducted a raid against the 937th Engineers on 21 January, used Highway 14N as its primary route of advance to the target area. The PN further stated that he carried no weapon during the attack and that his primary mission was to carry wounded or dead personnel to the village (assumed to be Mo'nu) during the attack.

مستتهي

INCl 2 to INCl 8

Inclosure 4: Equipment Losses

1. The following damage was sustained by aircraft stationed at Camp Holloway:

TYPE	<u>init</u>	<u> </u>	TYPE DA	MACE	<u>rocvalon</u>
ij н 1 н	57th	109	Minor	Windshiold	604th DSII
10H-1 H	170th	394	Minor	T/R & Windshield	604th DST
υн-1 н	189th	753	Minor	T/Boom	604th DST
UH-1H	119th	374	Minor	T/R	CO Arca
TH-1H	119th	376	Minor	T/Boom	CO Ascan
UH-1H	119th	524	Minor	N'/R Blades	00 Isroa
11H-1H	119th	517	Minor	T/Boom 7 Plades	CO Area
एम-1म	1 19th	609	Minor	T/B & Engine	CO Arca
11H-1H	1 19th	533	Minor	T/B & Trans	00 Aroa
τин-1н.	119th	534	Minor	T/Boom	00 Aroa
11H-1H	119th	527	Ninor	Exhaust Cover	00 Aroa
TIH-1 H	335th	643	Minor	T/R & Pilots Door	Trans Ramp
UH-1H	335th	702	Minor	N/R Blades & T/Boom	Trans Ramp
UH-1H	335th	638	Minor	T/R Eng & Windshield	Trans Ramp
UH-1 H	335th	620	Major	T/Boom & M/R Blades	Trans Ramp
TIH-1H	4th Div	589	Evac	Destroyed	604th DSII
11H-1H	604th TC	092	Minor	Shootmotel	604th DSU
UH⊷1 C:	119th	591	Major	Destroyed	604th DST
UH-1C	170th	483	Major	Dostroyed	604th DSU
UH-1C	189th	690	Minor	T/B & Dr Shaft	CO Area
TTH-10	335 t h	612	Minor	T/B & Windshiold	Trans Ramp
17H-10	335th	664	Minor	T/B & Tail Rotor	Trans Ramp
יתו – 10	7/17th	063	Evac	Destroyed	604th DSII
TIH-10	7/17th	735	Major	Over 7 days	604th DST
TIH-1C	134th	632	Minor	M/R Blades	604th DSII
UH-1D	604th	018	Evac	Destroyod	604th DSII
CH-47	179th	978	Minor	Aft Vert Fin	604th DSU
он-6л	7/17th	807	Minor	Shoetmotal	604th DSU
U - 6∆	125th ATC	733	Major	Over 7 days	604th DS''

2. The following damage was sustained by equipment other than air-craft:

TYPE	TINU	DAMAGE .	TOCATIOA
3/4T Truck	189th	Windshield, radiator, all tires and sheetmetal	CO Area
Forklift	88th S&S	Radiator	Bn Aroa
Forklift	88th S&S	Radiator	Bn Aroa
Pad #8	88th S&S	Ammo Pad dostroyed	Bn Arca

3. Substantial structural damago throughout contonement area due to blast effect when Ammo Pad #8 exploded.

INCI 4 to

INCI 8

DEPARTMENT OF THE ARMY
HEADQUARTERS, 52D COMBAT AVIATION DATTALION
APO San Francisco 96318

AVGD-SC

4 February 1968

SUBJECT: Enemy Attack on US Installations After Action Report

TO:

Commanding Officer 17th Combat Aviation Group APO San Francisco 96240

INFO:

Commanding Officer
1st Aviation Brigade
APO San Francisco 96384

1. General: Camp Holloway, Pleiku, RVN, was attacked by two (2) 82M. mortar tubes of an unknown main force unit at 0140 hours on 30 January 1968. The duration of the attack was approximately thirty (30) minutes, during which 20-30 rounds fell within the confines of Camp Holloway.

2. Sequence of Events:

- a. The enemy mortar crews (estimated 12 men) moved into position, vicinity AR 817477 (1400 meters from target center of mass) using the village of Plei Mo'nu as their base of operations. At 0140 hours, approximately 10-15 rounds were fired, impacting north to south on a lateral sheath 200 meters wide (maximum deflection spread at that range without re-laying the tubes).
- b. The location of the enemy position was visually confirmed from the HAIF control tower and counter-mortar and gunship fire was employed to neutralize the position. However, after a three to five minute pause, 10-15 additional rounds were received, impacting from south to north along a lateral sheath. The gunships again engaged the position with aerial rocket and mini-gun fire. Incoming rounds ceased at approximately 0210 hours, immediately after the gunships engaged them for the second time.
- c. Gunships and counter-mortar fire continued to engage the confirmed enemy position and possible infiltration routes (Inclosure 1).
- d. During the attack, this installation was on 100% alert and remained so until approximately 0700 hours. Throughout the night gunships and mortars continued H&I fires with unknown results. There are no indications that the Camp holloway perimeter was penetrated during the attack.

INCI 5

CONFIDENTIAL

INCL 8

81

AVGD-CC CONFIDENTIAL 4 Feb 68
SUBJECT: Enemy Attack on US Installations After Action Report

- e. The mortar attack again indicates that the enemy has used his detailed knowledge of the Camp Holloway facilities. Intended targets were the aircraft revetments and support facilities. Factors that may have influenced the enemy course of action are:
- (1) Passive defense measures provide more protection to personnel than aircraft.
- (2) Destruction of aircraft denies combat elements the prime movers of supplies, equipment and troops into norward areas, seriously affecting combat operations.
- (3) Armed aircraft located at this installation constitute a major deterrent to ground assaults of installations in the Pleiku area.
 - 3. Significant Intelligence Information:
- a. The enemy mortar section used the same general location as the mortar element of the 408th Sapper Bn which attacked this installation on 26 January 1968.
- b. The reaction of the gunships probably caused the enemy mortars to cease fire, and may have spoiled a planned ground attack. 250 enemy personnel had earlier been reported in the vicinity of AR815565, preparing for an attack on some installation in the area.
- c. The following morning the same enemy element (identified as the H-15 Bn) was located, taken urships. 130 VC and NVA were killed a aircraft and the Battalion Commander captured.
 - 4. Damage Information:
 - a. Personnel losses by unit are listed in inclosure 2.
- b. Major items of equipment damaged or destroyed are listed in inclosure 3.
 - 5. Planned actions and recommendations:
 - a. Planned Actions.
- (1) When an attack is eminent, aircraft will be evacuated from Camp Holloway to an area less likely to be attacked.
- (2) Aircraft will be dispersed to decrease the danger of excessive damage to aircraft.
- (3) Additional protection will be provided by placing vehicles around the aircraft to absorb as much of the shrappel damage as possible.

4 Feb 68

AVGD-CC CONFIDENTIAL SUBJECT: Enemy Attack on US Installation After Action Report

b. Recommendations.

- (1) Increase the manning level of the assigned Security Detachment, that it may secure and interdict the area around Camp Holloway, to preclude the employment of enemy mortars.
- (2) Replace damaged or destroyed equipment as soon as possible. Priority of replacements should be to aircraft to enable the battalion to continue to meet its support requirements.
- (3) Present perimeter lighting continues to be inadequate. The emergency request of said lighting, dated 10 December 1966, has yet to be completed. Recommend immediate action.

3 Incl

1-Defensive Posture (AMP) DA

3-Equipment Losses

EDWARD P. LUKERT, JR.

LTC, Inf Commanding

CONFIDENTIAL

· AB YOU!

Inclosure 3: Equipment Losses CONFIDENTIAL

1. The following aircraft were damaged as a result of the mortar attack on Camp Holloway on 30 January 1968.

UNIT	TYPE A/C	A/C NR	DAMAGE	<u>DESCRIPTION</u>
134th	C	632	Minor	Sheetmetal & blades
134th	C	148	Minor	Shootmetal & windshield
170th	C	546	Minor	Vort fin
170th	C	140	Major	Fuselage, tail boom,
			-	tail rotor & engine deck
119th	C	685	Minor	Tail boom
189th	C	691	Minor	Sheetmetal & tail boom
189th	C	696	Minor	Sheetmetal
189th	C	690	Minor	Main Rotor Blade
170th	H	537	Major	Fuel cell & tail boom
170th	H	218	Minor	Vert fin
170th	H	358	Major	Fuselage, tail boom,
			: -	tail rotor & engine deck
170th	H	323 .	Major	Shectmetal & tail boom
170th	$\mathbf{H}_{c^{*}}$	220	Minor	Sheetmetal
170th	H	170	Minor	Sheetmet al
189th	H	066	Minor	Engine cowl & exhaust
				cowl
189th -	H	385	Minor	Chin bubble & windshield
170th	Ħ	538	Major	Sheetmetal & main rotor blade

2. The following major items of equipment were damaged as indicated.

UNIT	TYPE EQUIP	<u>DANIAGE</u>	DESCRIPTION
179th 179th 179th	2§T Trk 2§T Trk 2§T Trk	Destroycd Major Major	∿.
344th AOD	3/4T Trk	Major	Cabin, Windshield, Hood, Engine & Skin
344th AOD	<u>‡</u> T Trk	Moderate (Radiator, Windshield, & Skin

90

Incl 3 to Incl 5 to Incl 8

CGNFICENTIAL

DEPARTMENT OF THE ARMY 57TH ASSAULT HELICOPTER COMPANY APO 96499

11 January 1968

SUBJEC" Report of Sapper Attack

TO:

Commanding Officer
52d Combat Aviation Battalion
APO 96318

1. General

- a. This unit was attacked by a MVA sapper unit at 0200 hours on 10 January 1968. The attack lasted for twenty-five (25) minutes and was concentrated against the motor pool and aircraft maintenance areas inflicting major damage to each. (See attached diagram at inclosure 1)
- b. The sapper unit, an estimated 30 40 man force, approached the compound from the north east through an area serving as a boundry between C Troop 2/1 Cav and 173d Abn Pde maintenance area. The 57th Assault Helicopter Company compound lies within the area covered by these units. Entry into the compound was gained by using bamboo sticks 18 24 inches high and notched on each end to prop-up the wire. Four such lanes were made within a 10 meter section. This area was blown during the attack and provided the escape route.
- c. The track was well planned and executed with precision. Indications are that the NVA had detailed knowledge of the general layout of the compound. The enemy probably selected this section of the compound due to:
- (1) A 30 40 man crew performs maintenance every night utilizing exterior lighting.
- (2) A defile running from the north through east provided a covered approach to ${\tt WS}$ defense.
- (3) The lights of the maintenance area provided an excellent ground guide. They also silhouetted maintenance personnel as well as aircraft while providing cover for sapper teams.
- d. Sapper teams were organized in groups of five with a combination of satchel men and automatic weapons personnel.

INCL 9

CONFIDENTIAL

91

SUBJECT: Report of Sapper Attack

11 January 1968

A minimum of three such teams plus one rocket team were within or around the compound perimeter.

- e. It is concluded that the reaction of organic personnel precluded the accomplishment of the overall plan of the sapper teams.
- (1) Upon completion of sweeping the maintenance area, sapper teams were encountered as they approached the tent billets, taken under fire and then withdrow.
- (2) NVA bodies left behind had baskets with a total of 25 30 charges and grenades to be used.
- (3) A briefing map drawn on the groun included the maintenance area and COC bunker.
- (4) A rocket team was operating separately along the north west sector thus indicating an attempt to destroy structures to the front of the compound.

2. Sequence of events

- a. At 0200 hours action was initiated by a minimum of two teams placing demolitions in vehicles and aircraft. Simultaneously, maintenance personnel were taken under fire and work areas blasted. Reaction by on-duty personnel was probably slow due to an immunity to fire brought on by speradic fire from local ARVN forces over the past few weeks.
- b. A NVA security force outside the perimeter pinned down the north east machine gun positions during the majority of the attack.
- c. After setting explosive charges, capper teams proceded to the eastern edge of billet area and were engaged by organic personnel.
 - d. Teams withdrew to the north east without entering the billets.
- o. A rocket team with one launcher and four rounds were killed while attempting to enter the compound. No rounds were expended.
- f. The sapper force withdrew from the compound and entered the 173d Abn Bde maintenance area.
- g. Nine NVA bodies were found in and around the north and north east portion of the 57th Assault Helicopter Company perimeter.

SUBJECT: Report of Sapper Attack

11 January 1968

- 3. Significant factors
- a. The NVA had excellent intelligence as to the layout of this compound which could be attributed to one or a combination of fasters.
- (1) Local civilians (assumed) have constantly been along the roads bordering the compound attempting to sell items and pick-up material. On numerous occasions this unit has contacted Province for their removal as well as driving them away. This is affective for periods of hours only.
- (2) Surrounding hills and easy access to the city of Kontum allows uncontrolled surveillance of the area.
- (3) Local hire personnel are being used on the compound to free personnel for utilization in their MOS.
- b. 24th STZ and Sector personnel report that this group is the first encountered who were carrying knives. When associated with the "tent city" at Kontum it is assumed overall plans were to sweep the billet area placing charges in numerous tents.
- c. NVA personnel were all outfitted in shorts. When considering US and ARVN forces wear fatigue uniform and the cold weather now prevailing it it concluded this is an easy means for them to distinguish between friend and foe when engaged at close range. If this tactic is substantiated it could be used as factors in identification by our forces.
- d. It appears the enemy desired to inflict heavy casualties and destroy aircraft with vehicles being convinient target because of location. Destruction of aircraft must have been the paramount desire. Had the attack originated in the tent area casualties would have been extremely high but reaction of on duty maintenance personnel would have precluded the destruction of helicopters. A three-prong attack against motor pool, aircraft mainterance and quarters would have been disasterous.
 - e. A listing of personnel loses by MOS is at inclosure 2.
- f. A listing of major items of equipment demaged or destroyed is attached at inclosure 3.
- g. The posture and capability to provide Aircraft Field Maintenance Support is at inclosure 4.

93

SUBJECT: Roport of Sappor Attack

11 January 1968

- 4. Lossons learned by this action.
- a, This action again confirms that an assault helicopter company is neither organized nor manned to provide its own local security with organic assets and provide continued maintenance support on a 24 hour basis. The aviation company should be treated like a supporting artillery element where the supported force is required to provide local security. The lack of adequate security and personnel has been recognized by this unfit and a letter drafted on 9 January 1968 is attached at inclosure 5. (Not received, 1995, Dt.)
- b. Defensive wire around the 57th Assault Helicopter Commany compound requires improvement, expansion and incorporation of anti-personnel mines, and warning devises. Trip flares previously installed have been removed by civilians on numerous occasions.
- c. The best wire barrier is of little value if not illuminated by perimeter lighting and covered by fire.
- d. Alert procedures require reevaluation. Current defensive concepts call for individuals to remain in bunker or protective area during mortar or recket attack and to occupy defensive positions along the perimeter during ground attack. The major problem encountered is distinguishing between sapper attacks and incoming mortar rounds. The majority of personnel interpreted this as a mortar attack and remained in place for 5 10 minutes.
- e. Overall security must be planned and coordinated by the senfor commander in the area. However, a sufficient security force must be provided to the assault helicopter company to guard against infiltration of outer units and local defenses.
 - 5. Planmed actions and recommendations.

a. Planned actions

- (1) The defensive wire around this compound has been relocated to include all of the permanent cantonment area. Improvements are now being made to include anti-personnel mines. The wire design is depicted at inclosure 6. (Not received, 1445 Dn)
- (2) Roads passing through the compound are being blocked off by wire thus including the entire area and denying civilian traffic access to the compound.

94

CUNFICENTIAL

SUBJECT: Report of Sappor Attack

11 January 1968

- (3) Night maintenance is being reduced drastically and local security increased to a size capable of providing minimum cover of our one mile long perimeter. This action is planned to continue until a sufficient security force is made available. If addition personnel can not be provided consideration should be given to relocating this unit to a more secure area such as Camp Holloway.
- (4) Present defensive bunkers are being reevaluated and some repositioned. Additional bunkers are being prepared.
- (5) This unit now has three search lights on hand which were inoperative on the night of attack because of a lack of bulbs which are not available through supply channels. Four bulbs have now been found and the lights are being employed as perimeter lights until adequate equipment can be provided.
- (6) Defensive plans are being reviewed and updated as deemed appropriate.

b. Recommerdations:


- (1) Replacement of destroyed equipment as soon as possible with priority on aircraft.
- (2) An absolute priority be established to provide the 57th Assault Helicopter Company with the 66 man security force outlined in inclosure 5 and scout dogs.
- (3) Permanent perimeter lighting be issued on a pricrity basis.
- (4) If the above can not be accomplished recommend restationing of the 57th Assault Helicopter Company to a more secure area.

5 Incl as Incl 2 withdrawn, Hqs, DA /s/GEORGE E. BURNISON /t/CEORGE E. BURNISON Major, Infantry Cormonding

A TRUE COPY

PAUL R. DAVIS CPT, Infantry 95

103



124

57TH ASSAULT HELICOPTER COMPANY DAMAGED EQUIPMENT

deam doo a cod			
6115-833-1498	Gonarator Set 10 KM, AC	SN: 3505	1 ca
2330-141-8050	Trailer, ego, 1 T M105A2	TTS 14 685094	1 ea
	Fire Units, feild range		3 oa
2330-542-2029	firniler, tenk, water, M10742		1 ca
6115-913-9290	Gonerator Set 3 KW	SM: 01489	1 ea
6115-074-8830	Generator Set 5 KM	SN: 0917 .	1 ea
6115-736-8509	Generator Set 1.5 KW	SN: 1702	1 ea
7330-238-2411	Food Container, insulated	•	2 ea
2320-5424783	Truck, util, + T, M151	19A# 2D6635	1 ea
2320-542-4636	Truck, ego, 3/4 T M37B1	TISA# 304935	
		3A5699 , 3B7593	
		3B7321, 2D33332	5 ea
2320-835-8322	Truck, ego, 3/4 T M37	USA# 2443447	1 oa
2320-055-9262	Truck, dump, 5T M51A2	USA# 5E8513	1 ea
4210-202-8076	Fire fighting equipment		
	Set TRK NTD	USA# 4E9910	1 32
2320-077-1631	Truck, Tank, Fuel, 25 T,		
	M49A2C	IISA# 4J3224	
		4J3514, 4J3503	3 oa
2320-7389509	Trailer, ego, 3/4 T M101	usa# 6r1861	1 oa
2320-141-8050	Trailer, ego, 17 T, MOSA2	11SA# 655095	1 ca
1520-859-2670	Helicoptor, Wtil, WH-1H	SN: 66-1138,	
	- , ,	66-1066, 6601055,	
	•	66-1196, 66-1065	5 oa
15209978862	Helicopter, Util, UF-10	sv: 66-15081,	-
	•	66-15149.	2' ea
8340-5437787	Tont, GP, Modium	• • • •	5 oa
<i>5</i> 805 – 503 – 2775	Telephone set TA-43/PT		3 ea
5180323-4692	Tool Lit, Acit, Mech Gon	,	5 st
4933-994-9242	Tool Set, Acft, Arat, Supple	nent	1 st
4933-989-9816	Tool Set, Acft, Armt Rpmn Ba	sic	2 st
8470-926-1574	Body Armor AcftF & B plates		5 อล
73307218499	Container, thermal, 3 gal	,	3 ea
1005-2140934	Revolver Cal .38	SM: 953838	1 ea
8415-817-0598	Jacket, aviators		1 oa
8415-782-3037	Helmet APH-5		2 ea
1005-907-0720	Armament Sub-system M23		
	MG Mounts		
	3123 2676		
	4745 2713	•	

INcl 3

INCL 9

97

Dimiliand

-2-

THEMITIPENT.

1 00

3 02

1 08

1090-923-5671

7110-270-9840 7110-270-9838

7110-286-3796

5826-92607228

3340-262-2402

5820-892-0864

Armument Sub-systom H/C XM21

Radio Set AN/ASC-10

Tent Liner, GP Med Radio Set, AN/VRG-47, MTD #T TRK

			-	
Fylon # 1253 1253 1250 1250 1289	Bascol # 1379 1426 1429 1661 2325	<u>Fods</u> # 1702 1714 1747 1741		,
14.00	2737			
Dock, TYI	it ton, doub), pull-out,		. 60x34-30 ^½ 11	5 en
podiatal			60x34x30급#	1 ea
Filing Ca w/Lock	abinet, Cap	sz, 5 drs,		1 อก

/s/RUSSEL L. WENG JR. /t/RUSSEL L. WENG JR. WO1, GMC Supply Officer

A TRUE COTY

PAUL R. DAVIS CPT, INFANTRY

98

615TH TRANSPORTATION DEPACEMENT DAMACED EQUIPMENT

2320-542-4636 2320-055-9260 2320-077-1631 2320-077-1616	Truck, ego, 3/4 T 13781 Truck, tractor, 5T, N5A2 Truck, tank fuel, 257, Truck, ego, 24T, M35A2	113/4/2011 #A201 #A201	5F3139 4J2410 4J2314	1	02 02 03
2330-141-8050	Trailor, cgo, 14T, M1D5A2	Įr G A∦	4K2369 4 684617		69 69
8340-951-6419	Tent, frame, typo, maint		- 1401.		ea
5180-754-0641	Tool Kt, Auto Moch			4	ા
5180-323-4692	Tool Kt, Acft Mech, General	•		3	on
5180-323-4876	Tool Kt, Air Frame, Repairman	Army	Acft	3	98.
5180-323-4915	Tool Kt, Electrical Repairman			2	oa
71253300130	Cabinet, Tool & Spare Parts			2.	ca
1005-073-9421	Rifle, 5.56rm XM 6E1			7	οa
6625-553-0142	Multimotor			1	oa
61332226204	Charger Battery (Beatifier)	•		1	00.
4920-962-3097	Test Sot, Liquid quantity			1	oa
3439-585-6057	Soldering, gun			1	oa
3415-242-5789	Drill, Grindor			1	oa

/s/RUSSEL L. VENG JR.
/t/RUSSEL L. WENG JR.
WO1, DYC
Supply Officer

A TRUE COFY

PAUL R. DAVIS CPT, INFANTRY

99

INCL 9

107

CCNFIDENTIAL

DEPARTMENT OF THE ARMY
155TH ASSAULT HELICOPTER COMPANY
"FLYING DRAGONS"
APO 96297

27 January 1968

SWBJECT: Combat After Action Report (AVRA-G-1)

TO:

Commanding Officer 17th Combat Aviation Croup APO 96240

1. Following report is submitted 1st Aviation Brigade Regulation #335-1.

in accordance with

2. Map overlay showing location of rounds is inclosed with each copy.

2 Incl
1. Combat 4 Lar Action
Report

Report

2. Hap

Withdraw,,

Has, DA

/s/BILLY R. COODALL /t/BILLY R. COODALL Major, Infantry Commanding

100

INCI PA

C-O-W-F-J-D-E-W-T-J-A-J.

VC Attack on US Installations After Action Report (AUBA-G-1)

DEG:	170125 Jan 68			
Unit or Units:	155 AMC, 165 Trans, 185 MAC			
Strength of Units (2 above):	1pprox. 550 -	- 600		
Estimated number of Viet Cong:	Unknown	ndre district (mary per 1871 - 1871 (m.		
Location (6 digit coordinates):	17805042	n na nagasaka jepi naki nakin kiki. An naki kiki panaman kiki kiki kiki kiki majan kwe pindebesiki.		
Casualties:				
FRIENDLY VC	·			
MIA O O N/A				
Description of friendly losses of i.c. (CE, Gunner, etc.)	f personned by t	vne <u>N/A</u>		
		See attrched sheet .		
Estimate of weapons used by the	orc: 82mm mortar	to a responsibility of the contract of the con		
Gunships and other reinforcement	s used: 2 Flores	hips, 2 Guns, Spooky		
Estimated number of rounds fired	•			
60mm Mortar FRIENDL	<u>Y:</u> Y/A <u>VC</u> :	A\V		
81mm Mortar	52.	36		
4.2" Fortar	M/V	M/V		
Artillory	A/V	M\V		
Gunships	vi\v	$\pi \setminus V$		
Other	$\Lambda \backslash V$	A \V		
	Unit or Units: Strength of Units (2 above): Estimated number of Viet Cong: Location (6 digit coordinates): Casualties: FRIENDLY VC FIA 0 0 0 WIA 0 0 0 MIA 0 N/A Description of friendly losses or i.e. (CE, Gunner, etc.) Poscription of equipment losses, (Aircraft, Veapons by type, etc. Estimate of weapons used by the Gunships and other reinforcement. Estimated number of rounds fired 60mm Mortar Estimated number of rounds fired 60mm Mortar 4.2" Fortar Artillery Gunships	Unit or Units: Strength of Units (2 above): Estimated number of Viet Cong: Location (6 digit coordinates): MIA 0 0 0 MIA 0 0 0 MIA 0 N/A Description of friendly losses of personnel by trice. (CE, Gunner, etc.) Pescription of equinment losses, friendly or VC: (Aircraft, Weapons by type, etc.) Estimate of weapons used by the VC: Estimated number of rounds fired: 60mm Mortar FRIENDLY: V/A VC: 81mm Mortar 4.2" Nortar M/A Artillery M/A Gunships		

Annex A to 1st Aviation Brigade Rogulation 335-1 dtd 20 June 1967

Incl 1 to

INCL 9A

CONFIDENTIAL

131

Pil

CONFIDENTIAL

12.	Did the VC use satchel charges: VES NO XX
	How many? N/L What typo? N/A
	How employed? N/1.
13.	Distance at which action was initiated 3200 meters.
14.	What was the duration of the attack? 'pprox. 4 - 5 minutes
15.	Why was the engagement broken off?
	Installation defense was adequate YES
	Installation defense was inadequate NO
	VC stopped shooting and withdrew YES
	Other reasons (briefing explain) V/A
16.	Generally, what was the friendly reaction and behavior? (discuss)
	See Attached sheet
17.	Name of sonior 1st Aviation Brigade Officer present Naj Caldwell
18.	Unit having primary responsibility for defense of installation: 155
10.	Attach a scaled diagram indicating the following:
aftu	a. Sketch of friendly position prior to and deployment immediately r the initiation of the attack.
(i.e	b. Target location of suppressive and supporting fires by types ., Armed Felicopter, Artillery, etc.)
in f	c. Other information considered partitiont by reporting officer not ormat.

/s/RILLY R. GOOP WIJ.
/t/BILLY R. GOOP WIL
Major, Infantry
Commanding

102

CONFIDENTIAL

A.P. WOWI

8. A. Aircraft:

- 1. 155th AFC:
 - 4 TH-1H Light Damage
 - 1 UF-1H Moderate Damage
- 2. 185th RAC: Mone
- 3. 165th Trans: Vone
- 4. 92nd AHC (TDY):
 - 2 VH-1H Light Damage
 - 7 UH-1H Toxtensive Domago
- B. Buildings:
 - 1. 155th MC: Mone
- 2. 165th Trans: Extensive damage to maintenance office and orderly room.
 - 3. 185th R'C: None

16. Flareship and guaships airborne at approximately 0145 hours and remained aloft until approximately 0300 hours when releaved by Spooky aircraft. Mortar crews fired White Phospherous and Illumination rounds on preplanned concentrations from 0135 to 0230 hours with unknown results. All personnel manned bunkers and berm positions from 0130 until 0700 hours expending heavy small arms fire on Brown and suspected enemy positions until releaved by an ARVN reaction force outside of the commound. A state of readiness was maintained until 0700 hours, 17 January 1968.

103

CONFIDENTIAL

112060 34

DEPARTMENT OF THE AMY
155TH ASSAULT PELICOPTER COMPANY
"FLYING DRAGONS"
APO 96297

3 Fobruary 1968

SUBJECT: Combat After Action Report (AVBA-G-1)

TO:

Commanding Officer

93nd Combat Aviation Battalion

APO 96318.

1. Following after action report is submitted in accordance with 1st Aviation Brigade Regulation 335-1.

2. Nap overlays unavailable for enclosure at this time. Will forward as soon as possible.

/s/BILLY R. GOOD ILL
/t/BILLY R. GOOD ILL
Major, Infantry
Commanding

104

INCl 9 B

C-O-V-D-I-D-E-V-T-J-A-I,

VC Attack on US Installations \fter Action Report (AVB.L-C-1)

1.	DTG:	040245 Jan 68		
2.	Unit or Units:	155th AFC, 165 TD, 185th 9AC		
3.	Strength of Units (2 above):	<u> ^pnrox. 550 - 600</u>		
4.	Estimated number of Viet Cong:	T'nknown		
5.	Location (6 digit coordinates):	<u> 19805042</u>		
6.	Casualties:			
	Edlemnta ac			
	MIV O O MIV O O NIV O	,		
7.	Description of friendly losses of personnel by type N/A i.e. (CE, Gunner, etc.)			
8.	Description of equipment losses, friendly or VC: See attached sheet Aircraft, Weapons by type, etc.			
9.	Estimate of weapons used by VC: 82mm Mortar: R-40 Rockets			
10.	Gunships and other reinforcements used: 1 Flareship; 2 Gunships			
11.	Estimated number of rounds fired	:		
	60mm Mortar FRIENDLY	C: N/A VC:	M\v	
	81mm Mortor	68	40	
	4.2" Moratr	N/V	M\V	
	^rtillery	NV	A\V.	
	Gunships	N/V	$M \setminus V$	
	Other (B-40 Rockets)	V/V	6	

Annex A to 1st Aviation Brigade Regulation 335-1 dtd 20 Juno 1967

mor d

12.	Did the VC use satchel charges: XESNO
	How many? N/A That type? N/A
	How emplaced? N/A
13	Distance at which action was initiated 3200 meter.
14,	What was the duration of the attack? Spprox. 5 - 8 minutes
15.	Why was the engagement broken off?
	Installation defense was adequate YES
	Installation defense was inadequate NO
	VC stopped shooting and withdrew YES
	Other reasons (briefly explain) N/A
16.	Generally, what was the friendly reaction and behavior? (Discuss)
	Soc attached shoct
17.	Name of senior 1st Aviation Rde unit officer mesent Maj Caldwell
18.	Unit having primary responsibility for defense of installation 155
19.	Attach a scaled diagram indication the following:
nfte	a. Sketch of friendly position prior to and deployment immediately r initiation of attack.
(5. •0	b. Target location of suppressive and supporting fire by types Armed Holicopter, Artillary, etc.)
	e. Other information considered pertinent by reporting officer not

100

CONFIDENTIAL

INCK d

contained in format.

6. A. Aircraft

- (1) 155
 - 2 UH-1H, Destroyed
 - 3 WH-1H, Extensive Damage
 - 3 THECH, Modernte Damago
 - 4 WH-4H, Minor Damago
 - 2 UH-1H, (Dustoff) Minor Damage
- (2) 185
 - 9 01-G, linor Damago

h. Buildings

(1) 155

Maintenance Hangar, Extensive Damage COC & Officers Club, Minor Damage Fire Fouse, Minor Damage

 $(2) \cdot 165$

Maintenance Office, Extensive Damage Sheet Metal Shop, Extensive Damage

(3) 185

Motor park Tent, Extensive Damago

c. Vohicles

- (1) 155
 - 1 Fire Truck, Minor Damage
 - 2 1/4 Ton Jeops, Moderate to Extensive Damage
- (2) 185
 - 1 Fire Truck, Extensive Damage
 - 1 Fuel Truck, Extensive Damago
 - 1 24 Ton Truck, Light Damage
 - 2 5 Ton Trucks, Light Damogo
 - 6 Trailors, Light Damage
 - 1 Power lubricator, Extensive Damage

CONFIDENTIAL

MCr d

1/2

CONFIDENTIAL

16. One Flareship and 2 Gunships were airborne by 0250 to 0255 hours and remained aloft until approximately 0500 hours. Norther crows fired W.E. and W.P. rounds from 0250 until 0410 hours ("peroximately 68 rounds), on preplanned concentrations: Results unknown. "Ill personnel manned hunkers and berm positions from 0245 until 0500, expending heavy fire upon known and suspected enemy positions outside the compound: Negative results known at this time. Friendly casualties were non-existent. Maintained state of alort readiness until 0700 hours, 5 January 1968.

100

1200-7

121

CONFIDENTIAL

DEPARTMENT OF THE ARMY
155TH ASSAULT HELICOPTER COMPANY
"FLYING DRAGONS"
APO 96297

11 February 1968

SUBJECT: Combat Operations After Action Report (AVBA-G-1)

TO:

Commanding Officer 52d Combat Aviation Battalion APO 96318

- 1. Following is a narrative description of the mortar attack which occurred at Camp Coryell, RVN, on 30 January 1968.
- a. At 0250 hours, 30 January 1968, Camp Corvell came under a mortar attack. Approximately 20 rounds fell within the limits of the compound, the majority of which fell in the heliconter parking area.
- b. The compound had been put on 100% alert by Major Billy R. Goodall, Commanding Officer of the 155th Assault Pelicopter Company, et 0200 hours.
- c. At the time of the attack, one Thareship and two Gunships were airborne to give support to units in the Ban Me Thuet area. These ships gave continual support until daylight and were credited with the destruction of two mortar positions.
 - 2. Attached heroto as Annex I is a list showing eircraft damage.
- 3. Due to the number of rounds that have fallen during the period of these attacks it has been impossible to plot the location of each round.

/s/BILLY R. COODALL /t/BILLY R. COODALL Major, Infantry Commanding

INCI 90

VAMEX I

NIMBER	DVM.CE
66-16381	Moderate
66-16377	Moderato
66–16389	Moderate
64-16580	Moderate
66-16375	Light
6616441	Light

ANNEX I to INCL 9B,

 $\rho_{\prime\prime}$

CONFICENTIAL

DEPARTMENT OF THE ARRY
HEADQUARTERS, 52D COMBAT AVIATION BATTALION
APO Ser Francisco 96318
"FLYING DRAGONS"

AVGD-CZ

6 February 1958

SUBJECT:

Decapitulation of Availability, Mission Ready, EMP and EDM percentage taken from DA Form 1352 and daily aircraft status.

UH-1C	STD	NON	DEC	JAN
Availability	75	78.4	79.4	68.2
Mission Ready	80	58.1	54.6	54.8
EDM	17	15.1	15.8	. 16.4
EDP	8	.677	4,8	5.4
UH1 H	STD	ИОЛ	DEC	JAW
Availability	78	84.6	82 . 5	77.6
Mission Ready	80	72.4	68,2	60.8
EDM	17	13.6	14.3	16,6
EDP	5	1.7	3,2	5.9
UH-1 Combined	STO	VOV	DEC	JAN
Availability	80	81.5	81.0	72.9
Mission Ready	80	65,3	66.4	57.8
EUM	17	14.4	151	16.5
EDP	_5	4.2	4,00	5.7
CII-47	SID	NOV	DEC	ŭ.k.N
Availability	65	55.0	65.0	54.5
Mission Ready	50	43,2	43.0	39.5
EDM	23	29.0	23.0	34.5
EDP	12	16,0	12.0	11.0

MCF 10

CUNFIDENTIAL 52D BN CRASH FACTS INCIDENT & ACCIDENT EXTRACT

#	DATE/TIME	DAMAGE		UH-1 MODEL	TINU	SYNOPSIS
1.	081915Jun67	INCIDENT	\$6000.	D	170th	TOWER DIRECTED LOW-LEVEL - HIT WIRES
2.	101030Jun67	INCIDENT	\$1CO .	D	1stC	FUEL HOSE OVER SKID
3.	221510Jun67	MAJ OR	HEAVY	D	170th	REM DECAY LINDING - TIGHT LZ
4,	221545Juno7	MAJOR (2H)HEAVY	H¹s	189th	INTERLESHED ELADES - SHUT DOWN
5.	261130Jun67	MAJOR	NOT BAD	С	170th	LOST RPM (POWER RECOVERY AUTO- ROTATION)
6.	271645Jun67	INCIDENT	\$1500	H	189th	TREE STRIKE INTO CONFINED AREA
7,	011615Jv167	MAJOR .	LATOT	D	335th	TAIL ROTOR STRIKE
8.	071030Jul67	INCIDENT	\$400	Н	155th	ENGINE FAILURE-TAIL BOOM STRUCK PADDY DIKE
9.	121135Jul67	INCLDENT	\$6556	D	335th	
10.	191425Ju167	MJOR	TOTAL (1ix	nj)D	335th	
11	310945Jul67	MAJOR	TOTAL (3KIA_1WI	Н	189th	WX - INLOVERTANT IMC
12.	131630Aug6?	MAJ OR	HEAVY	H	335th	RPM DECAY-LANDING TIGHT LZ
13,	181545hug67	INCIDENT	\$4000	C	189th	AND O BOX COVER-TAIL & MAIN ROTOR
14.5	241600/.ug67	Major	TOTAL (6KIA-3WI	H	119th	CRASHED INTO WATER (FCOLISHNESS)
15.	251320/ug67	INCIDENT		Н	189th	ENGINE FAILURE-STRUCK BRUSH
16.	020055Sep67	MAJOR	TOTAL (2KIA-4WL	H	119th	NICHT WX-INADVERTANT IMC
17.	031130Sep67	MAJ CR	NOT BAD	Ć	189th	ENGINE FAILURE-SOFT EARTH
	041500Sep67	MiJOR	TOT/L(2i:	nj)H	170th	MMO BOX COVER-TAIL ROTOR OFF
19.	211930Sep67	MAJOR	TOTAL (4W)	IÀ)H	189th	TAIL ROTOR FAILURE-AUTOROTATION TO TREES
20.	291100Sep67	INCLIENT	\$2721	H	170th	TAIL ROTOR STRIKE (DIRT MOUND)
	0510200ct67	INCIDENT		H	189th	TREE STRIKE
22.	0613500ct67	Maj or	TOTAL (1WIA)	C	119th	RPM DECAY T/O RWY (4th ATTEMPT)
23.	1410500ct67	Mi.JOR	NOT BAD	H	170th	REVETMENT STRIKE (TEST FLIGHT)
	1915450ct67		TOTAL	H	155th	
25.	2215200ct67	MADOR	TOTAL	H	170th	FIRE IN AVIONICS COAPARTMENT
_			(1 SMOKE	•		
26.	, 2209200ct67	MAJ OR	TOTAL (4KIA)	H	170th	TAIL ROTOR STRIKE-LOW LEVEL
27.	2617L30nt67	MAJOR	TOTAL	C	170th	THIL ROTOR FAILURE (IP GOOD SAVE)
	3018480ct67	INCIDENT	\$1000	D	281 st	
	. 071600Nov67		TOT/L (AIWS)	Н	375th	DECLYED RPM TAKE OFF
30.	. 171730Nov67	INCIDENT		H (v)	57th	BLADE STRIKE ARVN HEAD W/HELMET
31.	. 220930Mov67	MAJOR	TOT/L (1 LIGHT	H	170th	ENGINE FAILURE (5001) AUTORO- TATED INTO TREES
32.	231045Nov67	INCIDIAN		н_	170th	

INCL W

121

CONFICENTIAL

33. 251340Mov67	M.JOR	HE(VY (2VIV.)	Н	155th	N1 SHAFT FAILURE-LOW AUTO-
34. 261600Nov67	INCIDENT	\$4,000	H	155th	TAIL ROTOR STRIKE IN TIGHT LZ
35. 271515Nov67	INCIDENT	\$5000	H .	57th	RPM DECLY-TAKE OFF HIT MOUND
36. 281240Nov57	MIJOR	TOTIL	H	189th	BIJDE STRIKE LANDING TIGHT LZ
37. 061730Dec67	MAJOR	TOTAL	H	170th	RPM DECAY LINDING TIGHT LZ
38. 101735Dec67	MAJOR	NOT BAD	H	155th	TEST FLIGHT ENGINE FAILURE
	((1KIA ARVN-	SMIV)		
39。161545Dec67	MLJ OR	TOTIL	Н	170th	RPM DECLY TAKE OFF PINACLE
	(2	eria-6wia)		•	
40, 201600Dec67	MAJOR	TOTAL.	H	189th	TREE STRIKE (200' HOVER)
	(L_i)	KIA ZWIA)			EQUIPMENT DROP
41 · 211300Dec67	MAJOR	TOTAL (2HEL)H	189th	INTERMESHING ROTOR CONGESTED
	(1	KIA-IWIA)			LANDING FIELD

MOTES: !. Normal Flying Day 0700 to 1900 (12 Hours)

- 2. %4! Considered events: 22 (51%) occurred after 1500 hours (Lest 25% of day)
- 3. *27 Major Accident: 17 (67%) occurred after 1500 hours (Last 25% of day)
- 4. Two peak periods: 1030-1330, 1500-1800 (Worst) for 11 41 events
- 5. No accidents, incidents, forced landings or precautionary landings from 0700-0920 every one on file considered (approx 75) Practically all the aircraft fly during this period.

*Some from other units, but reported through this Hqs.

CONFIDENTIAL

11

PRIORITY IMEDL. TE

CO, 52D CBT AVN BN, PIETKU, RVN

USABAAR, FT RUCKER, ALA INFO: USAAMC, ST LOUIS, MO CG, USAEV, LONG BINH, RVN CG, 1ST AVN BDE, LONG BINH, RVN CO, 34TH CEN SPT CP, SAIGON, RVN CO, 17TH CBT AVN GP, NHT, RVN

UNCLAS AVGD-CFS 8003-20

SUBJECT: PROBLEMS, AIR FITTER, SAND AND DUST SEPARATOR.

- 1. FIELD EXPERIENCE HAS SHOWN THAT SEVERAL RELATED PROBLEMS EXIST IN ACTURE THE AIR FILTER, SAND AND DUST SEPARATOR (MANUFACTURERS P/RM NO. 1-010-500-05 AND 1-010-500-06) INCORPORATED WITH THE T-53-L13 INSTALLATION.
- 2. TIME DOES NOT PERMIT A THOROUGH REVIEW OF RECORDS TO REVEAL ACCURATE STATISTICS. SUFFICIENT EXPERIENCE CLEARLY POINTS TO TRENDS THAT WARRANT IMEDIATE ACTION. ANY SAPIE SURVEY WILL REVEAL THE VALIDITY OF THESE TRENDS.
- 3. A. FIRST: THE INCIDENCE OF FOD DUE TO INCESTION OF SMALL AND LARGE OBJECTS HAS RISEN TO AN ALABATING RATE. AN OVERSIGHT MUST HAVE EXISTED WHEN THE FILTER WAS DESIGNED.
- B. REASONS CAN BE FOUND FOR THE INCREASED ALOUNT OF FOREIGN OBJECTS INGESTED FROM THE PLENUM CHAMBER AREA:
- (1) INCREASED WIGHT MAINTENANCE DUE TO INCREASED AISSION SUPPORT.
 - REDUCED MAINTENANCE MANPOWER, ESPECIALTY SUPERVISORS.
- (3) INCREASED USE OF PENEPRIME (ASPHALT) CAUSING OBJECTS TO ADHELE TO THE BOOTS.
 - (4) REDUCED MECHANIC EXPERIENCE.
 (5) CHEW FATIGUE

EMPHASIS TO REDUCE THE ABOVE CAUSES CAN MAKE SOME REDUCTION IN FOD, BUT THE SIMPLEST AND MOST EFFECTIVE SOLUTION IS TO EFFECT AN IMPEDIATE ENGINEERING FIX.

1968 JVN

1100

03

HOL 176/216

DANNY L. LINDBURG, SP4, DRAFTER

DAVID L. BOIVIN, MAJ, INF, AAPO

INCL 12

- C. THE INCIDENCE OF FOD ASSOCIATED WITH THE T-53-L13 IS DISPROPORTIONATE TO THE T-53-L11, WHICH HAD THE SQUIRREL CAGE THAT STOPPED MOST FOD. IT IS EVIDENT THAT THE NEW SYSTEM IS NOT AS EFFECTIVE IN FOD PREVENTION. THIS SYSTEM DOES NOT INCORPOR-ATE A LAST CHANCE FILTER WHICH WILL PREVENT FOD. A FIX IS POS-SIBLE IN MINIMUM TIME AND COST. THE COST OF DAMAGED ENGINES AND AIRCRAFT AND ASSOCIATED LOSS OF LIFE WILL FAR OUTWEIGH ANY COSTS TO EXPEDIATE THIS SIMPLE ITEM. UNTIL A PERMANENT FIX CAN BE DEVELOPED AND PRODUCED, A NYLON MESH SCREEN MAY PROVE SATISFACTORY. SUCH MATERIAL WAS USED IN 1964 TO PREVENT HAY INGESTION DURING DEVELOPMENT OF THE BARRIER FILTER. SEVERAL SOLUTIONS ARE POSSIBLE. A SCREEN BETWEEN THE SAND AND DUST SEPARATOR AND THE ENGINE AIR-INTAKE IS RECOMMENDED. THUS THE ADDED SCREEN WOULD FILTER PRIMARILY FOD. ITS OPERATION IN RELATIVELY CLEAN AIR WOULD AVOID CLOGGING FOR A LONGER TIME, AND MAKE FOR SAFER OPERATION AND LESS REQUIRED MAINTENANCE. THE SAND AND DUST SEPARATOR IS A ACCOMPLISHING THE PURPOSE FOR WHICH IT WAS DESIGNED. BUT, OF THE TWO PROBLEMS, FOD IS THE MOST SERIOUS SINCE THE FAILURE IS OFTEN CATASTROPHIC AND WITHOUT WARNING.
- A. SECOND: CLEANING OF THE ENGINE COMPRESSOR ASSEMBLY AND STATORS (A FREQUENT NECESSITY IN THIS ENVIRONMENT) IS HAMPERED BY THE LOWER HALF OF THE SAND DUST SEPARATOR. TO REMOVE THIS SECTION, THE SHORT SHAFT (FSN 1560-862-3819) MUST BE REMOVED. DUE TO DEMANDS UPON MAINTENANCE PERSONNEL OFTEN THIS TIME CONSUM-ING PROCEDURE IS BY-PASSED. WHEN THE LOWER HALF IS PRESENT DURING CLEANING, THIS RESULTS IN CLEANING OF THE ROTATIONAL COMPRESSOR BLADES BUT ONLY THE UPPER HALF OF THE FIXED STATION BLADES. THIS METHOD CAUSES A VARIATION OF COMPRESSOR AIRFLOW THAT CREATES COMPLETE LOADING OF THE BLADES PASSING THROUGH THE UPPER HALF AND SOME UNLOADING IN THE LOWER HALF. THE RESULTANT FLUTTER AND VI-BRATION OF THE BLADES CAN CAUSE FATIGUE FAILURE. YET, THE MOST IMMEDIATE AND DIRECT RESULT OF THE DISRUPTED FLOW PATTERN IS HIGH EGT AND LOW POWER OUT-PUT. THIS CONDITION CAN BE TRANSIENT AND VARIATIONS DO EXIST AS TO EGT AND POWER OUT-PUT, DUE TO THE RANDOM EFFECTIVENESS OF THE CLEANING METHOD. LOW POWER OUT-PUT IS NOT ALWAYS ACCOMPANIED BY HIGH EGT; IS INSIDIOUS AND MAY BE TRANSIENT.
- B. THE SOLUTION IS REVAMPING OF THE LOWER HALF OF THE PARTICLE SEPARATOR FOR EASY REMOVAL. VISUAL INSPECTION IS NOT POSSIBLE (EVEN WITH A MIRROR) OF THE OPEN INLET AIR SECTIONS AT THE BOTTOM HALF OF THE SEPARATOR. THIS IS THE AREA THAT IS DIRTIEST AND SUSPECT OF THE MAJORITY OF FOD INGESTION. ELIMINATION OF THE FIVE RETAINING BOLTS IN THE LOWER HALF MAY BE ELIMINATED BY INCORPORATING ANOTHER (QUICK DISCONNECT) V-BAND COUPLING AROUND THE MOUNTING RING ASSEMBLY. IT MAY BE POSSIBLE TO FORM AN ADEQUATE LIP (TO HOLD THE V-BAND) ON THE COMPONENTS NOW IN USE.

AAPO

5. THESE TWO FACTORS CAN BE DIRECTLY RELATED TO THE PROBLEMS ASSOCIATED WITH THE HIGH USAGE OF T-53-L13 ENGINES IN THIS COMMAND. THESE FACTORS ARE ALSO RELATED DIRECTLY AND INDIRECTLY TO ACCIDENT CAUSES. EMPHASIS ON THESE TWO FACTORS WILL SIGNIFICANTLY REDUCE ENGINE USAGE. THIS ENGINE WOULD BE FAR MORE RELIABLE THAN IS INDICATED BY THE HIGH USAGE AND SHORT LIFE EXPERIENCED IN THIS COMMAND DURING THE PAST SIX MONTHS.

116

Security Classification	· /:
	ROL DATA - R & D
(Security classification of title, body of abstract and indexing a DRIGINATING ACTIVITY (Corporate author)	annotation must be entered when the overall separt is classified)
OACSFOR, DA, Washington, D.C. 20310	Confidential
	28. GROOP
	4 '
REPORT TITLE	
perational Report - Lessons Learned, Hqs,	52d Combat Aviation Battalion (U)
DESCRIPTIVE NOTES (Type of report and inclusive dates)	
Experiences of unit engaged in countering AUTHORIS (First name, middle initial, lest name)	urgency operations, 1 Nov 6/-31 Jan 1968
AU 1 HORts (Filet name, middle miliet, test mans)	/
CO, 52d Combat Aviation Battalion	· ·
REPORT DATE	78. TOTAL NO. OF PAGES 75. NO. OF REFS
	11/2
6 February 1968	98. ORIGINATOR'S REPORT NUMBER(S)
· · · · · · · · · · · · · · · · · · ·	681156
PROJECY NO.	, / 001130
N/A	9b. OTHER REPORT NO(2) (Any other numbers that may be assigned
	(lula topoti)
DISTRIBUTION STATEMENT	
י או אייני א	
	•
• •	•
GLEBRI CAPTIVANO MANAGEM	12. SPONSORING MILITARY ACTIVITY
SUPPLEMENTARY HOTES	IN SECURIORIST MISSION OF STATE
N/A	OACSFOR, DA, Washington, D.C. 20310
ABSTRACT	•
•	
1	
	•
•	
•	•
•	
	•
•	•
	•
·	
~	17
7	·
	\.
	\

UNCLASSIFIED